

LKK Auto Consultants Pte Ltd

(Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CC4/AIG20004729/KGA3Q2

Date: 12/01/2021

REFERENCE

Handling Insurer: AIG Asia Pacific Insurance Pte. Ltd. Policy No: 0999994248

Claimant Vehicle No : SLK2376C **Insured Vehicle No :** SJW9285X

Date of Loss: 27/10/2019 Nature of Claim: TP Claim No: 1858017815SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SLK2376C	Engine No:	2ZRR980616
Make & Model:	TOYOTA PRIUS HYBRID, 1.8 CVT (A)	Chassis No:	JTDKB3FU103540633
Reg. Date:	10/01/2017 (Man. Year: 2016)	Odometer:	237979 km
Colour:	Metallic Silver		
Engine Capacity:	1798 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	195/65 R15	Rear Tyre Size:	195/65 R15
Front Left Side:	Yokohama 9 mm	Rear Left Side:	Yokohama 9 mm
Front Right Side:	Yokohama 9 mm	Rear Right Side:	Yokohama 9 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	1,597.97	1,030.61	567.36	35.51
Miscellaneous Items	0.00	0.00	0.00	
Labour	594.00	424.00	170.00	28.62
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Gross Total (S\$)	2,191.97	1,454.61	737.36	33.64
+ GST 7.00/7.00% (S\$)	153.44	101.82	51.62	33.64
Nett Amount (S\$)	2,345.41	1,556.43	788.98	33.64
+ Car Rental (2.0 x S\$83.00/day) (S\$)		166.00		
+ Doc/Search Fee (S\$)		7.45		
Nett Liability (S\$)		1,729.88		

INSPECTION

Date of Assignment: 31/03/2020

Date Inspected: 01/04/2020 Inspected At: Esteem Performance Pte Ltd (HQ)
Blk 5033 Ang Mo Kio Ind Park 2, #01-259
Singapore 569536

Estimated Period of Repair: 2.0 days

Adjuster: KENNETH KONG

Manager: Chong Pui Lin

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*L/R BUMPER CORNER	Serviceable	149.70 FL	*- FL
2	1		*LEFT RETAINER	Serviceable	112.70 FL	*- FL
3	1		*R/R BUMPER CORNER	Serviceable	149.70 FL	*- FL
4	1		*REAR BUMPER	Buckled	450.80 FL	*450.80 FL
5	1		*REAR BUMPER REINF	Bent	398.90 FL	*398.90 FL
6	1		*REAR COVER BUMPER	Dented	582.60 FL	*582.60 FL
7	1		*RIGHT RETAINER	Serviceable	112.70 FL	*- FL
8	1		*RR BMP CLIP	Necessary	40.00 FL	*40.00 FL
9	1		*REVERSE SENSOR	Serviceable	200.00 FS	*- FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (\$\$)	2,197.10	1,472.30
- List Item Discount on L Items 30.00/30.00% (\$\$)	599.13	441.69
Total Parts (\$\$)	1,597.97	1,030.61

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<u>Labour Items</u>				
1	REVERSE SENSOR TO R&R	New	120.00	50.00
2	TO TUFF COAT TO TUFF COAT	New	100.00	0.00
3	13.0 WU X50.00 SGD/H	New	65.00	65.00
4	LABOUR COST 44.0 WU X50.00 SGD/H	New	220.00	220.00
5	MATERIAL COST	New	89.00	89.00
Gross Labour Cost (\$\$)			594.00	424.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >