

22/03/2021

ASS. REC. RV:

Surveyor: Adrian

REF: CS/MS920004733/AGND3

Special Instruction:

ASSIGNMENT (Office)

From (Person): Crystallee of MSIG Date/Time: 3/3/2020 @ 3:41pm

Estimated Cost: _____ Bill to: _____

OD/TP/WS/TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No: SKJ 7179P Insured: SFQ 9399E

at Workshop m/s Advance Auto Garage Tel: 9007 9247

of 23 Keiki Bukit Ave 4 # 04-01

Policy No: _____ Claim No: _____

Sum Insured: _____ Excess: _____

Make of Veh: _____ D.O.A. 27/03/2020
(Client's Record)

CA / REV / REP. / REV 24 HRS (up) H.O.D. Endorsement: _____

Date/Time: 3:45pm @ 3/3/2020 Person Contacted: Xavier Vehicle IN / OUT

Date/Time	Action/Instruction	Estimate	Remarks
	SKJ 7179P - NS/INCISCO8169 / Sq bn 2		Don: 29/03/2021
	SFQ 9399E - X		
<u>1/4/20</u>	Informed Crystal pending for workshop est by email		
<u>15/4/20</u>	Adrian confirmed LS \$5800 (Red 6364 To, 5290)		

ASS. REC. BY:

REF:

ASSIGNMENT

From: _____ Date: _____
 Estimated Cost: _____
OD / TP / WS / TP RES / OD RES / EVA / INV / MV
 To Inspect Vehicle No: _____
 at Workshop m/s _____
 of _____
 Insured: _____
 Policy No. _____
 Claims No. _____
 Sum Insured: _____ Excess: _____
 (Client's Record)
 Make of Veh: _____

N/S	O/S

(Policy Condition)
 Remark: **The veh had commenced its repair at the time of inspection.**

Bal. or Market Value: _____
 IDAC Accident Rport: _____ Consistent? : **Yes** or No
 GIA / PR Seen: _____ Consistent? : **Yes** or No
 Est. Repairs: _____ days Res.: **Yes** or No
 Lum Sum: _____ % 3 Val.: **Yes** or No
 CA / REV / REP. / 24 HRS
 Date: _____ Person Contacted: _____ Vehicle: **IN / OUT**

Veh No: **SKJ 7179P** Yr Regn: **2008 / Oct**
 Type: **M.Car** / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /
 Truck / Trailer or _____
 Make: **Toyota Uias** - c.c. **1497**
 Colour: **Black** A/C: **Insured / Std / NI / NA**
 Sp. Reading: **269028** T/Radio: **Insured / Std / NI / NA**
 Eng/No: _____
 C/No: **MROS34Y930S084730**
 Gen. Cond: **Good** / Fair / Poor / Burnt
 Steering: **In order** / Jammed / Leaked / Burnt or _____
 Brake: **In order** / Jammed / Leaked / Burnt or _____
 Modi: **Nil / S/Rim** / STD A/Rim or _____
 Tyre Size: F: **195/55R15**
 R: **195/55R15**
 BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /
 TOYO / YOKO or **Radar**.
 Front _____ Rear _____
 R/Bal. **06** mm R/Bal. **06** mm
 L/Bal. **06** mm L/Bal. **06** mm
 D.O.A. _____ D.O.I. **31/03/20**
 Survey held at **Advance**.
 Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or
Rear x/s.
 The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time	Action / Instruction
	TP MS16.
	COE Expiry: 23/10/23.
	MV: 201K
	PV: 10.8K
	Nett: 9.21K

Date/Time, File Pass to? : **Prefi. Report**
 : **Final Report**
 1) _____
 Date/Time, File Return to? _____
 2) **15/4 -typist**
 Report Format: **Merimen**
 Lump Sum / L.B.I: **5800/p**

Days Of Repair: **10**
 Resurvey No. of Trip: **1**

Add Fee: : Site Insp (\$) _____
 : Interview (\$) _____
 : Tech. Invs (\$) _____
 : Weekend (\$) _____

Survey Fee: _____
 Transportation: _____ \$ + P.S. _____ \$
 Photos _____
 Others _____
 TOTAL _____

TPMS16. SKJ7179P.
 Veron Toyota Vios
 MR053HY9305084730

Rear Bumper	Distorted	459.50 ✓
Rear Bumper Clips	nn	30 ✓
Rear Bumper Side Holder x 02	RH Paint	75.5 x 2 = 151 75.50
Rear Bumper Reflector RH.	crushed	90.30 ✓
Rear Bumper Reverse Sensor	Damaged	280(SN) 200(SN)
Rear End Panel	Distorted	596.40 ✓
Rear End Panel Top Garnish	distorted	def 230.80 ✓
Rear End Panel Bracket RH.	distorted	BT 85.60 ✓
Rear End Panel Sealant.	nn	60(SN) ✓
Taillamp RH.	Smashed	299.50 ✓
Taillamp Panel RH.	DIST	115 ✓
Bootlid	Buckled	565.10 ✓
Bootlid lock	nn	100.70 x
Bootlid Weatherstripe	cut	194.50 ✓
Bootlid Hinge x 02	nn	68.6 x 2 = 137.20 x
Toyota Logo		27.50 ✓
Vios Wordmark	nn	30.90 ✓
E Emblem.		30.20 ✓

SKJ7179P.

Rees RH Fenders	Distorted	790.70 ✓
Rees RH ^{Fender} Inner Trim	crumpled	225 ✓
Rees RH ^{Fender} Inner Trim Clips	all	30 ✓
Rees RH Fender Inner Shield.	Missing	68.90 ✓
Rees RH Fender Inner Shield Clips.	all	20 ✓
Rees RH Fender Wheel House.	R	561.60. ✓
Rees Windscreen Moulding.	?	120.50 ✓
Rees Windscreen Sealant.	all	60(SN) ✓
Rees RH Tyre.	all	220(SN) ✗
Spere Tyre Panel	R	871.40 ✓
Spere Tyre Panel Top Board	toin toin	190.30 ✓
Spere Tyre Panel Side Board.	toin toin	59 ✓
Spere Tyre Panel Side Sponge RH.	Distorted	220 ✓
Spere Tyre Panel Centre Sponge.	all	210.30 ✓
Rees Exhaust Pipe.	NN	569. ✓
Rees Exhaust Mounting.		30.90. ✗
Spere Tyre Side Panel RH.	Distorted DIST	102.90 ✓

SKJ7179P

Panel Beating	1800 1500
Spray Painting.	1600 1300
Wiring.	50 30
To underseal.	150 120
To remove reverse sensor	100 50
To remove upholstery.	150 80
To remove rear windscreen.	180 120
To remove exhaust pipe.	150 X
To transfer bootlid fittings.	150 80

12,164.70

hist 4868.40

labour 3280

land 3651.30

total 7251.30

S.N 320

1/2 5.8K.

10 Days.

(5.8K)

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed **and** is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature:
Date: