

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS/MSG20004733/AGVD3E2

Date: 20/04/2020

REFERENCE

Handling Insurer: MSIG Insurance (Singapore) Pte. Ltd.

Policy No: 28924018QMY

Claimant Vehicle No : SKJ7179P

Insured Vehicle No : SFQ9399E

Date of Loss: 27/03/2020

Nature of Claim: TP

Claim No: 622678

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: **SKJ7179P**

Make & Model: TOYOTA VIOS EA, 1.5 (A)

Engine No: 1NZX815415

Reg. Date: 24/10/2008 (Man. Year: 2008)

Chassis No: MR053HY9305084730

Colour: Black

Odometer: 269028 km

Engine Capacity: 1497 cc

Market Value/New Car Price: N/A

Sum Insured (S\$): **Market Value/New Car Price**

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes

Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition: Yes

CONDITION OF TYRES

Front Tyre Size: 195/55 R15

Rear Tyre Size: 195/55 R15

Front Left Side: RADAR 6 mm

Rear Left Side: RADAR 6 mm

Front Right Side: RADAR 6 mm

Rear Right Side: RADAR 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	7,834.70	3,971.30	3,863.40	49.31
Miscellaneous Items	0.00	0.00	0.00	
Labour	4,330.00	3,280.00	1,050.00	24.25
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	12,164.70	7,251.30	4,913.40	40.39
Approved Total (Overridden) (S\$)		5,800.00		
Nett Amount (S\$)	12,164.70	5,800.00	6,364.70	52.32

INSPECTION

Date of Assignment: 15/04/2020

Date Inspected: 31/03/2020 Inspected At:

Polymath Garage Pte Ltd - Kaki Bukit (HQ)
23 KAKI BUKIT AVENUE 4 #04-01 AAS
KAKI BUKIT CENTRE
SINGAPORE 415933

Estimated Period of Repair: 10.0 days

Adjuster: XING GUO QIANG

Manager: VERON CHEN

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference

Part Source: MRM-SG	Version: 1.0 (Last Synchronised: 20 Apr 2020)
Parts: 143	TOYOTA VIOS EA 1.5 (A) (Catalogue:Merimen Singapore 1.0)
Labour: Repairer's	(Price-denominated Standard List)
Print Code: (Unsubmitted, no print-code for SKJ7179P)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*REAR BUMPER	Distorted	459.50 F	*459.50 FL
2	1		*REAR BUMPER CLIPS	Necessary	30.00 F	*30.00 FL
3	1		*REAR BUMPER SIDE HOLDER	O/S Damaged	151.00 F	*75.50 FL
4	1		*REAR BUMPER REFLECTOR RH	Cracked	90.30 F	*90.30 FL
5	1		*REVERSE SENSOR	Damaged	280.00 FS	*200.00 FS
6	1		*REAR END PANEL	Distorted	596.40 F	*596.40 FL
7	1		*REAR END PANEL TOP GARNISH	Deformed	230.80 F	*230.80 FL
8	1		*REAR END PANEL BRACKET RH	Bent	85.60 F	*85.60 FL
9	1		*REAR END PANEL SEALANT	Necessary	60.00 FS	*60.00 FS
10	1		*TAILLAMP RH	Smashed	299.50 F	*299.50 FL
11	1		*TAILLAMP PANEL RH	Distorted	115.00 F	*115.00 FL
12	1		*BOOTLID	Buckled	565.10 F	*565.10 FL
13	1		*BOOTLID LOCK	Not Necessary	100.70 F	*- FL
14	1		*BOOTLID WEATHERSTRIPE	Cut	194.50 F	*194.50 FL
15	2		*BOOTLID HINGE	Not Necessary	137.20 F	*- FL
16	1		*TOYOTA LOGO	Necessary	27.50 F	*27.50 FL
17	1		*VIOS WORDING	Necessary	30.90 F	*30.90 FL
18	1		*E EMBLEM	Necessary	30.20 F	*30.20 FL
19	1		*REAR RH FENDER	Distorted	790.70 F	*790.70 FL
20	1		*REAR RH FENDER INNER TRIM	Crumpled	225.00 F	*225.00 FL
21	1		*REAR RH FENDER INNER TRIM CLIPS	Necessary	30.00 F	*30.00 FL
22	1		*REAR RH FENDER INNER SHIELD	Missing	68.90 F	*68.90 FL
23	1		*REAR RH FENDER INNER SHIELD CLIPS	Necessary	20.00 F	*20.00 FL
24	1		*REAR RH FENDER WHEEL HOUSE	Repair	561.60 F	*- FL
25	1		*REAR WINDSCREEN MOULDING	Necessary	120.50 F	*120.50 FL
26	1		*REAR WINDSCREEN SEALANT	Necessary	60.00 FS	*60.00 FS
27	1		*REAR RH TYRE	Not Necessary	220.00 FS	*- FS
28	1		*SPARE TYRE PANEL	Repair	871.40 F	*- FL
29	1		*SPARE TYRE PANEL TOP BOARD	Torn	190.30 F	*190.30 FL
30	1		*SPARE TYRE PANEL SIDE SPONGE RH	Distorted	220.00 F	*220.00 FL
31	1		*SPARE TYRE PANEL CENTRE SPONGE	Cracked	210.30 F	*210.30 FL
32	1		*REAR EXHAUST PIPE	Not Necessary	569.00 F	*- FL
33	1		*REAR EXHAUST MOUNTING	Not Necessary	30.90 F	*- FL
34	1		*SPARE TYRE SIDE PANEL RH	Distorted	102.90 F	*102.90 FL
35	1		*SPARE TYRE PANEL SIDE BOARD	Torn	59.00 F	*59.00 FL

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (\$\$)	7,834.70	5,188.40
- List Item Discount on L Items 0.00/25.00% (\$\$)	0.00	1,217.10
Total Parts (\$\$)	7,834.70	3,971.30

Report was unsubmitted during this print-out.

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
Report was unsubmitted during this print-out.						

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	PANEL BEATING	New	1,800.00	1,500.00
2	SPRAY PAINTING	New	1,600.00	1,300.00
3	WIRING	New	50.00	30.00
4	TO UNDERSEAL	New	150.00	120.00
5	TO REMOVE REVERSE SENSOR	New	100.00	50.00
6	TO REMOVE UPHOLSTERY	New	150.00	80.00
7	TO REMOVE REAR WINDSCREEN	New	180.00	120.00
8	TO REMOVE EXHAUST PIPE	New	150.00	0.00
9	TO TRANSFER BOOTLID FITTINGS	New	150.00	80.00
			Gross Labour Cost (S\$)	3,280.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >