

TPMS16.

SKJ7179P.

Veron

Toyota Vios

MR053H49305084730

Rear Bumper	Distorted	459.50 ✓
Rear Bumper Clips	MR	30 ✓
Rear Bumper Side Holder x 02	RH Punch	75.5 x 2 = 151 75.50
Rear Bumper Reflector RH.	could	90.30 ✓
Rear Bumper Reverse Sensor	Damaged	280(SN) 200(SN)
Rear End Panel	Distorted	596.40 ✓
Rear End Panel Top Garnish	Rehd	230.80 ✓
Rear End Panel Bracket RH.	Best	85.60 ✓
Rear End Panel Sealant.	MR	60(SN) ✓
Taillamp RH.	smashed	299.50 ✓
Taillamp Panel RH.	Distorted	115 ✓
Bootlid	MR	565.10 ✓
Bootlid lock	MR	100.70 x
Bootlid weatherstripe	MR	194.50 ✓
Bootlid hinge x 02	MR	68.6 x 2 = 137.20 x
Toyota Logo	?	27.50 ✓
Vios Wording	MR	30.90 ✓
E Emblem.		30.20 ✓

SKJ7179P.

Rees RH Fenders	Distorted	790.70 ✓
Rees RH ^{Fender} Inner Trim	crumpled	225 ✓
Rees RH ^{Fender} Inner Trim Clips.	all	30 ✓
Rees RH Fender Inner Shield.	Missing	68.90 ✓
Rees RH Fender Inner Shield Clips.	all	20 ✓
Rees RH Fender Wheel House.	Repair	561.60. ✗
Rees Windscreen Moulding.	3 new	120.50 ✓
Rees Windscreen Sealant.		60(SN) ✓
Rees RH Tyre.	all new	220(SN) ✗
Spere Tyre Panel	Repair	871.40 ✗
Spere Tyre Panel Top Board	to re	190.30 ✓
Spere Tyre Panel Side Board.	to re	59 ✓
Spere Tyre Panel Side Sponge RH.	Distorted	220 ✓
Spere Tyre Panel Centre Sponge.	crumpled	210.30 ✓
Rees Exhaust Pipe.	3 new	569. ✗
Rees Exhaust Mounting.	all new	30.90. ✗
Spere Tyre Side Panel RH.	Distorted	102.90 ✓

SKJ7179P

Panel Beating	1800	1500
Spray Painting.	1600	1300
Wiring.	50	30
To underseal.	150	120
To remove reverse sensor	100	50
To remove upholstery.	150	80
To remove rear windscreen.	180	120
To remove exhaust pipe.	150	X
To transfer bootlid fittings.	150	80

hist 4868.40

Land% 3651.30

S.N. 320

labour 3280

total: 7251.30

h/s: 5.8K.

10 Days.

5.8K

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature:
Date: