

## LKK Auto Consultants Pte Ltd

(Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

## VEHICLE DAMAGE INSPECTION REPORT

**Our File No:** CC4/AIG20004734/UEA3Q2

**Date:** 04/02/2021

### REFERENCE

Handling Insurer: AIG Asia Pacific Insurance Pte. Ltd. Policy No: 2100425838

**Claimant**  
**Vehicle No :** SKD3504S **Insured Vehicle No :** GBE725S

Date of Loss: 28/03/2020 Nature of Claim: TP Claim No: 7887541826SG

### DESCRIPTION & IDENTIFICATION OF VEHICLE

|                             |                                   |             |                   |
|-----------------------------|-----------------------------------|-------------|-------------------|
| Reg No:                     | <b>SKD3504S</b>                   |             |                   |
| Make & Model:               | MERCEDES-BENZ E250, 1.8 CGI (A)   | Engine No:  | 27186030047499    |
| Reg. Date:                  | 15/06/2010 (Man. Year: 2010)      | Chassis No: | WDD2073472F041215 |
| Colour:                     | Grey                              | Odometer:   | 147609 km         |
| Engine Capacity:            | 1796 cc                           |             |                   |
| Market Value/New Car Price: | N/A                               |             |                   |
| Sum Insured (\$\$):         | <b>Market Value/New Car Price</b> |             |                   |

### CONDITION OF VEHICLE AT THE TIME OF SURVEY

|                          |                         |                      |                          |                         |
|--------------------------|-------------------------|----------------------|--------------------------|-------------------------|
| General Condition:       | Steering (Serviceable): | Yes                  | Footbrake (Serviceable): | Yes                     |
| Handbrake (Serviceable): | Yes                     | Engine Modification: | No                       | Pre-accident Condition: |

### CONDITION OF TYRES

|                   |                  |                  |                  |
|-------------------|------------------|------------------|------------------|
| Front Tyre Size:  | 245/40 R18       | Rear Tyre Size:  | 265/35 R18       |
| Front Left Side:  | Continental 6 mm | Rear Left Side:  | Continental 6 mm |
| Front Right Side: | Continental 6 mm | Rear Right Side: | Continental 6 mm |

*The above values represent the remaining tyre treads depth*

| <b>COST OF CLAIMS</b>                             | <b>Repairer's</b> | <b>Adjuster's</b> | <b>Difference</b> | <b>Diff %</b> |
|---|-------------------|-------------------|-------------------|---------------|
| Parts   | 8,266.50          | 5,596.62          | 2,669.88          | 32.30         |
| Miscellaneous Items                               | 0.00              | 0.00              | 0.00              |               |
| Labour  | 1,910.00          | 970.00            | 940.00            | 49.21         |
| Paintwork Labour                                  | 0.00              | 0.00              | 0.00              |               |
| Towing  | 0.00              | 0.00              | 0.00              |               |
| <b>Calculated Gross Total (\$\$)</b>              | <b>10,176.50</b>  | <b>6,566.62</b>   | <b>3,609.88</b>   | <b>35.47</b>  |
| <b>Approved Total (Overridden) (\$\$)</b>         |                   | <b>5,000.00</b>   |                   |               |
| <b>(\$\$)</b>                                     | 10,176.50         | 5,000.00          | 5,176.50          | 50.87         |
| <b>+ GST 7.00/7.00% (\$\$)</b>                    | 712.36            | 350.00            | 362.36            | 50.87         |
| <b>Nett Amount (\$\$)</b>                         | <b>10,888.86</b>  | <b>5,350.00</b>   | <b>5,538.86</b>   | <b>50.87</b>  |
| <b>+ Loss of Use (6.0 x S\$100.00/day) (\$\$)</b> |                   | 600.00            |                   |               |
| <b>+ Doc/Search Fee (\$\$)</b>                    |                   | 8.00              |                   |               |
| <b>Nett Liability (\$\$)</b>                      |                   | <b>5,958.00</b>   |                   |               |

### INSPECTION

Date of Assignment: 31/03/2020

Date Inspected: 31/03/2020 Inspected At:

Precise Auto Service (HQ)  
No 1 Kaki Bukit Ave 6, #02-34/36  
Singapore 417883

Estimated Period of Repair: 4.0 days

---

**Adjuster:** MARCUS CHUA**Manager:** Asher Sng Rong Yi

*NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.*

## REPAIR DETAILS

### Recommended Parts

| No. | Qty | Part No. | Particulars                            | Condition          | Repairer's  | Amount       |
|-----|-----|----------|--|--------------------|-------------|--------------|
| 1   | 1   |          | *FRONT BUMPER FASCIA                   | Distorted          | 1,830.00 FL | *1,516.22 FL |
| 2   | 1   |          | *FRONT BUMPER SIDE RETAINER            | Cracked            | 68.00 FL    | *68.00 FL    |
| 3   | 10  |          | *FRONT BUMPER CLIPS                    | Necessary          | 45.00 FL    | *45.00 FL    |
| 4   | 1   |          | *FRONT BUMPER LOWER GARNISH            | Serviceable        | 156.00 FL   | *- FL        |
| 5   | 1   |          | *FRONT BUMPER PARKING SENSOR -RH       | Shorted            | 281.00 FL   | *245.00 FL   |
| 6   | 1   |          | *HEAD LAMP -RH                         | Cracked            | 3,178.00 FL | *3,012.25 FL |
| 7   | 1   |          | *HEAD LAMP NOZZLE -RH                  | Cracked            | 185.00 FL   | *185.00 FL   |
| 8   | 1   |          | *FRONT FENDER -RH & LH                 | O/S Bent / Cracked | 1,990.00 FL | *995.00 FL   |
| 9   | 2   |          | *FRONT FENDER CHROME MOULDING -RH & LH | Necessary          | 90.00 FL    | *90.00 FL    |
| 10  | 1   |          | *FRONT FENDER EMBLEM BLUE EFFICIENCY   | Necessary          | 62.00 FL    | *62.00 FL    |
| 11  | 1   |          | *FRONT GRILLE                          | Serviceable        | 1,300.00 FL | *- FL        |

F=Franchise part. L=ListItemDisc.

|  |                 |                 |
|--|-----------------|-----------------|
| <b>Sub Total (\$)</b>                                    | <b>9,185.00</b> | <b>6,218.47</b> |
| <b>- List Item Discount on L Items 10.00/10.00% (\$)</b> | 918.50          | 621.85          |
| <b>Total Parts (\$)</b>                                  | <b>8,266.50</b> | <b>5,596.62</b> |

Report was unsubmitted during this print-out.

## Recommended Miscellaneous Items

There are no new miscellaneous items selected.

## Recommended Labour

| No                              | Particulars  | Lab.Type | Repairer's      | Amount        |
|---------------------------------|--|----------|-----------------|---------------|
| <b><u>Labour Items</u></b>      |  |          |                 |               |
| 1                               | TO CHECK WIRING SYSTEM   | New      | 80.00           | 20.00         |
| 2                               | TO RESPRAY AFFECTED AREAS  | New      | 800.00          | 600.00        |
| 3                               | TO RENEW DAMAGED PARTS ,STRAIGHTEN & REPAIR & AND ALIGED ALL PARTS | New      | 750.00          | 300.00        |
| 4                               | TO RESET ELECTRICAL MODULE SYSTEM                                  | New      | 280.00          | 50.00         |
| <b>Gross Labour Cost (\$\$)</b> |  |          | <b>1,910.00</b> | <b>970.00</b> |

Report was unsubmitted during this print-out.

< END OF ESTIMATES >