

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORTAIG Asia Pacific Insurance Pte. Ltd.
AIG Building, 78 Shenton Way, #09-16
Singapore 079120**Our File No:** CC3/AIG20004738/AVV3E2**Date:** 03/11/2020**REFERENCE**

Insured/Claimant:	LIM EK CHOW(LIN YICHAO)	Policy No:	1800024297
Date of Loss:	25/03/2020	Nature of Claim:	OD Claim No: 3501987402SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SKM2899L	Engine No:	CHZ553766
Make & Model:	AUDI Q2, 999cc 1.0 TFSI S TRONIC (A)	Chassis No:	WAUZZZGA9JA030672
Reg. Date:	13/03/2018 (Man. Year: 2017)	Odometer:	26760 km
Colour:	Black		
Engine Capacity:	999 cc		
Market Value/New Car Price:	S\$90,000.00		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	215/60 R16	Rear Tyre Size:	215/60 R16
Front Left Side:	Michelin 6 mm	Rear Left Side:	Michelin 6 mm
Front Right Side:	Michelin 6 mm	Rear Right Side:	Michelin 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	6,865.00	4,122.88	2,742.12	39.94
Miscellaneous Items	0.00	0.00	0.00	
Labour	8,012.00	3,622.00	4,390.00	54.79
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	14,877.00	7,744.88	7,132.12	47.94
- Excess (S\$)	800.00	800.00	0.00	0.00
(S\$)	14,077.00	6,944.88	7,132.12	50.67
+ GST 7.00/7.00% (S\$)	985.39	486.14	499.25	50.67
Nett Amount (S\$)	15,062.39	7,431.02	7,631.37	50.67

INSPECTION

Date of Assignment:	31/03/2020		
Date Inspected:	31/03/2020	Inspected At:	Premium Automobiles Pte Ltd (HQ) 55 UBI ROAD 1 Singapore 408699
Estimated Period of Repair:	6.0 days		

Adjuster: ADRIAN LING**Manager:** VERON CHEN

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FRONT FENDER-LH	Dented	1,079.00 FS	*863.20 FS
2	1		*FRONT FENDER ATTACHMENT PARTS	Not Necessary	38.00 FS	*- FS
3	1		*FRONT FENDER BRACKET-LH	Not Necessary	15.00 FS	*- FS
4	1		*FRONT FENDER CLOSING ELEMENT-LH	Damaged	31.00 FS	*24.56 FS
5	1		*FRONT FENDER INSULATION-LH	Not Necessary	72.00 FS	*- FS
6	1		*WHEEL HOUSING LINER SEAL-UPPER	Not Necessary	35.00 FS	*- FS
7	1		*WHEEL HOUSING LINER-LH	Not Necessary	185.00 FS	*- FS
8	1		*WHEEL HOUSING LINER ATTACHMENT PARTS	Not Necessary	54.00 FS	*- FS
9	1		*FRONT DOOR-LH	Dented	2,380.00 FS	*1,904.00 FS
10	1		*FRONT DOOR ATTACHMENT PARTS	Not Necessary	89.00 FS	*- FS
11	1		*FRONT DOOR CATCH	Damaged	113.00 FS	*90.40 FS
12	1		*FRONT DOOR COVER-LH	Cut	242.00 FS	*193.20 FS
13	1		*EXTERIOR MIRROR MOUNTING	Damaged	485.00 FS	*387.60 FS
14	1		*MIRROR CAP-LH	Not Necessary	159.00 FS	*- FS
15	1		*MIRROR GLASS-LH	Not Necessary	206.00 FS	*- FS
16	2		*FRONT WHEEL COVER-LH/RH	Necessary	606.00 FS	*484.00 FS
17	1		*FRONT ALUMINIUM RIM-LH	Not Necessary	579.00 FS	*- FS
18	1		*SUNDRIES	Necessary	300.00 FS	*18.80 FS
19	1		*FRONT DOOR WINDOW GLASS LHS	Cut	185.00 FS	*148.00 FS
20	1		*FRONT DOOR INNER COVER LHS	Deformed	12.00 FS	*9.12 FS

F=Franchise part. S=SpcNett.

Total Parts (S\$) 6,865.00 4,122.88

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	TO DISMANTLE LHS FRONT DOOR PANEL TRIM. TO REMOVE AND RENEW LHS WING MIRROR ASSY	New	400.00	0.00
2	TO DISMANTLE FRONT BUMPER, LHS FRONT FENDER AND LHS FRONT DOOR.RE-ORGANISE CRASH MANAGEMENT COMPONENTS.REINSTALL ALL PARTS REMOVED	New	3,200.00	1,500.00
3	TO RESPRAY LHS FRONT FENDER,LHS FRONT DOOR AND LHS WING MIRROR COVER	New	2,900.00	1,250.00
4	TO RENEW LHS FRONT RIM AND CARRY OUT WHEEL ALIGNMENT	New	280.00	0.00
5	TO CARRY OUT DIAGNOSTIC CHECK	New	192.00	192.00
6	TO INSTALL SOLAR FILM FOR FRONT DOOR WINDOW GLASS LHS	New	400.00	400.00
7	TO REMOVE,CHECK AND REINSTALL FRONT WIRE HARNESS FOR HEADLIGHTS,HORNS,OUTSIDE TEMPERATURE SENSOR AND HEADLIGHT WASHER ASSY	New	360.00	0.00
8	TO REMOVE AND TRANSFER LHS FRONT DOORS MULTI-LOCK SYSTEM AND POWER WINDOW DEVICES.INSPECT FOR DAMAGES	New	280.00	280.00
			Gross Labour Cost (\$\$)	3,622.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >