

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

AIG Asia Pacific Insurance Pte. Ltd.
AIG Building, 78 Shenton Way, #09-16
Singapore 079120

Our File No: CC3/AIG20004740/ASV3E2

Date: 21/12/2020

REFERENCE

Insured/Claimant: LOH SHU MING Policy No: 1900167425
Date of Loss: 27/03/2020 Nature of Claim: OD Claim No: 0668113356SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: **SMP4083X**
Make & Model: AUDI A4, 2.0 TFSI QU S-TRONIC (A) Engine No: CVK086442
Reg. Date: 25/09/2019 (Man. Year: 2019) Chassis No: WAUZZZF42KA104740
Colour: White Odometer: 12538 km
Engine Capacity: 1984 cc
Market Value/New Car Price: S\$140,000.00
Sum Insured (S\$): **Market Value/New Car Price**

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes
Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 245/40 R18 Rear Tyre Size: 245/40 R18
Front Left Side: Goodyear 6 mm Rear Left Side: Goodyear 6 mm
Front Right Side: Goodyear 6 mm Rear Right Side: Goodyear 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	38,926.50	18,099.84	20,826.66	53.50
Miscellaneous Items	0.00	0.00	0.00	
Labour	16,944.00	6,664.00	10,280.00	60.67
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	55,870.50	24,763.84	31,106.66	55.68
- Excess (S\$)	1,100.00	1,100.00	0.00	0.00
(S\$)	54,770.50	23,663.84	31,106.66	56.79
+ GST 7.00/7.00% (S\$)	3,833.94	1,656.47	2,177.47	56.79
Nett Amount (S\$)	58,604.44	25,320.31	33,284.13	56.79

INSPECTION

Date of Assignment: 31/03/2020
Date Inspected: 31/03/2020 Inspected At: Premium Automobiles Pte Ltd (HQ)
55 UBI ROAD 1
Singapore 408699
Estimated Period of Repair: 9.0 days

Adjuster: ADRIAN LING

Manager: Hiew May Fung

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FRONT BUMPER	Distorted	2,068.00 FS	*1,654.40 FS
2	1		*FRONT BUMPER FIXING PARTS	Not Necessary	553.00 FS	*- FS
3	2		*FRONT BUMPER SECURING STRIP	Not Necessary	67.00 FS	*- FS
4	1		*FRONT BUMPER GRILLE - CENTRE	Not Necessary	185.00 FS	*- FS
5	1		*FRONT BUMPER CLOSING ELEMENT - LOWER CENTRE	Cracked	198.00 FS	*158.00 FS
6	1		*FRONT BUMPER AIR GUIDE - LH	Not Necessary	59.00 FS	*- FS
7	1		*RADIATOR GRILLE	Cracked	2,058.00 FS	*1,646.40 FS
8	1		*FRONT BUMPER AIR GUIDE GRILLE - LH	Cracked	344.00 FS	*275.20 FS
9	1		*FRONT BUMPER CARRIER	Not Necessary	757.00 FS	*- FS
10	1		*FRONT BUMPER FOAM FILLER PIECE	Cracked	117.00 FS	*93.60 FS
11	1		*FRONT BUMPER COVER	Damaged	120.00 FS	*96.00 FS
12	1		*FRONT BUMPER GUIDE SECTION - LH	Damaged	34.00 FS	*27.12 FS
13	1		*FRONT BUMPER BRACKET - LH	Not Necessary	214.00 FS	*- FS
14	1		*CAUTION SIGN STICKER	Necessary	13.00 FS	*10.24 FS
15	1		*AIRCON STICKER	Necessary	7.00 FS	*5.36 FS
16	1		*LOCK CARRIER BRACKET	Cracked	129.00 FS	*103.20 FS
17	2		*FRONT BUMPER SUPPORT - LH / RH	Not Necessary	54.00 FS	*- FS
18	1		*HORN - LH HIGH TONE	Not Necessary	38.00 FS	*- FS
19	1		*SPRING SHACKLE - LH	Not Necessary	27.00 FS	*- FS
20	1		*FRONT PARKING AID SENSOR - INNER / OUTER (2PCS)	Damaged (1Pc Only)	245.50 FS	*196.40 FS
21	4		*FRONT PARKING AID SEAL RING	Not Necessary	14.00 FS	*- FS
22	1		*FRONT FENDER - LH	Distorted	722.00 FS	*577.60 FS
23	1		*FRONT FENDER ATTACHMENT PARTS	Not Necessary	190.00 FS	*- FS
24	1		*FRONT FENDER CLOSING ELEMENT - LH	Not Necessary	47.00 FS	*- FS
25	1		*FRONT FENDER BRACKET - LH	Bent	33.00 FS	*26.24 FS
26	1		*DEFORMATION ELEMENT BRACKET - LH	Necessary	46.00 FS	*36.80 FS
27	1		*FRONT FENDER BRACKET	Bent	30.00 FS	*23.52 FS
28	1		*FRONT FENDER UPPER BRACKET - LH	Damaged	32.00 FS	*24.96 FS
29	1		*FRONT FENDER BRACE - LH	Distorted	112.00 FS	*89.20 FS
30	1		*FRONT FENDER CLOSING ELEMENT - LH	Not Necessary	31.00 FS	*- FS
31	1		*FRONT FENDER COVER - LH	Necessary	11.00 FS	*8.56 FS
32	1		*WHEEL HOUSING LINER - LH	Deformed	226.00 FS	*180.40 FS
33	1		*WHEEL HOUSING LINER ATTACHMENT PARTS	Not Necessary	219.00 FS	*- FS
34	1		*WHEEL SPOILER - LH	Cracked	69.00 FS	*55.04 FS
35	1		*WHEEL SPOILER TRIM - LH	Not Necessary	33.00 FS	*- FS
36	1		*STONE CHIP GUARD - LH	Necessary	48.00 FS	*37.92 FS
37	1		*BONNET	Dented	2,634.00 FS	*2,107.20 FS
38	1		*BONNET ATTACHMENT PARTS	Not Necessary	388.00 FS	*- FS
39	2		*BONNET LID HINGE - LH / RH	Not Necessary	574.00 FS	*- FS
40	1		*BONNET IMPACT PROTECTION - CENTRE	Necessary	26.00 FS	*20.56 FS
41	2		*BONNET IMPACT PROTECTION - LH / RH	Necessary	52.00 FS	*41.36 FS
42	1		*FENDER LEDGE COVER - LH INNER	Not Necessary	58.00 FS	*- FS
43	1		*FENDER LEDGE COVER - LH	Not Necessary	29.00 FS	*- FS
44	1		*FENDER LEDGE COVER - LH	Necessary	21.00 FS	*16.72 FS
45	2		*BONNET GAS FILLED STRUT	Not Necessary	224.00 FS	*- FS
46	2		*BONNET STRIKER - LH / RH	Not Necessary	94.00 FS	*- FS
47	2		*BONNET LID LOCK	Not Necessary	403.00 FS	*- FS
48	1		*BONNET BOWDEN CABLE - CENTRE	Not Necessary	54.00 FS	*- FS
49	1		*BONNET BOWDEN CABLE	Not Necessary	54.00 FS	*- FS
50	1		*BONNET RELEASE LEVER	Not Necessary	13.00 FS	*- FS
51	1		*PLENUM CHAMBER COVER	Not Necessary	92.00 FS	*- FS

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
52	1		*BONNET SOUND ABSORBER	Not Necessary	323.00 FS	*- FS
53	1		*LED HEADLIGHT - LH	Cracked	7,321.00 FS	*5,856.80 FS
54	1		*MAIN LIGHT ELECTRONICS POWER MODULE	Not Necessary	732.00 FS	*- FS
55	1		*LIGHT CONTROL SYSTEM CONTROL UNIT	Not Necessary	707.00 FS	*- FS
56	1		*HEADLAMP HOUSING REPAIR KIT - LH	Not Necessary	124.00 FS	*- FS
57	1		*HEADLIGHT HOSE - LH	Not Necessary	34.00 FS	*- FS
58	1		*LIFT CYLINDER - LH	Cracked	198.00 FS	*158.00 FS
59	1		*LIFT CYLINDER CORRUGATED PIPE	Not Necessary	88.00 FS	*- FS
60	1		*LOCK CARRIER	Not Necessary	956.00 FS	*- FS
61	2		*COOLANT REGULATOR SUPPORT	Not Necessary	71.00 FS	*- FS
62	1		*AIRCON CONDENSER	Not Necessary	586.00 FS	*- FS
63	1		*REFRIGERANT LINE	Not Necessary	157.00 FS	*- FS
64	1		*REFRIGERANT LINE	Not Necessary	320.00 FS	*- FS
65	1		*CHARGE AIR COOLER	Not Necessary	552.00 FS	*- FS
66	1		*PRESSURE PIPE - LH	Not Necessary	402.00 FS	*- FS
67	1		*RADIATOR AIR GUIDE - LH	Not Necessary	27.00 FS	*- FS
68	1		*RADIATOR AIR GUIDE - LH	Not Necessary	12.00 FS	*- FS
69	1		*RADIATOR AIR GUIDE - LOWER	Not Necessary	21.00 FS	*- FS
70	1		*RADIATOR AIR GUIDE - UPPER	Not Necessary	15.00 FS	*- FS
71	1		*FRONT DOOR - LH	Dented	2,243.00 FS	*1,794.40 FS
72	1		*FRONT DOOR OUTER SEAL - LH	Necessary	193.00 FS	*154.40 FS
73	1		*BONDING AGENT	Necessary	46.00 FS	*36.72 FS
74	1		*CLEANING SOLUTION	Necessary	64.00 FS	*51.20 FS
75	1		*FRONT DOOR ATTACHMENT PARTS	Not Necessary	828.00 FS	*- FS
76	1		*FRONT DOOR CATCH	Not Necessary	99.00 FS	*- FS
77	1		*EXTERIOR MIRROR MOUNTING - LH	Damaged	1,025.00 FS	*820.00 FS
78	1		*MIRROR CAP - LH	Missing	249.00 FS	*199.20 FS
79	1		*MIRROR GLASS - LH	Cracked	1,137.00 FS	*909.60 FS
80	1		*WINDOW SLOT SEAL - LH	Cut	289.00 FS	*230.80 FS
81	1		*WINDOW GUIDE TRIM STRIP	Not Necessary	242.00 FS	*- FS
82	1		*CORNER TRIM - LH	Not Necessary	43.00 FS	*- FS
83	1		*FRONT DOOR WINDOW - LH	Cut	273.00 FS	*218.00 FS
84	1		*FRONT WISHBONE LINK - LH	Not Necessary	507.00 FS	*- FS
85	1		*FRONT SUSPENSION GUIDE - LH	Not Necessary	887.00 FS	*- FS
86	1		*UPPER CONTROL ARM - LH	Not Necessary	480.00 FS	*- FS
87	1		*REAR UPPER CONTROL ARM - LH	Not Necessary	480.00 FS	*- FS
88	1		*WHEEL BEARING HOUSING - LH	Not Necessary	912.00 FS	*- FS
89	1		*SWIVEL JOINT	Not Necessary	182.00 FS	*- FS
90	1		*WHEEL HUB	Not Necessary	460.00 FS	*- FS
91	1		*SUSPENSION FORKS - LH	Not Necessary	249.00 FS	*- FS
92	1		*COUPLING RODS	Not Necessary	125.00 FS	*- FS
93	1		*GAS SHOCK ABSORBER	Not Necessary	284.00 FS	*- FS
94	1		*TRACK ROD	Not Necessary	93.00 FS	*- FS
95	1		*STEERING GEAR GREASE	Not Necessary	41.00 FS	*- FS
96	1		*TIE ROD END	Not Necessary	186.00 FS	*- FS
97	1		*DOUBLE ANGLED BALL BEARING	Not Necessary	237.00 FS	*- FS
98	1		*FRONT RIM - LH (NPA)	Not Necessary	0.00 FS	*- FS
99	1		*FRONT NO PLATE	Necessary	60.00 FS	*60.00 FS
100	1		*SUNDRIES	Necessary	500.00 FS	*98.72 FS

F=Franchise part. S=SpcNett.

Total Parts (S\$) 38,926.50 18,099.84

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	TO TOW BACK FROM ACCIDENT SCENE	New	280.00	0.00
2	TO REMOVE, CHECK AND REINSTALL FRONT WIRE HARNESS FOR HEADLIGHTS, HORNS, OUTSIDE TEMPERATURE SENSOR, HEADLIGHT WASHER ASSY AND FRONT PARKING AID	New	480.00	480.00
3	TO REMOVE AND RENEW AIRCOND CONDENSER, CHARGED AIR COOLER AND RADIATOR. CHECK ELECTRICAL FANS AND CONTROL UNIT. PRESSURISE COOLING SYSTEM. TO CARRY OUT VACUUM AND REGAS	New	1,200.00	0.00
4	TO INSTALL SOLAR FILM FOR LHS FRONT DOOR WINDOW GLASS	New	400.00	400.00
5	TO REMOVE AND TRANSFER LHS FRONT DOORS MULTI LOCK SYSTEM AND POWER WINDOW DEVICES. INSPECT FOR DAMAGES	New	280.00	280.00
6	TO DISMANTLE LHS FRONT DOOR PANEL TRIM	New	350.00	0.00
7	TO DISMANTLE AND RENEW FRONT BUMPER, BONNET, LHS FRONT FENDER, LHS HEADLIGHT AND LHS FRONT DOOR. TO RENEW FRONT LOCK CARRIER AND ALIGN TO POSITION. RE-ORGANISE CRASH MANAGEMENT COMPONENTS. REINSTALL ALL PARTS REMOVED	New	5,950.00	2,250.00
8	TO RESPRAY FRONT BUMPER, LHS FRONT FENDER, BONNET, HINGES, LHS FRONT DOOR, LHS WING MIRROR COVER AND LHS SILL PANEL	New	5,300.00	2,350.00
9	TO RENEW LHS FRONT RIM. TO CARRY OUT PRE-WHEEL ALIGNMENT AND POST-WHEEL ALIGNMENT TEST	New	520.00	520.00
10	TO CARRY OUT DIAGNOSTIC CHECK	New	384.00	384.00
11	TO RENEW LHS FRONT WHEEL SUSPENSION ASSY. TO INSPECT FOR FURTHER DAMAGES	New	1,800.00	0.00
			Gross Labour Cost (S\$)	16,944.00
				6,664.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >