Adjuster Report Page 1 of 4

### LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

#### VEHICLE DAMAGE INSPECTION REPORT

Our File No: CC6/III20004744/AGA3Q2

**Date:** 25/01/2021

**REFERENCE** 

Handling Insurer: India International Insurance Pte Ltd Policy No: MCOM0015

Claimant FRK95/177 Insured Vehicle No: SHA3633D

Vehicle No: FBK9547Z Insured Vehicle No: SHA3633D

Date of Loss: 21/03/2020 Nature of Claim: TP Claim No: MCT20030403

**DESCRIPTION & IDENTIFICATION OF VEHICLE** 

Reg No: FBK9547Z

 Make & Model:
 HONDA CB400SF, 399cc
 Engine No:
 NC42E1204937

 Reg. Date:
 16/04/2016 (Man. Year: 2015)
 Chassis No:
 NC421604929

Colour: Red Odometer: 0 km

Engine Capacity: 399 cc Market Value/New Car Price: N/A

Sum Insured (S\$): Market Value/New Car Price

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes

Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

**CONDITION OF TYRES** 

Front Tyre Size: 150/60 R17 Rear Tyre Size: 160/60 R17
Front Left Side: Bridgestone 6 mm Rear Left Side: Bridgestone 6 mm
Front Right Side: Bridgestone 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	2,675.95	1,404.00	1,271.95	47.53
Miscellaneous Items	0.00	0.00	0.00	
Labour	550.00	460.00	90.00	16.36
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	3,225.95	1,864.00	1,361.95	42.22
Approved Total (Overridden) (S\$)		1,500.00		
Nett Amount (S\$)	3,225.95	1,500.00	1,725.95	53.50
+ Loss of Use (3.0 x S\$2	20.00/day) (S\$)	60.00		
+ Doc/S	earch Fee (S\$)	7.45		
Net	tt Liability (S\$)	1,567.45		

INSPECTION

Date of Assignment: 30/03/2020

Date Inspected: 30/03/2020 Inspected At: Hua Meng Spray Painting Workshop

(HQ)

No 1 Kaki Bukit Avenue 6, #01-61

Autobay@Kaki Bukit Singapore 417883

Estimated Period of Repair: 3.0 days

Adjuster: ADRIAN LING Manager: Chong Pui Lin

Adjuster Report Page 2 of 4

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

Adjuster Report Page 3 of 4

### **REPAIR DETAILS**

Part Source: (Last Synchronised: 07 Jan 2021)

Parts: N/A HONDA CB400SF 399cc (Model not available in database)

Labour: Repairer's (Price-denominated Standard List)

Print Code: (Unsubmitted, no print-code for FBK9547Z)

Validity: These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page

Further Info: Items/values not in reference catalogue are prefixed with an asterisk \*.

#### **Recommended Parts**

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount		
1	1		*TAILLAMP	Cracked	253.00 FL	*253.00 FL		
2	2		*REAR SEAT CENTRE GARNISH	Cracked	644.00 FL	*198.00 FL		
3	2		*REAR SEAT SIDE GARNISH	Cracked	414.00 FL	*209.00 FL		
4	1		*REAR WHEEL FENDER	Not Necessary	201.30 FL	*- FL		
5	1		*REAR WHEEL FENDER REFLECTOR	Not Necessary	28.80 FL	*- FL		
6	2		*REAR SIGNAL LAMP	Not Necessary	179.40 FL	*- FL		
7	1		*REAR BOX	Cracked	345.00 FS	*345.00 FS		
8	1		*REAR BOX BASE	Not Necessary	92.00 FS	*-FS		
9	1		*REAR BOX BRACKET	Not Necessary	138.00 FS	*- FS		
10	1		*REAR BOX REFLECTIVE STICKERS	Necessary	57.50 FS	*30.00 FS		
11	1		*REAR CAMERA	Damaged	460.00 FS	*400.00 FS		
12	1		*REAR NUMBER PLATE	Bent	35.00 FS	*35.00 FS		
F=Franchise part. S=SpcNett. L=ListItemDisc.								
				Sub Total (S\$)	2,848.00	1,470.00		
	- List Item Discount on L Items 10.00/10.00% (S\$)				172.05	66.00		
				Total Parts (S\$)	2,675.95	1,404.00		
	Report was unsubmitted during this print-out.							

Adjuster Report Page 4 of 4

# Recommended Miscellaneous Items

There are no new miscellaneous items selected.

## Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Lab	our Items			
1	TO CHECK WIRING	New	50.00	30.00
2	REMOVE & REINSTALL REAR CAMERA	New	50.00	30.00
3	REMOVE, REPLACE & REPAIR CONSISTENT TO THE ACCIDENT	New	250.00	200.00
4	RESPRAY PAINTING	New	200.00	200.00
	Gross Labour Cost (S\$)		550.00	460.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >