



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 3

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SFB 3344G

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	<u>REPLACEMENT OF PARTS</u>			
1	FRT BONNET	TO REPAIR SEE LABOUR	1,958.00	-
10	FRT FENDER WHEELARCH CLIP	NECESSARY	65.00	26.00
10	FRT FENDER INNERSHIELD CLIP	NOT NECESSARY	65.00	-
1	FRT FENDER RH	DENTED	1,243.00	1,243.00
1	FRT FENDER BRACKET RH	NOT NECESSARY	128.00	-
1	FRT FENDER INNERSHIELD RH	NOT NECESSARY	268.00	-
1	FRT FENDER TOP GARNISH RH	NOT NECESSARY	88.00	-
1	FRT FENDER WHEELARCH GARNISH RH	CUT	152.00	152.00
1	FRT BUMPER	BROKEN	1,406.00	1,406.00
1	FRT BUMPER LOWER	CUT	516.00	516.00
1	FRT BUMPER LOWER GARNISH (SILVER COLOUR)	NOT NECESSARY	333.00	-
10	FRT BUMPER CLIP	NECESSARY	65.00	26.00
1	FRT BUMPER SIDE RETAINER LH, SUPPORT	NOT NECESSARY	133.00	-
1	FRT BUMPER SIDE RETAINER RH, SUPPORT	BROKEN	133.00	133.00
1	FRT BUMPER BRACKET LH, GUIDE	NOT NECESSARY	111.00	-
1	FRT BUMPER BRACKET RH, GUIDE	CRACKED	111.00	111.00
1	FRT BUMPER SPONGE	CRACKED	263.00	263.00
1	FRT BUMPER REINFORCEMENT, IMPACT BAR	NOT NECESSARY	927.00	-
1	FRT BUMPER LOGO	NECESSARY	158.00	158.00
1	FRT BUMPER LOW LIP	NOT NECESSARY	173.00	-
1	FRT BUMPER FOG LAMP COVER RH	NOT NECESSARY	113.00	-
1	FRT BUMPER FOG LAMP RH	CRACKED	330.00	330.00
1	FRT GRILLE TOP	NOT NECESSARY	243.00	-
1	FRT GRILLE TOP COVER	NOT NECESSARY	131.00	-
1	FRT GRILLE LOW	NOT NECESSARY	311.00	-
1	RH HEADLAMP	CUT	983.00	983.00
1	FRT WHEELHOUSE MEMBER RH	NOT NECESSARY	651.00	-
1	A/C CONDENSER	NOT NECESSARY	875.00	-
1	A/C CONDENSER TOP AIR GUIDE	NOT NECESSARY	150.00	-
1	FRT KNUCKLE ARM RH	NOT NECESSARY	417.00	-

Report Ref No. CS/LPC20004756/Esd3e2



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:2 of 3

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
1	FRT WHEEL BEARING RH	DAMAGED	587.00	587.00
1	FRT LOW ARM RH	NOT NECESSARY	928.00	-
1	FRT SHOCK ABSORBER RH	NOT NECESSARY	443.00	-
1	FRT STABILIZER LINK RH	NOT NECESSARY	142.00	-
1	FRT RIM RH	CUT	898.00	898.00
1	FRT RH DOOR	NOT NECESSARY	1,700.00	-
1	FRT RH DOOR BLACK STICKER	NOT NECESSARY	196.00	-
1	FRT RH DOOR PROTECTOR	NOT NECESSARY	151.00	-
1	FRT INTAKE RESONATOR BOX (ADDITIONAL)	CRACKED	145.00	145.00
1	FRT INTAKE AIR DUCT (ADDITIONAL)	CRACKED	145.00	145.00
	LESS 10% DISCOUNT		-1,783.50	-712.20
			16,051.50	6,409.80
	<u>SPECIAL NETT ITEMS</u>			
1	FRT NUMBER PLATE (SN)	NOT NECESSARY	65.00	-
1	FRT TYRE RH (SN)	TORN	300.00	200.00
			365.00	200.00
	<u>LABOUR</u>			
	TO DISMANTLE / RENEW THE ACCIDENT DAMAGED PORTION, TO PANEL BEATING, RESHAPE, STRAIGHTEN, ORIENTATE AND ALIGN REPAIR / REPLACEMENT PARTS. INCLUSIVE OF THE REPAIR OF FRT BONNET.		2,750.00	1,100.00
	CARRY OUT SPRAY PAINTING ON AFFECTED AREA, FRT BUMPER, FRT BONNET, FRT SUPORT PANEL, FRT WHEELHOUSE PANEL RH, FRT FENDER RH, FRT DOOR RH.		3,000.00	1,500.00
	TO DISCONNECT WIRE HARNESS OF ELECTRICAL COMPONENT TO FACILITATE REPAIRS, RECONNECT AND CHECK ELECTRICAL FUNCTION AFTER REPAIR.		120.00	80.00
	TO REMOVE AND REFIT AIRCON CONDENSOR, VACUUM, REFILL AND CHECK AIR CON GAS SYSTEM.	NOT NECESSARY	220.00	-
	TO REMOVE AND REFIX RADIATOR AND CONDUCT PRESSURE TEST.	NOT NECESSARY	120.00	-
	TO REMOVE AND REPLACE RHF UNDER CARRIAGE PARTS.		550.00	275.00
	TO CONDUCT 4 WHEEL ALIGNMENT.		180.00	120.00

Report Ref No. CS/LPC20004756/Esd3e2



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:3 of 3

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	TO CONDUCT RESET OF ENGINE LIGHT ON.	NOT NECESSARY	350.00	-
			7,290.00	3,075.00
GRAND TOTAL			23,706.50	9,684.80
RECOMMENDED COST OF REPAIRS				9,684.80
LESS EXCESS				-500.00
NETT LIABILITY				9,184.80

Report Ref No. CS/LPC20004756/Esd3e2

CHEN TSUE YEE

Automotive Assessor

ADRIAN LING WAI PING

B.Eng,AMSOE,AMIRTE,AMSAE-A,M.MATAI

Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.