Adjuster Report Page 1 of 4

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CC6/AIG20004765/R1DS3Q2

Date: 28/07/2020

REFERENCE

Handling Insurer: AIG Asia Pacific Insurance Pte. Ltd. Policy No: 1900013989 Claimant SJA5555J Insured Vehicle No: SJF950H

Vehicle No:

Date of Loss: 28/03/2020 ΤP Nature of Claim: Claim No: 9439338594SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

SJA5555J Reg No:

BMW 640I, 3.0 GRAN COUPE M SPORT LED SR Engine No: Make & Model: 07708676N55B30A

NAV HUD (A)

Reg. Date: 10/07/2014 (Man. Year: 2013) Chassis No: WBA6A02030DZ12261

Colour: Gold Odometer: 82860 km

Engine Capacity: 2979 сс Market Value/New Car N/A

Price:

Market Value/New Car Price Sum Insured (S\$):

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes

Handbrake (Serviceable): Yes Engine Modification: Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 245/40R F19 Rear Tyre Size: 245/40R F19 Front Left Side: Rear Left Side: Bridgestone 6 mm Bridgestone 6 mm Front Right Side: Rear Right Side: Bridgestone 6 mm Bridgestone 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	7,904.00	7,904.00	0.00	0.00
Miscellaneous Items	0.00	0.00	0.00	
Labour	910.00	560.00	350.00	38.46
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Gross Tota	I (S\$) 8,814.00	8,464.00	350.00	3.97
+ GST 7.00/7.00%	(S\$) 616.98	592.48	24.50	3.97
Nett Amoun	t (S\$) 9,430.98	9,056.48	374.50	3.97
+ Loss of Us	se (4.0 x S\$120.00/day) (S\$)	480.00		

Nett Liability (S\$) 9,536.48

INSPECTION

Date of Assignment: 15/04/2020

Date Inspected: 15/04/2020 Inspected At: Woon Meng Motor Pte Ltd (Bukit

Batok)

50 Bukit Batok Street 23., #01-06

Midview Building Singapore 659578

Estimated Period of Repair: 3.0 days Adjuster Report Page 2 of 4

Adjuster: MOHD RASUL Manager: CHAN JIA LE

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

Adjuster Report Page 3 of 4

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount		
1	1		*FRONT BUMPER (NPA)	Repair	0.00 FL	*- FL		
2	1		*FRONT HEADLAMP O/S	Scratched	7,800.00 FL	*7,800.00 FL		
3	1		*FRONT BUMPER SENSOR	Scratched	520.00 FL	*520.00 FL		
F=Franchise part. L=ListItemDisc.								
				Sub Total (S\$)	8,320.00	8,320.00		
- List Item Discount on L Items 5.00/5.00% (S\$)					416.00	416.00		
				Total Parts (S\$)	7,904.00	7,904.00		
Report was unsubmitted during this print-out.								

Adjuster Report Page 4 of 4

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Lab	our Items			
1	TO REMOVE, REPAIR , REPLACE & INSTALL DAMAGED PARTS	New	350.00	200.00
2	TO R&R SENSOR WIRING	New	100.00	80.00
3	TO R&R WIRING	New	60.00	30.00
4	TO PUTTY & SPRAY PAINTING	New	400.00	250.00
	Gross Labor	ır Cost (S\$)	910.00	560.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >