

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CC4/AIG20004771/R1DS3Q2
Date: 28/09/2020

REFERENCE

Handling Insurer: AIG Asia Pacific Insurance Pte. Ltd. Policy No: 1800067098
Claimant
Vehicle No : SLK4384R **Insured Vehicle No :** SJJ318M
 Date of Loss: 30/03/2020 Nature of Claim: TP Claim No: 0169805002SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: **SLK4384R**
 Make & Model: MAZDA 3, 1.5 L 4-DOOR SEDAN SP.6EAT (A) Engine No: P520421103
 Reg. Date: 17/01/2017 (Man. Year: 2016) Chassis No: JM6BN22A8H0135771
 Colour: Grey Odometer: 170222 km
 Engine Capacity: 1496 cc
 Market Value/New Car Price: N/A
 Sum Insured (S\$): **Market Value/New Car Price**

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes
 Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 205/60 R15 Rear Tyre Size: 205/60 R15
 Front Left Side: Firenza 6 mm Rear Left Side: Firenza 6 mm
 Front Right Side: Firenza 6 mm Rear Right Side: Firenza 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	3,082.80	1,674.56	1,408.24	45.68
Miscellaneous Items	0.00	0.00	0.00	
Labour	1,650.00	700.00	950.00	57.58
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	4,732.80	2,374.56	2,358.24	49.83
Approved Total (Overridden) (S\$)		1,800.00		
(S\$)	4,732.80	1,800.00	2,932.80	61.97
+ GST 7.00/7.00% (S\$)	331.30	126.00	205.30	61.97
Nett Amount (S\$)	5,064.10	1,926.00	3,138.10	61.97
+ Loss of Use (4.0 x S\$70.00/day) (S\$)		280.00		
+ Doc/Search Fee (S\$)		7.45		
Nett Liability (S\$)		2,213.45		

INSPECTION

Date of Assignment: 01/04/2020
 Date Inspected: 01/04/2020 Inspected At: 60 Jalan Lam Huat #03-35/36
 Singapore 737869
 Repairer: Lion City Rentals Pte Ltd (HQ)
 Estimated Period of Repair: 3.0 days

Adjuster: MOHD RASUL**Manager:** CHAN JIA LE

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*REAR BUMPER	Deformed	1,129.00 FL	*1,129.00 FL
2	1		*REAR BUMPER RETAINER RH	Serviceable	58.15 FL	*- FL
3	1		*REAR BUMPER REINFORCEMENT	Bent	564.20 FL	*564.20 FL
4	1		*REAR BUMPER LOWER COVER	Serviceable	300.00 FL	*- FL
5	1		*REAR BOOT	Serviceable	1,005.30 FL	*- FL
6	1		*REAR BUMPER RETAINER LH	Serviceable	58.15 FL	*- FL
7	1		*REAR BOOT SKYACTIV EMBLEM	Not Necessary	66.80 FL	*- FL
8	1		*REAR BOOT MAZDA LOGO	Not Necessary	78.30 FL	*- FL
9	1		*REAR BOOT MAZDA 3 EMBLEM	Not Necessary	56.10 FL	*- FL
10	1		*REAR BUMPER LH TOW COVER	Missing	50.00 FL	*50.00 FL
11	1		*REVERSE SENSOR	Not Working	240.00 FS	*200.00 FS
12	1		*BUMPER CLIPS	Necessary	150.00 FS	*80.00 FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (\$)	3,756.00	2,023.20
- List Item Discount on L Items 20.00/20.00% (\$)	673.20	348.64
Total Parts (\$)	3,082.80	1,674.56

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	TO LABOUR CHARGE FOR REMOVING REAR BUMPER ,REAR BOOT ,END PANEL OUT TO FACILITATE REPAIRS AND REPLACEMENT OF DAMAGED PARTS	New	750.00	300.00
2	TO RESPRAY REAR BUMPER ,REAR BOOT ,REAR END PANEL AND SPRAY TYRE PANEL	New	900.00	400.00
			Gross Labour Cost (\$\$)	700.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >