

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CC4/III20004776/R1PS3Q2

Date: 14/09/2020

REFERENCE

Handling Insurer:	India International Insurance Pte Ltd	Policy No:	D18MCV0002394_01
Claimant Vehicle No :	SHB340M	Insured Vehicle No :	GBF4506B
Date of Loss:	28/03/2020	Nature of Claim:	TP
		Claim No:	MCV2020D0000748

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SHB340M		
Make & Model:	TOYOTA PRIUS TAXI, 1.8 (A)	Engine No:	2ZR6165703
Reg. Date:	19/09/2014 (Man. Year: 2014)	Chassis No:	JTDKN36U405750591
Colour:	Maroon	Odometer:	554832 km
Engine Capacity:	1798 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	195/65 R15	Rear Tyre Size:	195/65 R15
Front Left Side:	Neuton 6 mm	Rear Left Side:	Neuton 6 mm
Front Right Side:	Neuton 6 mm	Rear Right Side:	Neuton 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	9,911.43	997.13	8,914.30	89.94
Miscellaneous Items	0.00	0.00	0.00	
Labour	2,781.00	1,210.00	1,571.00	56.49
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	12,692.43	2,207.13	10,485.30	82.61
Approved Total (Overridden) (S\$)		2,050.00		
Nett Amount (S\$)	12,692.43	2,050.00	10,642.43	83.85
+ Loss of Use (7.0 x S\$69.00/day) (S\$)		483.00		
+ Car Rental (7.0 x S\$100.58/day) (S\$)		704.06		
+ Doc/Search Fee (S\$)		7.00		
Nett Liability (S\$)		3,244.06		
Global Sum Settlement (S\$)		3,200.00		

INSPECTION

Date of Assignment: 31/03/2020

Date Inspected: 01/04/2020 Inspected At:

Smrt Automotive Services Pte Ltd
(HQ)
No. 61 Woodlands Industrial Park E9,
#04-04 Premium Building
Singapore 757047

Estimated Period of Repair: 4.0 days

Adjuster: MOHD RASUL

Manager: CHEW HSIAO TONG

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference

Part Source: MRM-SG	Version: 1.0 (Last Synchronised: 09 Jun 2020)
Parts: 144	TOYOTA PRIUS TAXI 1.8 (A) (Catalogue:Merimen Singapore 1.0)
Labour: Repairer's	(Price-denominated Standard List)
Print Code: (Unsubmitted, no print-code for SHB340M)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FENDER FRT/LH (DISC 25%)	Buckled	723.40 F	*542.55 F
2	1		*NAME PLATE (HYBRID) (DISC 25%)	Necessary	51.90 F	*38.93 F
3	1		*MIRROR LAMP LH (DISC 10%)	Scratched	65.30 F	*58.77 F
4	1		*STICKER DECAL SMRT (DOOR) (SN)	Necessary	60.00 F	*60.00 F
5	1		*ADVERTISEMENT STICKER (SN)	Necessary	296.88 F	*296.88 F
6	1		*DOOR FRT/LH	Repair	894.40 F	*- F
7	1		*COVER OUTER MIRROR LH	Repair	107.40 F	*- F
8	1		*WHEEL DISC FRONT	Repair	1,484.20 F	*- F
9	1		*BUMPER FRT	Repair	482.00 F	*- F
10	1		*HINGE LOWER LHF ,DOOR	Not Necessary	90.10 F	*- F
11	1		*HINGE UPPER LHF ,DOOR	Not Necessary	80.50 F	*- F
12	1		*FENDER PROTECTOR FRT/LH UPPER	Not Necessary	46.10 F	*- F
13	1		*PROTECTOR FRONT FENDER SIDE PANEL LH	Not Necessary	114.50 F	*- F
14	1		*FENDER LINER FRT/LH	Not Necessary	171.70 F	*- F
15	1		*FENDER LINER PAD ,FR WHEEL LH	Not Necessary	49.30 F	*- F
16	1		*FENDER APRON SUB FRT/LH	Not Necessary	637.80 F	*- F
17	1		*BUMPER CLIPS	Not Necessary	1.61 F	*- F
18	1		*BUMPER SUPPORT F/RH	Not Necessary	76.40 F	*- F
19	1		*BUMPER SUPPORT F/LH	Not Necessary	76.40 F	*- F
20	1		*BUMPER ENERGY ABSORBER FRT	Not Necessary	78.80 F	*- F
21	1		*BUMPER REINFORCEMENT FRT	Not Necessary	498.40 F	*- F
22	1		*ARM SUB-ASSY ,FR BUMPER LH	Not Necessary	250.40 F	*- F
23	1		*ARM SUB-ASSY ,FR BUMPER RH	Not Necessary	250.40 F	*- F
24	1		*BUMPER GRILLE SUB-ASSY ,LOWER	Not Necessary	311.10 F	*- F
25	1		*BUMPER LIP FRT	Not Necessary	139.60 F	*- F
26	1		*BUMPER FRT ABSORBER LOWER	Not Necessary	127.70 F	*- F
27	1		*UNDER COVER CENTER	Not Necessary	448.30 F	*- F
28	1		*TYRE	Serviceable	126.74 F	*- F
29	1		*HEAD LAMP LH	Serviceable	945.20 F	*- F
30	1		*MIRROR ASSY ,LH	Serviceable	1,224.90 F	*- F

F=Franchise part.

Total Parts (S\$) 9,911.43 997.13

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	PANEL BEATING & BODY WORK	New	507.00	300.00
2	SPRAY PAINT	New	1,674.00	750.00
3	TO REMOVE AND REFIT TYRE RIM (SPRAYING PURPOSE)	New	120.00	30.00
4	TO REMOVE AND REFIX WING MIRROR	New	120.00	70.00
5	TO REPLACE SUNDRY PARTS	New	100.00	0.00
6	TO CHECK WIRING AND SYSTEM FUNCTION	New	80.00	0.00
7	TO WASH AND VACUUM	New	60.00	0.00
8	TO DO WHEEL ALIGNMENT /TYRE BALANCING	New	120.00	60.00
Gross Labour Cost (\$\$)			2,781.00	1,210.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >