



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 1

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. FBP 1228X

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	<u>REPLACEMENT OF PARTS</u>			
1	HANDLE BAR (CONSISTENT)	NOT NECESSARY	105.00	-
1	VISOR (CONSISTENT)	CUT	280.00	280.00
1	HEAD LAMP ASSY (CONSISTENT)	CRACKED	850.00	850.00
1	HEAD LAMP PANEL -FRONT (CONSISTENT)	CUT	105.00	105.00
2	FRONT SIDE PANEL L/RH (CONSISTENT)	N/S CUT / O/S CRACKED	260.00	260.00
1	FRONT MUDGUARD (CONSISTENT)	BROKEN / CUT	350.00	350.00
1	LOWER PANEL -BELLY PAN (CONSISTENT)	CUT	150.00	150.00
1	LH STEP BOARD PANEL (CONSISTENT)	CUT	150.00	150.00
1	SET MIRROR (CONSISTENT)	N/S CUT	78.00	39.00
1	EXHAUST GUARD (CONSISTENT)	NOT NECESSARY	120.00	-
1	INITION SWTICH COVER RH (CONSISTENT)	NOT NECESSARY	150.00	-
1	SET FORK TUBE (CONSISTENT)	DISTORTED	560.00	560.00
1	FORK TUBE BRACKET UNDER (CONSISTENT)	NOT NECESSARY	250.00	-
	LESS 10% DISCOUNT		-340.80	-274.40
			3,067.20	2,469.60
	<u>LABOUR</u>			
	TOWING FEE.	NOT NECESSARY	40.00	-
	REMOVE & REPLACE NECESSARY PARTS, ALIGN & ETC.		280.00	200.00
	REMOVE & CHARGE FORK TUBE ,TOP UP FORK OIL SEAL -RE-ALIGN.		150.00	80.00
	PUTTY & TOUCH UP PAINT WORK.		320.00	150.00
			790.00	430.00
	GRAND TOTAL		3,857.20	2,899.60
	RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION)			2,300.00

Report Ref No. CC4/ASM20004781/Dga3q2

ANG BRYAN TANI

Automotive Assessor / Investigator

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.