

## LKK Auto Consultants Pte Ltd

(Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

## VEHICLE DAMAGE INSPECTION REPORT

**Our File No:** CC4/III20004784/KGA3Q2

**Date:** 16/07/2020

### REFERENCE

Handling Insurer: India International Insurance Pte Ltd	Policy No:	MCOM0015
<b>Claimant</b>		
<b>Vehicle No :</b> SMR2589G	<b>Insured Vehicle No :</b>	SHA6233E
Date of Loss: 29/03/2020	Nature of Claim: TP	Claim No: MCT20030499

### DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SMR2589G		
Make & Model:	AUDI A5, 2.0 SB TFSI S TRONIC (DESIGN) (A)	Engine No:	CVK051065
Reg. Date:	29/12/2017 (Man. Year: 2017)	Chassis No:	WAUZZZF52JA050332
Colour:	Metallic Black	Odometer:	27800 km
Engine Capacity:	1984 cc		
Market Value/New Car Price:	N/A		
Sum Insured (\$\$):	<b>Market Value/New Car Price</b>		

### CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

### CONDITION OF TYRES

Front Tyre Size:	275/30Z R20	Rear Tyre Size:	275/30Z R20
Front Left Side:	Michelin 8 mm	Rear Left Side:	Michelin 8 mm
Front Right Side:	Michelin 8 mm	Rear Right Side:	Michelin 8 mm

*The above values represent the remaining tyre treads depth*

<b>COST OF CLAIMS</b>	<b>Repairer's</b>	<b>Adjuster's</b>	<b>Difference</b>	<b>Diff %</b>
Parts	12,515.40	1,740.80	10,774.60	86.09
Miscellaneous Items	0.00	0.00	0.00	
Labour	2,690.00	700.00	1,990.00	73.98
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
<b>Calculated Gross Total (\$\$)</b>	<b>15,205.40</b>	<b>2,440.80</b>	<b>12,764.60</b>	<b>83.95</b>
<b>Approved Total (Overridden) (\$\$)</b>		<b>1,950.00</b>		
<b>(\$\$)</b>	15,205.40	1,950.00	13,255.40	87.18
<b>+ GST 7.00/7.00% (\$\$)</b>	1,064.38	136.50	927.88	87.18
<b>Nett Amount (\$\$)</b>	<b>16,269.78</b>	<b>2,086.50</b>	<b>14,183.28</b>	<b>87.18</b>
<b>+ Car Rental (3.0 x \$S180.00/day + 7.00% GST) (\$\$)</b>		577.80		
<b>Nett Liability (\$\$)</b>		<b>2,664.30</b>		
<b>Global Sum Settlement (\$\$)</b>		<b>2,650.00</b>		

### INSPECTION

Date of Assignment:	15/04/2020	
Date Inspected:	15/04/2020 Inspected At:	MBM Wheelpower Pte Ltd (HQ) 160 Sin Ming Drive #06-02, Sin Ming AutoCity Singapore 575722
Estimated Period of Repair:	3.0 days	

---

**Adjuster:** KENNETH KONG**Manager:** Chong Pui Lin

*NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.*

## REPAIR DETAILS

### Reference

<b>Part Source:</b>	MRM-SG	Version: 1.0 (Last Synchronised: 29 May 2020)
<b>Parts:</b>	143	AUDI A5 2.0 SB TFSI S TRONIC (DESIGN) (A) (Catalogue:Merimen Singapore 1.0)
<b>Labour:</b>	Repairer's	(Price-denominated Standard List)
<b>Print Code:</b>	(Unsubmitted, no print-code for SMR2589G)	
<b>Validity:</b>	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
<b>Further Info:</b>	Items/values not in reference catalogue are prefixed with an asterisk *.	

### Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FRONT BUMPER	Dented / Buckled	1,858.00 FL	*1,712.00 FL
2	10		*BUMPER CLIPS /RIVETS	Not Necessary	70.00 FL	*- FL
3	1		*FRONT BUMPER RH SIDE RETAINER	Serviceable	180.00 FL	*- FL
4	1		*FRONT BUMPER LOWER RH FOG LAMP COVER	Serviceable	290.00 FL	*- FL
5	1		*FRONT RH FENDER	Repair	890.00 FL	*- FL
6	1		*HEAD LAMP RH	Serviceable	3,618.00 FL	*- FL
7	1		*BODY SEALANT	Not Necessary	80.00 FS	*- FS
8	1		*VOSSEN RIM (LOCAL REPAIR)	Dented	5,800.00 FS	*200.00 FS
9	1		*TYRE -MICHELIN PS4	Serviceable	420.00 FS	*- FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

<b>Sub Total (S\$)</b>	<b>13,206.00</b>	<b>1,912.00</b>
<b>- List Item Discount on L Items 10.00/10.00% (S\$)</b>	690.60	171.20
<b>Total Parts (S\$)</b>	<b>12,515.40</b>	<b>1,740.80</b>

Report was unsubmitted during this print-out.

## Recommended Miscellaneous Items

There are no new miscellaneous items selected.

## Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<b><u>Labour Items</u></b>				
1	TO REMOVE,REFIT & REPAIR AFFECTED DAMAGED PARTS .INCLUDING TO KNOCK -OUT ,WELD & STRAIGHTEN ON THE AFFECTED PARTS	New	1,000.00	200.00
2	TO CONDUCT ALL WHEEL COMPUTERISED ALIGNMENT	New	100.00	60.00
3	TO RESET ENGINE WARNING LIGHT (ABS ,SRS,ECU MEMORY & ETC)	New	250.00	0.00
4	TO APPLY ANTI RUST COATING	New	150.00	0.00
5	TO REMOVE,REFIT & UPHOLSTERY TO FACILITATE REPAIRS	New	150.00	0.00
6	TO REMOVE & REPLACE BUMPER SENSORS	New	60.00	0.00
7	TO CHECK & RECONNECT ALL NECESSARY WIRING	New	80.00	0.00
8	TO SPRAY PAINT ON THE AFFECTED AREAS	New	900.00	440.00
<b>Gross Labour Cost (\$\$)</b>			<b>2,690.00</b>	<b>700.00</b>

Report was unsubmitted during this print-out.

< END OF ESTIMATES >