



## LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

### TAX INVOICE

SOMPO INSURANCE SINGAPORE PL  
50 RAFFLES PLACE  
#05-01/06  
SINGAPORE LAND TOWER  
SINGAPORE 048623

INV No. AC2003270  
INV Date 17/04/2020  
Reference CS/SMO20004787/Evd3n2  
Code SMO



### PROFESSIONAL SERVICE FEE

Vehicle No. SJN 7560L  
Insured Veh. SJJ 1101P  
Claim No. CMTD2001300/RUC  
Policy No.  
Accident Date 26/03/2020  
Inspection Date 02/04/2020

Description	Total
Survey Inspection	250.00
Resurvey Inspection	
Digital Photographs	
Transportation	
<b>Subtotal</b>	<b>250.00</b>
<b>GST (7%)</b>	<b>17.50</b>
<b>Grand Total</b>	<b>267.50</b>

We shall be glad if you could forward the payment at your early convenience.

Cheque should be crossed and made payable to **'LKK Auto Consultants Pte Ltd'**

LKK Auto Consultants Pte Ltd

*HYN*



## LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

### Affiliated to Federation Internationale Des Experts En Automobile

SOMPO INSURANCE SINGAPORE PL

Ref : CS/SMO20004787/Evd3n2

50 RAFFLES PLACE

#05-01/06

SINGAPORE LAND TOWERSINGAPORE 048623

Date : 17-04-2020



Code : SMO

### 1. Policy Particulars :- THIRD PARTY CLAIM

<b>Insured Veh.</b>	SJJ 1101P	<b>Veh. Inspected</b>	SJN 7560L
<b>Policy No.</b>		<b>Coverage (\$)</b>	0.00
<b>Claim No.</b>	CMTD2001300/RUC	<b>Excess (\$)</b>	0.00
<b>Assign From</b>	GRACE TEO	<b>Assign Date</b>	01/04/2020

### 2. Vehicle Particulars & Condition

<b>Make &amp; Model</b>	TOYOTA WISH	<b>c.c</b>	1794
<b>Engine No.</b>	HIDDEN	<b>Year of Reg.</b>	2009
<b>Chassis No.</b>	JTDER12WX03002002	<b>Colour</b>	BLUE
<b>Odometer</b>	411642	<b>Steering</b>	IN ORDER
<b>Brakes</b>	IN ORDER	<b>Modification</b>	SPORTS RIM
<b>General</b>	FAIR		

### 3. Conditions of Tyres

	<b>Size</b>	<b>Make</b>	<b>Balance</b>
<b>R/H Front Tyre</b>	205/55 R16	NEXEN	5 mm
<b>L/H Front Tyre</b>	205/55 R16	NEXEN	5 mm
<b>R/H Rear Tyre</b>	205/55 R16	NEXEN	5 mm
<b>L/H Rear Tyre</b>	205/55 R16	NEXEN	5 mm

### 4. Description of Damages

THE VEHICLE SUSTAINED DAMAGES AT THE REAR N/S PORTION.

DAMAGES SEE DETAILS.

### 5. General Information

<b>Accident Date</b>	26/03/2020	<b>Inspection Date</b>	02/04/2020
<b>Survey held at</b>	3 AMK STREET 62 #01-45		
<b>Repairer</b>	AUBURN AUTO PTE LTD		

### 5a. Remarks

A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS.  
B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.

### 5b. Estimate Days of Repair

<b>ESTIMATED NORMAL PERIOD FOR REPAIR:</b>	<b>2 Working Days</b>
--	-----------------------



# LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 2

## ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SJN 7560L

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	<b><u>REPLACEMENT OF PARTS</u></b>			
1	REAR L/H PANEL	NOT NECESSARY	1,100.00	-
1	REAR L/H PANEL MECHANISM	NOT NECESSARY	600.00	-
1	REAR L/H DOOR LOCK	NOT NECESSARY	280.00	-
1	REAR L/H PANEL WINDSCREEN SEAL	NOT NECESSARY	105.00	-
1	REAR L/H PANEL BUMPER	DENTED	1,200.00	500.30
2	REAR L/H PANEL BUMPER SIDE RETAINERS	BROKEN	250.00	144.20
1	REAR L/H PANEL BUMPER REFLECTORS	NOT NECESSARY	720.00	-
1	REAR L/H PANEL GARNISH	NOT NECESSARY	260.00	-
1	REAR L/H PANEL INNER GARNISH	NOT NECESSARY	350.00	-
1	RUBBER MOULDING	NOT NECESSARY	120.00	-
1	REAR L/H HEAD LIGHT	NOT NECESSARY	750.00	-
	LESS 25% DISCOUNT		-	-161.13
			5,735.00	483.37
	<b><u>SPECIAL NETT ITEMS</u></b>			
1	REAR L/H WINDSCREEN SEALANT (SN)	NOT NECESSARY	120.00	-
1	REAR L/H PANEL BUMPER CLIP (SN)	NECESSARY	150.00	30.00
			270.00	30.00
	<b><u>LABOUR</u></b>			
	REMOVE AND REFIT REAR R/H PANEL.	NOT NECESSARY	500.00	-
	REMOVE AND REFIT REAR R/H PANEL BUMPER.		300.00	200.00
	REMOVE,REFIT AND REPLACED DAMAGE AND CHECK UP REAR ELECTRICAL WIRING.		150.00	30.00
	REMOVE AND REFIT INNER GARNISHES TRIM TO ASSIST REPAIR.	NOT NECESSARY	200.00	-
	TO APPLY UNDERCOATING ON REPLACED PANEL.	NOT NECESSARY	120.00	-
	TO RESPRAY PAINTING.		1,400.00	200.00
			2,670.00	430.00
	<b>GRAND TOTAL</b>		<b>8,675.00</b>	<b>943.37</b>
	<b>RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION)</b>			<b>750.00</b>

Report Ref No. CS/SMO20004787/Evd3n2



Report Ref No. CS/SMO20004787/Evd3n2

A black ink signature of Chen Tsue Yee, consisting of a stylized 'C' followed by 'T' and 'Y'.

**CHEN TSUE YEE**

**Automotive Assessor**

A black ink signature of Ho Leong Chuan, featuring a stylized 'H' and 'L'.

**HO LEONG CHUAN**

**Automotive Assessor**

**DISCLAIMER OF LIABILITY TO THIRD PARTIES:-** This Report is made solely for the use and benefit of the Client named on the front page of this Report.

**No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.**



## LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

PHOTOGRAPHS FOR VEHICLE NO. SJN 7560L

INSPECTION







## LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





## LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





## LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

PHOTOGRAPHS FOR VEHICLE NO. SJN 7560L

RE-INSPECTION

