Page 1 of 5 Adjuster Report

#### LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

#### VEHICLE DAMAGE INSPECTION REPORT

AIG Asia Pacific Insurance Pte. Ltd.

Our File No: AIG Building, 78 Shenton Way, #09-16

Date: 01/09/2020 Singapore 079120

REFERENCE

Insured/Claimant: LI OU Policy No: 1700070039

Date of Loss: 26/03/2020 Nature of Claim: OD Claim No: 7135644851SG

**DESCRIPTION & IDENTIFICATION OF VEHICLE** 

**SLS2376K** Reg No:

AUDI A5, 2.0 SB TFSI S TRONIC (DESIGN) (A) Make & Model: Engine No: CVK043513

Reg. Date: 14/09/2017 (Man. Year: 2017) Chassis No: WAUZZZF50JA022089

Colour: Odometer: 40441 km Brown

**Engine Capacity:** 1984 cc Market Value/New Car Price: S\$129,000.00

Sum Insured (S\$): **Market Value/New Car Price** 

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Footbrake (Serviceable): Yes

Yes Engine Modification: Pre-accident Condition: Handbrake (Serviceable): No

CONDITION OF TYRES

Front Tyre Size: 245/40 R18 Rear Tyre Size: 245/40 R18 Front Left Side: Pirelli 5 mm Rear Left Side: Pirelli 5 mm Pirelli 5 mm Front Right Side: Pirelli 5 mm Rear Right Side:

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	14,629.00	4,763.00	9,866.00	67.44
Miscellaneous Items	0.00	0.00	0.00	
Labour	19,112.00	5,437.00	13,675.00	71.55
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Gross Total (S\$)	33,741.00	10,200.00	23,541.00	69.77
+ GST 7.00/7.00% (S\$)	2,361.87	714.00	1,647.87	69.77
Nett Amount (S\$)	36,102.87	10,914.00	25,188.87	69.77

**INSPECTION** 

Date of Assignment: 01/04/2020

Date Inspected: 01/04/2020 Inspected At: Premium Automobiles Pte Ltd (UBI)

> 55 Ubi Road 1 Singapore 408699

CC3/AIG20004789/EQF3E2

Estimated Period of Repair: 7.0 days

Adjuster: **CHEN TSUE YEE** Manager: SHIAU CHAN

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

Adjuster Report Page 2 of 5 Adjuster Report Page 3 of 5

(REPAIR COST NOT CONCLUDE) (EXCLUDE CHECK ITEMS \$\$1,256.00 NETT) Adjuster Report Page 4 of 5

# **REPAIR DETAILS**

# **Recommended Parts**

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*REAR BUMPER	Repair	2,385.00 FS	*- FS
2	1		*REAR BUMPER FIXING PARTS	* Check	156.00 FS	*- FS
3	1		*REAR BUMPER SECURING STRIP	* Check	210.00 FS	*- FS
4	1		*TRIM MOLDING	Not Necessary	958.00 FS	*- FS
5	1		*REAR LIGHT REFLECTOR - RH	Not Necessary	39.00 FS	*- FS
6	1		*REAR BUMPER GUIDE SECTION - RH	Not Necessary	41.00 FS	*- FS
7	1		*SIDE PANEL - RH	Repair	2,354.00 FS	*- FS
8	1		*SIDE WINDOW - RH	Not Necessary	676.00 FS	*- FS
9	1		*WHEEL HOUSING LINER - RH	Not Necessary	259.00 FS	*- FS
10	1		*WHEEL HOUSING LINER ATTACHMENT PARTS	Not Necessary	86.00 FS	*- FS
11	1		*REAR DOOR - RH	Dented	2,946.00 FS	*2,946.00 FS
12	1		*REAR DOOR OUTER SEAL - RH	Necessary	209.00 FS	*209.00 FS
13	1		*BONDING AGENT	Necessary	46.00 FS	*46.00 FS
14	1		*CLEANING SOLUTION	Necessary	64.00 FS	*64.00 FS
15	1		*REAR DOOR ATTACHMENT PARTS	* Check	122.00 FS	*- FS
16	1		*REAR DOOR CATCH	* Check	113.00 FS	*- FS
17	1		*DOOR HANDLE TRIM PLATE - RH	Missing	83.00 FS	*83.00 FS
18	1		*HANDLE BEZEL TRIM - RH	Cut	128.00 FS	*128.00 FS
19	1		*DOOR HANDLE SENSOR - RH	* Check	215.00 FS	*- FS
20	1		*EXTERIOR DOOR HANDLE - RH	* Check	40.00 FS	*- FS
21	1		*MOUNTING BAR - RH	Not Necessary	154.00 FS	*- FS
22	1		*SILL PANEL TRIM ATTACHMENT PARTS	Necessary	123.00 FS	*123.00 FS
23	1		*SILL PANEL TRIM ADHESIVE TAPES	Necessary	200.00 FS	*200.00 FS
24	1		*SIDE MEMBER TRIM - RH	Repair	778.00 FS	*- FS
25	1		*REAR ALUMINIUM RIM - RH	Cut	964.00 FS	*964.00 FS
26	1		*ACRYLIC SEALANT	Not Necessary	180.00 FS	*- FS
27	1		*CAVITY WAX	Not Necessary	140.00 FS	*- FS
28	1		*STONE CHIP	Not Necessary	180.00 FS	*- FS
29	1		*METAL FILLER POWDER	Not Necessary	280.00 FS	*- FS
30	1		*1/4 GLASS SEALANT	Not Necessary	100.00 FS	*- FS
31	1		*SUNDRIES	* Check	400.00 FS	*- FS
F=Fra	nchise	part. S=Spc	Nett.			
				Total Parts (S\$)	14,629.00	4,763.00

Report was unsubmitted during this print-out.

Adjuster Report Page 5 of 5

# Recommended Miscellaneous Items

There are no new miscellaneous items selected.

### Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labo	our Items			
1	TO REMOVE AND TRANSFER REAR PARKING AID AND REAR LID KICK SENSOR. CHECK FUNCTION AND RENEW ACCORDING TO DAMAGE	. New	360.00	360.00
2	TO RENEW 1/4 GLASS TO FACILITATE FENDER RENEWAL	New	300.00	0.00
3	TO INSTALL SOLAR FILM FOR 1/4 GLASS	New	400.00	0.00
4	TO REMOVE AND REINSTALL REAR SEAT, BACK REST, HAT TRAY, ABCD PILLAR TRIMS, LUGGAGE COMPARTMENT TRIMS. DISLODGE ROOF LINER AND DISENGAGE CURTAIN AIRBAG ETC	New	1,400.00	0.00
5	TO REMOVE AND TRF RHS REAR DOORS MULTI-LOCK SYSTEM AND POWER WINDOW DEVICES. INSPECT FOR DAMAGES	New	280.00	280.00
6	TO DISMANTLE AND RENEW REAR BUMPER, RHS REAR DOOR AND RHS SILL PANEL TRIM. CUT OUT AND WELD RHS REAR FENDER. RE-ORGANISE CRASH MANAGEMENT COMPONENTS. REINSTALL ALL PARTS REMOVED	New	7,200.00	1,750.00
7	TO RESPRAY REAR BUMPER, RHS REAR DOOR, DOOR HANDLE, RHS REAR FENDER, RHS SILL PANEL, DOOR ENTRANCES, ROOF CHANNEL, DRAIN PANEL, RHS SILL PANEL TRIM AND END PANELLING. TO CARRY OUT STONE CHIP TREATMENT AND JOINT SEALER WORKS	New	7,300.00	2,575.00
8	TO RENEW RHS REAR RIM AND CARRY OUT WHEEL ALIGNMENT	New	280.00	280.00
9	TO CARRY OUT DIAGNOSTIC CHECK	New	192.00	192.00
10	TO DISLODGE AND REINSTALL REAR WIRE HARNESS FOR LIGHTS, BATTERY MANAGER, FUSE AND RELAY TRAYS, ELECTRICAL AND AUDIO EQUIPMENT	New	1,400.00	0.00
	Gross Labour	r Cost (S\$)	19,112.00	5,437.00
	Report was unsubmitted during t	his print-out.		

< END OF ESTIMATES >