Adjuster Report Page 1 of 4

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS/CTI20004794/UYF3E2

Date: 11/05/2020

REFERENCE

China Taiping Insurance Handling Insurer:

(Singapore) Pte. Ltd.

Policy No: DMCVSN19166119000

Claimant Vehicle SKP6787J

Insured Vehicle No:

GBJ4294R

ΤP

No: Date of Loss:

28/03/2020

Nature of Claim:

Claim

SNM20D201564/GBJ4294R/CBS No:

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: **SKP6787J**

Make & Model: BMW 316I, 1.6 AT D/AB 4DR ABS HID (A) Engine No: A054J796N13B16A Reg. Date: 30/09/2014 (Man. Year: 2014) Chassis No: WBA3A12030J722244

Colour: Black

Odometer: 52015 km

Engine Capacity: 1598 cc

Market Value/New Car Price: N/A

Sum Insured (S\$): Market Value/New Car Price

CONDITION OF VEHICLE AT THE TIME OF SURVEY

Steering (Serviceable): Yes Footbrake (Serviceable): General Condition: Yes

Pre-accident Condition: Handbrake (Serviceable): Yes Engine Modification:

CONDITION OF TYRES

205/60 R16 Front Tyre Size: 205/60 R16 Rear Tyre Size: Front Left Side: Pirelli 6 mm Rear Left Side: Pirelli 6 mm Pirelli 6 mm Rear Right Side: Pirelli 6 mm Front Right Side:

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	2,223.00	900.00	1,323.00	59.51
Miscellaneous Items	327.97	202.97	125.00	38.11
Labour	255.50	42.00	213.50	83.56
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	2,806.47	1,144.97	1,661.50	59.20
Approved Total (Overridden) (S\$)		900.00		
(S\$)	2,806.47	900.00	1,906.47	67.93
+ GST 7.00/7.00% (S\$)	196.45	63.00	133.45	67.93
Nett Amount (S\$)	3,002.92	963.00	2,039.92	67.93

INSPECTION

01/04/2020 Present Location: Date of Assignment: Car City Auto Centre Pte Ltd (HQ) Date Inspected: 13/04/2020 Inspected At: Car City Auto Centre Pte Ltd (HQ)

Blk 9006 #01-198, Tampines Street 93

Singapore 528840

Estimated Period of Repair: 2.0 days Adjuster Report Page 2 of 4

Adjuster: MARCUS CHUA Manager: YVONNE WONG YIN CHENG

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

Adjuster Report Page 3 of 4

REPAIR DETAILS

Reference			
Part Source:	: MRM-SG	Version: 1.0 (Last Synchronised: 11 May 2020)	
Parts:	143	BMW 316I 1.6 AT D/AB 4DR ABS HID (A) (Catalogue:Merimen Singapore 1.0)	
Labour:	Repairer's	(Price-denominated Standard List)	
Print Code:	le: (Unsubmitted, no print-code for SKP6787J)		
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page		
Further Info: Items/values not in reference catalogue are prefixed with an asterisk *.			

Recommended Parts

No. Qty Part No.	Particulars	Condition	Repairer's	Amount	
1 1	*PARTS		2,223.00 F	*900.00 F	
F=Franchise part.		Total Parts (S\$)	2,223.00	900.00	
Report was unsubmitted during this print-out.					

Adjuster Report Page 4 of 4

Recommended Miscellaneous Items

No	Qty	Particulars		Repairer's	Amount
Miscellaneous Items					
1	1	EXTRAS		125.00	0.00
2	1	SPRAY PAINTING		202.97	202.97
			Sub Total (S\$)	327.97	202.97

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount		
Lab	Labour Items					
1	LABOUR	New	255.50	42.00		
		Gross Labour Cost (S\$)	255.50	42.00		
	Report was unsubmitted during this print-out.					

< END OF ESTIMATES >