

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

AIG Asia Pacific Insurance Pte. Ltd.
AIG Building, 78 Shenton Way, #09-16
Singapore 079120

Our File No: CC3/AIG20004807/EVF3E2

Date: 25/08/2020

REFERENCE

Insured/Claimant: MOHAMED HAZRIQ BIN HAMZAH SURATTEE Policy No: 1900148156
Date of Loss: 30/03/2020 Nature of Claim: OD Claim No: 2617876454SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: **SJB9998H**
Make & Model: AUDI Q2, 999cc 1.0 TFSI S TRONIC (A) Engine No: CHZC32402
Reg. Date: 28/08/2019 (Man. Year: 2019) Chassis No: WAUZZZGA9KA081249
Colour: Black Odometer: 8172 km
Engine Capacity: 999 cc
Market Value/New Car Price: S\$105,000.00
Sum Insured (\$\$): **Market Value/New Car Price**

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes
Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition: Yes

CONDITION OF TYRES

Front Tyre Size: 215/60 R16 Rear Tyre Size: 215/60 R16
Front Left Side: Bridgestone 6 mm Rear Left Side: Bridgestone 6 mm
Front Right Side: Bridgestone 6 mm Rear Right Side: Bridgestone 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	13,244.00	6,542.80	6,701.20	50.60
Miscellaneous Items	0.00	0.00	0.00	
Labour	5,552.00	2,402.00	3,150.00	56.74
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (\$\$)	18,796.00	8,944.80	9,851.20	52.41
- Excess (\$\$)	800.00	800.00	0.00	0.00
(\$\$)	17,996.00	8,144.80	9,851.20	54.74
+ GST 7.00/7.00% (\$\$)	1,259.72	570.14	689.58	54.74
Nett Amount (\$\$)	19,255.72	8,714.94	10,540.78	54.74

INSPECTION

Date of Assignment: 02/04/2020
Date Inspected: 02/04/2020 Inspected At: Premium Automobiles Pte Ltd (UBI)
55 Ubi Road 1
Singapore 408699
Estimated Period of Repair: 5.0 days

Adjuster: CHEN TSUE YEE

Manager: VERON CHEN

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FRONT BUMPER	Cut	1,763.00 FS	*1,410.40 FS
2	1		*FRONT BUMPER FIXING PARTS	Not Necessary	326.00 FS	*- FS
3	1		*FRONT BUMPER GRILLE - CENTRE	Not Necessary	186.00 FS	*- FS
4	1		*FRONT BUMPER AIR GUIDE GRILLE - LH	Broken	159.00 FS	*127.20 FS
5	1		*FRONT BUMPER END CAP - LH	Cracked	32.00 FS	*25.44 FS
6	1		*FRONT BUMPER SPOILER	Cracked	282.00 FS	*225.20 FS
7	1		*FRONT BUMPER CLOSING ELEMENT	Not Necessary	147.00 FS	*- FS
8	1		*WHEEL SPOILER - LH	Cut	32.00 FS	*25.44 FS
9	1		*FRONT BUMPER ADAPTER - LH	Necessary	34.00 FS	*26.72 FS
10	1		*RADIATOR GRILLE	Not Necessary	1,328.00 FS	*- FS
11	1		*RADIATOR GRILLE STRIKER PLATE	Not Necessary	117.00 FS	*- FS
12	1		*FRONT BUMPER CARRIER	Bent	646.00 FS	*516.80 FS
13	1		*FRONT BUMPER COVER	Not Necessary	95.00 FS	*- FS
14	1		*FRONT BUMPER FOAM FILLER PIECE	Not Necessary	73.00 FS	*- FS
15	1		*FRONT BUMPER GUIDE SECTION - LH	Not Necessary	34.00 FS	*- FS
16	1		*CAUTION SIGN STICKER	Not Necessary	13.00 FS	*- FS
17	1		*AIRCON STICKER	Not Necessary	7.00 FS	*- FS
18	1		*HORN - LH LOW TONE	Not Necessary	270.00 FS	*- FS
19	1		*SPRING SHACKLE - LH	Not Necessary	30.00 FS	*- FS
20	1		*FRONT FENDER - LH	Repair	1,079.00 FS	*- FS
21	1		*FRONT FENDER ATTACHMENT PARTS	Not Necessary	38.00 FS	*- FS
22	1		*FRONT FENDER BRACKET - LH	Not Necessary	45.00 FS	*- FS
23	1		*FRONT FENDER BRACKET - LH	Not Necessary	15.00 FS	*- FS
24	1		*FRONT FENDER BRACE - LH	Not Necessary	35.00 FS	*- FS
25	1		*WHEEL HOUSING LINER - LH	Not Necessary	185.00 FS	*- FS
26	1		*WHEEL HOUSING LINER ATTACHMENT PARTS	Not Necessary	54.00 FS	*- FS
27	2		*FRONT WHEEL COVER - LH / RH	Necessary	606.00 FS	*484.00 FS
28	1		*HEADLIGHT MOUNTING - LH	Not Necessary	112.00 FS	*- FS
29	1		*LED HEADLIGHT - LH	Cut	4,627.00 FS	*3,701.60 FS
30	1		*LIFT CYLINDER - LH	Not Necessary	134.00 FS	*- FS
31	1		*LIFT CYLINDER HOSE	Not Necessary	172.00 FS	*- FS
32	1		*WASH WATER RESERVOIR	Not Necessary	158.00 FS	*- FS
33	1		*RADIATOR AIR GUIDE - LH	Not Necessary	29.00 FS	*- FS
34	1		*RADIATOR AIR GUIDE - UPPER CENTRE	Not Necessary	21.00 FS	*- FS
35	1		*FRONT NO PLATE	Not Necessary	60.00 FS	*- FS
36	1		*SUNDRIES	Not Necessary	300.00 FS	*- FS

F=Franchise part. S=SpcNett.

Total Parts (\$\$) **13,244.00** **6,542.80**

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<u>Labour Items</u>				
1	TO REMOVE, CHECK AND REINSTALL FRONT WIRE HARNESS FOR HEADLIGHTS, HORNS, OUTSIDE TEMPERATURE SENSOR AND HEADLIGHT WASHER ASSY	New	360.00	360.00
2	TO DISMANTLE AND RENEW FRONT BUMPER, LHS FRONT FENDER AND LHS HEADLIGHT. RE-ORGANISE CRASH MANAGEMENT COMPONENTS. REINSTALL ALL PARTS REMOVED	New	2,800.00	750.00
3	TO RESPRAY FRONT BUMPER AND LHS FRONT FENDER	New	2,200.00	1,100.00
4	TO CARRY OUT DIAGNOSTIC CHECK	New	192.00	192.00
Gross Labour Cost (\$\$)			5,552.00	2,402.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >