



CYCLE & CARRIAGE

CYCLE & CARRIAGE AUTOMOTIVE PTE LIMITED PANDAN GARDENS CUSTOMER SERVICE CENTRE

209 Pandan Gardens Singapore 609339 Tel: 65684555 Fax: 65691056



Reg No : 197701469G

ESTIMATE

GST Reg No : MR-8500111-X

Invoice Name & Address	Owner Name & Vehicle Info	
Tan Wei-wen Paul (chen Weiwen, 12 Ang Mo Kio Avenue 2 #07-16 Singapore 567697 Contact No Mobile: 81336339	Cust No/Name	KCV07257/Tan Wei-Wen Paul (Chen Weiwen,P
	Reg No/Reg Date	SKT5832Y / 16/06/201
	Date In/Mileage	/ 0
	Chassis No	JMYSRCY1AFU004710
	Engine No	4A92BX6166
	Make/Model	MIT/LANCER EX 1.6 GLS 4A/T (F05)
	Colour/Trim	W03 / BK

Account No	Terms	Date/Time Printed	CSE	Operator	WIP No
CSM00041	Cash	01/04/2020/ 13:11	QUE	L261A/Edwin Caine	52686

Description of Goods / Services	Qty	Unit Price	Disc%	Amount
M SUNDRY SUPPLY RR NUMBER PLATE WITH CASING				80.00
M SUNDRY SUPPLY REVERSE SENSOR				220.00
E PNT88000 RENEW RR BUMPER REPAIR RR END PNL				1100.00
E PNT98000 RESPRAY RR BUMPER & RR END PNL				840.00
E PNT88000 REMOVE & REFIT RR FLR BOARD, TRIM & CARPET TO FACILITATE REPAIR				275.00
A 54900099 CHECK WIRING ELECTRICAL SYSTEM				50.00
A 10028901 TO CARRY OUT DIAGNOSTIC CHECK USING HI-SCAN PRO TEST USING HI-SCAN PRO TEST				200.00
E PNT88000 REMOVE & REFIT REVERSE SENSOR				100.00
M SUNDRY Sundries				50.00
M FACE, RR BUMPER	1.00	861.00	00.00	861.00
M BRKT, R/BMPR FACE SUPT, LH	1.00	17.00	00.00	17.00
M BRKT, R/BMPR FACE SUPT, RH	1.00	17.00	00.00	17.00
M CLIP, FR BUMPER	4.00	4.00	00.00	16.00
M CLIP, ENG ROOM COVER	4.00	2.00	00.00	8.00
M REINFORCEMENT, RR BUMPER	1.00	233.00	00.00	233.00

Estimate

SURVEYOR NAME: Tanflm 97495119
 SURVEYOR SIGNATURE: [Signature]
 DATE: 19/5/20 @ 11am

REMARKS: Resurvey after repair
03 days
Tanflm @ khawto.com

Nett	4,067.00
7% GST on	284.69
Total Payable	4,351.69

Confirm & accepted by _____
Authorized signatory and company stamp

Validity of this estimate is 14 days from date of quote. This is a computer generated document, no signature is required. Estimated costs quoted are excluding GST. We would mention that the above estimate is based on our initial inspection and does not include any additional parts or labour which may be required after repair work has commenced. Occasionally worn or damaged parts are discovered after work has started and needed for repairs or replacement. However, should this occur, we would advise you. Please be informed that a deposit of 50% of the above estimate is payable before commencement of the work. Payment for this may be made in cash, credit card or cheque. You must also agree to pay full amount for renewal of the windscreen in the event of inadvertent breakage in the course of renewing the rubber seal or other repair requiring the removal of the windscreen.