

**LKK Auto Consultants Pte Ltd**

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 1

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SKF 2517B

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	<u>REPLACEMENT OF PARTS</u>			
1	FRONT BUMPER	DEFORMED / TORN	2,155.95	2,155.95
1	FRONT BUMPER SIDE RETAINER N/S	NOT NECESSARY	85.00	-
1	FRONT BUMPER SPONGE	TORN	212.00	212.00
1	FRONT BUMPER REINFORCEMENT	TO REPAIR SEE LABOUR	754.00	-
1	FRONT BUMPER FOG LAMP GARNISH N/S	SCRATCHED	245.00	245.00
1	FRONT BUMPER PDC SENSOR N/S	SERVICEABLE	199.00	-
1	FRONT BUMPER NOZZLE COVER N/S	SERVICEABLE	35.00	-
1	FRONT BUMPER NOZZLE JET N/S	SERVICEABLE	195.00	-
1	HEADLAMP N/S	SCRATCHED	8,681.85	8,681.85
1	FRONT GRILLE	NOT NECESSARY	1,766.00	-
	LESS 5% DISCOUNT		-	-564.74
			14,328.80	10,730.06
	<u>LABOUR</u>			
	TO CHECK WIRING.		50.00	20.00
	TO R&R PDC SENSOR.		80.00	50.00
	TO REFILL AIR CON GAS.	NOT NECESSARY	120.00	-
	LABOUR FOR PANEL BEATING & REPLACING PARTS.INCLUSIVE OF THE REPAIR OF FRONT BUMPER REINFORCEMENT.		500.00	280.00
	TO PUTTY & SPRAY PAINTING.		500.00	250.00
			1,250.00	600.00
	GRAND TOTAL		15,578.80	11,330.06
	RECOMMENDED COST OF REPAIRS (CONFIRMED)			11,330.06

Report Ref No. CS/INC20004814/Uqd3n2

CHUA KANG SENG

Licensed Appraiser

K.K.LAU CPT(RET)**BEng(Hons),B.Bus,MBA,PEng,PE,
MInstAEA,MASME,MIRTE****REGD Auto Consultant-SAE, Licensed Appraiser**

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contact or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or replying on this Report, in whole or in part, does so at his or her own risk.