Adjuster Report Page 1 of 4

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CC4/AIG20004823/UGA3Q2

1KD1845109

Date: 28/07/2020

REFERENCE

Handling Insurer: AIG Asia Pacific Insurance Pte. Ltd. 1900160698 Policy No: Claimant **GBB1637Y** Insured Vehicle No: SGE1811K Vehicle No:

Date of Loss: ΤP 31/03/2020 Nature of Claim: Claim No: 5059180142SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

GBB1637Y Reg No:

TOYOTA DYNA 150 MANUAL 3SEATER, 3.0 D Make & Model: Engine No:

(M)

JTFAT35Y803001947 Reg. Date: 26/08/2008 (Man. Year: 2008) Chassis No:

Colour: White Odometer: 774088 km

Engine Capacity: 2982 cc Market Value/New Car N/A

Price:

Market Value/New Car Price Sum Insured (S\$):

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes

Handbrake (Serviceable): Yes Engine Modification: Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 195 R15 Rear Tyre Size: 155 R12C Front Left Side: Rear Left Side: Dunlop 5/5 mm Michelin 5 mm Front Right Side: Rear Right Side: Dunlop 5/5 mm Michelin 5 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS		Repairer's	Adjuster's	Difference	Diff %
Parts		2,606.82	1,326.74	1,280.08	49.11
Miscellaneous Items		0.00	0.00	0.00	
Labour		1,790.00	1,230.00	560.00	31.28
Paintwork Labour		0.00	0.00	0.00	
Towing		0.00	0.00	0.00	
	Calculated Gross Total (S\$)	4,396.82	2,556.74	1,840.08	41.85
	Approved Total (Overridden) (S\$)		2,000.00		
	(S\$)	4,396.82	2,000.00	2,396.82	54.51
	+ GST 7.00/7.00% (S\$)	307.78	140.00	167.78	54.51
	Nett Amount (S\$)	4,704.60	2,140.00	2,564.60	54.51
	+ Car Rental (6.0 x S\$100.00/day + 7.	00% GST) (S\$)	642.00		
	+ Doc/S	earch Fee (S\$)	8.00		
	Ne	tt Liability (S\$)	2,790.00		
	Global Sum S	Settlement (S\$)	2,750.00		

INSPECTION

Date of Assignment: 02/04/2020

Date Inspected: 02/04/2020 Inspected At: Precise Auto Service (HQ)

No 1 Kaki Bukit Ave 6, #02-34/36

Singapore 417883

Estimated Period of Repair: 5.0 days Adjuster Report Page 2 of 4

Adjuster: MARCUS CHUA Manager: Chong Pui Lin

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

Adjuster Report Page 3 of 4

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*TAIL LAMP	O/S Cracked	576.80 FL	*288.40 FL
2	1		*TAIL LAMP BRACKET	O/S Bent	363.40 FL	*181.70 FL
3	1		*TAIL GATE STICKER TOYOTA	Necessary	160.75 FL	*160.75 FL
4	1		*TAIL GATE RUBBER STOPPER	O/S Cut	91.80 FL	*45.90 FL
5	1		*TAIL GATE RUBBER STOPPER BRACKET	O/S Bent	303.00 FL	*151.50 FL
6	1		*TAIL GATE SIDE LOCK	O/S Bent	363.50 FL	*181.75 FL
7	2		*TAIL GATE SIDE LOCK BRACKET	No such part	322.20 FL	*- FL
8	2		*REAR NUMBER PLATE LAMP	Not Necessary	242.00 FL	*- FL
9	1		*REAR NUMBE PLATE BRACKET	Bent	182.55 FL	*182.55 FL
10	1		*SPARE TYRE CARRIER	Damaged / Jammed	263.10 FL	*263.10 FL
11	1		*SET REVERSE SENSOR	Shorted	380.00 FS	*200.00 FS
12	1		*REAR NUMBER PLATE	Bent	45.00 FS	*15.00 FS
13	1		*70KM/H STICKER	Necessary	15.00 FS	*10.00 FS
14	1		*13 PAX STICKER	Necessary	15.00 FS	*10.00 FS
F=Fra	anchise	part. S=Spc	Nett. L=ListItemDisc.			
				Sub Total (S\$)	3,324.10	1,690.65
	- List Item Discount on L Items 25.00/25.00% (S\$)				717.28	363.91
				Total Parts (S\$)	2,606.82	1,326.74

Report was unsubmitted during this print-out.

Adjuster Report Page 4 of 4

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Lab	our Items			
1	TO CHECK WIRING SYSTEM	New	80.00	20.00
2	TO TUFF COAT AFFECTED AREAS	New	120.00	0.00
3	TO REMOVE & REFIX SPARE TYRE CARRIER	New	120.00	0.00
4	TO RESPRAY AFFECTED AREAS	New	650.00	580.00
5	TO RENEW DAMAGED PARTS ,STRAIGHTEN & REPAIR TAIL GATE ,TAIL GATE LOWER PANEL & ALIGNED ALL PARTS	New	700.00	580.00
6	TO REMOVE & REFIX REVERSE SENSOR	New	120.00	50.00
	Gross Labour Cost (S\$)		1,790.00	1,230.00
	Report was unsubmitted duri	na this print-out.		

< END OF ESTIMATES >