

LKK Auto Consultants Pte Ltd

(Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CC4/FWD20004824/BEA3Q2

Date: 19/04/2021

REFERENCE

Handling Insurer: FWD Singapore Pte. Ltd. Policy No: PNCV2018-00000558-01

Claimant
Vehicle No : SMG6023D **Insured Vehicle No :** SLV3908D

Date of Loss: 30/03/2020 Nature of Claim: TP Claim No: 1202000015668

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SMG6023D		
Make & Model:	TOYOTA PRIUS PLUS, 1.8 (A)	Engine No:	2ZR0C65192
Reg. Date:	26/12/2018 (Man. Year: 2018)	Chassis No:	JTDZS3EUX0J034858
Colour:	Black	Odometer:	112991 km
Engine Capacity:	1798 cc		
Market Value/New Car Price:	N/A		
Sum Insured (\$\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	205/60 R16	Rear Tyre Size:	205/60 R16
Front Left Side:	Firenza 6 mm	Rear Left Side:	Firenza 6 mm
Front Right Side:	Firenza 6 mm	Rear Right Side:	Firenza 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	2,153.80	1,002.80	1,151.00	53.44
Miscellaneous Items	0.00	0.00	0.00	
Labour	1,620.00	590.00	1,030.00	63.58
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (\$\$)	3,773.80	1,592.80	2,181.00	57.79
Approved Total (Overridden) (\$\$)		1,300.00		
(\$\$)	3,773.80	1,300.00	2,473.80	65.55
+ GST 7.00/7.00% (\$\$)	264.17	91.00	173.17	65.55
Nett Amount (\$\$)	4,037.97	1,391.00	2,646.97	65.55
+ Loss of Use (4.0 x S\$80.00/day) (\$\$)		320.00		
+ Doc/Search Fee (\$\$)		7.45		
Nett Liability (\$\$)		1,718.45		

INSPECTION

Date of Assignment: 02/04/2020

Date Inspected: 02/04/2020 Inspected At:

My Car Consultant Pte Ltd - Ubi (HQ)
53 Ubi Ave 1, #01-33 Paya Ubi
Industrial Park
Singapore 408934

Estimated Period of Repair: 4.0 days

Adjuster: Lim Teow Guan**Manager:** Asher Sng Rong Yi

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference

Part Source:	MRM-SG	Version: 1.0 (Last Synchronised: 09 Apr 2021)
Parts:	M1-MPV	TOYOTA PRIUS PLUS 1.8 (A) (Catalogue:Merimen Singapore 1.0)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SMG6023D)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*REAR BUMPER	Cut	610.40 FL	*523.90 FL
2	1		*REAR BUMPER SIDE RETAINER LH }	Necessary	113.60 FL	*98.00 FL
3	1		*REAR BUMPER SIDE RETAINER RH }	Necessary	113.60 FL	*98.00 FL
4	1		*REAR BUMPER REINFORCEMENT	Dented	310.50 FL	*310.50 FL
5	1		*REAR BUMPER BRACKET LH	Not Damaged	115.30 FL	*- FL
6	1		*REAR BUMPER BRACKET RH	Not Damaged	115.30 FL	*- FL
7	1		*REAR BUMPER LIP	Not Damaged	718.50 FL	*- FL
8	1		*REAR BUMPER REFLECTOR LH	Not Damaged	80.60 FL	*- FL
9	1		*REAR BUMPER REFLECTOR RH	Not Damaged	80.60 FL	*- FL
10	1		*SET REAR REVERSE SENSOR	Scratched	250.00 FS	*200.00 FS
11	1		*SET REAR BUMPER CLIP	Necessary	80.00 FS	*30.00 FS
12	1		*SET REAR END PANEL GARNISH CLIP	Not Necessary	30.00 FS	*- FS
13	1		*FLOOR PANEL SEALANT	Not Necessary	50.00 FS	*- FS
14	1		*END PANEL SEALANT	Not Necessary	50.00 FS	*- FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (\$\$)	2,718.40	1,260.40
- List Item Discount on L Items 25.00/25.00% (\$\$)	564.60	257.60
Total Parts (\$\$)	2,153.80	1,002.80

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<u>Labour Items</u>				
1	TO CHECK ELECTRICAL WIRING	New	50.00	30.00
2	TO REMOVE AND REFIT REVERSE SENSOR	New	150.00	60.00
3	TO RESPRAY UNDERCOATING	New	100.00	50.00
4	APPLY ANTI-RUST ON AFFECTED AREAS	New	120.00	50.00
5	SPRAY PAINTING ON AFFECTED AREAS	New	600.00	200.00
6	PANEL BEATING ON AFFECTED AREAS	New	600.00	200.00
Gross Labour Cost (\$)			1,620.00	590.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >