

## LKK Auto Consultants Pte Ltd

(Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

## VEHICLE DAMAGE INSPECTION REPORT

**Our File No:** CC4/III20004826/UBA3Q2

**Date:** 12/11/2020

### REFERENCE

Handling Insurer: India International Insurance Pte Ltd	Policy No:	MCOM0015
<b>Claimant</b>		
<b>Vehicle No :</b> SJJ1121G	<b>Insured Vehicle No :</b>	SHC2823T
Date of Loss: 20/03/2020	Nature of Claim: TP	Claim No: MCT20030347

### DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SJJ1121G		
Make & Model:	MAZDA 6, 2.5 SEDAN PREMIUM EU6 (A)	Engine No:	PY20961943
Reg. Date:	29/09/2017 (Man. Year: 2017)	Chassis No:	JM6GL1031H0124169
Colour:	Red	Odometer:	22049 km
Engine Capacity:	2488 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	<b>Market Value/New Car Price</b>		

### CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

### CONDITION OF TYRES

Front Tyre Size:	225/45R19	Rear Tyre Size:	225/45R19
Front Left Side:	Bridgestone 6 mm	Rear Left Side:	Bridgestone 6 mm
Front Right Side:	Bridgestone 6 mm	Rear Right Side:	Bridgestone 6 mm

*The above values represent the remaining tyre treads depth*

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	3,523.30	2,844.30	679.00	19.27
Miscellaneous Items	0.00	0.00	0.00	
Labour	4,440.00	2,255.00	2,185.00	49.21
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
<b>Gross Total (S\$)</b>	<b>7,963.30</b>	<b>5,099.30</b>	<b>2,864.00</b>	<b>35.96</b>
<b>+ GST 7.00/7.00% (S\$)</b>	557.43	356.95	200.48	35.97
<b>Nett Amount (S\$)</b>	<b>8,520.73</b>	<b>5,456.25</b>	<b>3,064.48</b>	<b>35.96</b>
<b>+ Loss of Use (4.0 x S\$100.00/day) (S\$)</b>		400.00		
<b>Nett Liability (S\$)</b>		<b>5,856.25</b>		

### INSPECTION

Date of Assignment:	02/04/2020	
Date Inspected:	19/06/2020	Inspected At:
		Trans Eurokars Pte Ltd (Ubi)
		5 Ubi Close
		Singapore 408605
Estimated Period of Repair:	4.0 days	

**Adjuster:** MARCUS CHUA

**Manager:** CHUA ZHEN LI

*NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.*

## REPAIR DETAILS

### Reference

<b>Part Source:</b>	MRM-SG	Version: 1.0 (Last Synchronised: 10 Sep 2020)
<b>Parts:</b>	143	MAZDA 6 2.5 SEDAN PREMIUM EU6 (A) (Catalogue:Merimen Singapore 1.0)
<b>Labour:</b>	Repairer's	(Price-denominated Standard List)
<b>Print Code:</b>	(Unsubmitted, no print-code for SJJ1121G)	
<b>Validity:</b>	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
<b>Further Info:</b>	Items/values not in reference catalogue are prefixed with an asterisk *.	

### Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FRONT BUMPER	Cut	1,211.90 FS	*1,211.90 FS
2	1		*RETAINER RHS	Not Necessary	17.10 FS	*- FS
3	1		*CHROME RHS,FOGLAMP	Not Necessary	101.90 FS	*- FS
4	6		*CLIP,FRONT BUMPER	Necessary	22.20 FS	*22.20 FS
5	2		*FASTENER,FRONT BUMPER	Necessary	6.00 FS	*6.00 FS
6	2		*GROMMET,FRONT BUMPER	Necessary	5.80 FS	*5.80 FS
7	6		*FASTENER,FRONT BUMPER	Necessary	19.20 FS	*19.20 FS
8	6		*RIVET,FRONT BUMPER	Necessary	29.40 FS	*29.40 FS
9	8		*RIVET,FRONT BUMPER	Necessary	32.00 FS	*32.00 FS
10	1		*FRONT WHEEL RIM RHS	Deep Cut	1,497.80 FS	*1,497.80 FS
11	1		*TIRE	Not Necessary	480.00 FS	*- FS
12	1		*SUNDRIES	Necessary	100.00 FS	*20.00 FS

F=Franchise part. S=SpcNett.

<b>Total Parts (S\$)</b>	<b>3,523.30</b>	<b>2,844.30</b>
--------------------------	-----------------	-----------------

Report was unsubmitted during this print-out.

## Recommended Miscellaneous Items

There are no new miscellaneous items selected.

## Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<b><u>Labour Items</u></b>				
1	TO REPLACE FRONT BUMPER.TO REPAIR FRONT FENDER RH AND ALL AREAS AFFECTED BY THE ACCIDENT	New	1,320.00	660.00
2	TO RESPRAY FRONT BUMPER AND FRONT FENDER RH	New	1,260.00	945.00
3	TO TRANSFER FRONT PEDESTRIAN SENSORS	New	330.00	180.00
4	TO MOUNT SPORT RIM AND CONDUCT WHEEL BALANCING	New	120.00	0.00
5	TO CHECK STEERING GEOMETRY & CONDUCT FULL WHEEL ALIGNMENT	New	560.00	200.00
6	TO CARRY-OUT BODY CAVITY PRESERVATION	New	250.00	0.00
7	TO CHECK ELECTRICAL SYSTEM FOR PROPER FUNCTIONING	New	250.00	120.00
8	TO REPROGRAMME AFTER THE ACCIDENT REPAIR WORKS	New	350.00	150.00
<b>Gross Labour Cost (S\$)</b>			<b>4,440.00</b>	<b>2,255.00</b>

Report was unsubmitted during this print-out.

< END OF ESTIMATES >