

## LKK Auto Consultants Pte Ltd

(Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

## VEHICLE DAMAGE INSPECTION REPORT

**Our File No:** CS3/AIG20004828/BSD3E2

**Date:** 03/08/2020

### REFERENCE

Handling Insurer:	AIG Asia Pacific Insurance Pte. Ltd.	Policy No:	1900167425
<b>Claimant Vehicle No :</b>	FE1013J	<b>Insured Vehicle No :</b>	SMP4083X
Date of Loss:	27/03/2020	Nature of Claim:	TP
		Claim No:	0668113356SG

### DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	<b>FE1013J</b>		
Make & Model:	YAMAHA CZD300A / XMAX300, 292cc	Engine No:	H336E0043308
Reg. Date:	14/11/2018 (Man. Year: 2018)	Chassis No:	MH3SH0849KK005053
Colour:	Grey	Odometer:	0 km
Engine Capacity:	292 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	<b>Market Value/New Car Price</b>		

### CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

### CONDITION OF TYRES

Front Tyre Size:	120/70 R17	Rear Tyre Size:	180/60 R17
Front Left Side:	Michelin 2 mm	Rear Left Side:	Michelin 2 mm
Front Right Side:	0 mm	Rear Right Side:	0 mm

*The above values represent the remaining tyre treads depth*

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	0.00	0.00	0.00	
Miscellaneous Items	0.00	0.00	0.00	
Labour	0.00	0.00	0.00	
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
<b>Nett Amount (S\$)</b>	<b>0.00</b>	<b>0.00</b>	<b>0.00</b>	

### INSPECTION

Date of Assignment:	02/04/2020	
Date Inspected:	03/04/2020 Inspected At:	Funmasters Promotion (motor Division) (HQ) Blk 176 Sin Ming Drive #03-21 Sin Ming Autocare Singapore 575721
Estimated Period of Repair:	6.0 days	

**Adjuster:** Lim Teow Guan

**Manager:** DENISE TAY KWEE CHENG

*NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.*



## REPAIR DETAILS

### Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FRONT NUMBER PLATE	Broken	0.00 F	*- F
2	1		*FRONT FENDER WHEEL GUARD	Broken	0.00 F	*- F
3	2		*FRONT FORK ASSY	Bent	0.00 F	*- F
4	1		*FRONT FORK BRACKET	Bent	0.00 F	*- F
5	1		*FRONT FORK OIL SEAL	Necessary	0.00 F	*- F
6	1		*FRONT HEADLAMP	Dislodged	0.00 F	*- F
7	1		*FRONT HEADLAMP FAIRING	Broken	0.00 F	*- F
8	1		*FRONT WINDSHIELD	Broken	0.00 F	*- F
9	2		*FRONT WING MIRROR	Cut	0.00 F	*- F
10	1		*FRONT LH SIGNAL LAMP	Broken	0.00 F	*- F
11	1		*FRONT RH SIGNAL LAMP	Broken	0.00 F	*- F
12	1		*METER CASING	Broken	0.00 F	*- F
13	1		*METER ASSY	Dislodged	0.00 F	*- F
14	1		*ERP BRACKET	Bent	0.00 F	*- F
15	1		*COWLING STAY	Bent	0.00 F	*- F
16	1		*STEERING STEM	Bent	0.00 F	*- F
17	1		*STEERING CONE	Necessary	0.00 F	*- F
18	1		*HANDLE BAR	Bent	0.00 F	*- F
19	1		*HANDLE BAR GRIP	Cut	0.00 F	*- F
20	1		*HANDLE BAR BALANCER LH	Cut	0.00 F	*- F
21	1		*HANDLE BAR BALANCER RH	Cut	0.00 F	*- F
22	1		*CLUTCH LEVER	Broken	0.00 F	*- F
23	1		*HAND BRAKE LEVER	Broken	0.00 F	*- F
24	1		*SIDE FAIRING	Broken	0.00 F	*- F
25	1		*SIDE FAIRING TOP GARNISH	Cut	0.00 F	*- F
26	1		*FAIRING SHIELD	Broken	0.00 F	*- F
27	1		*FRONT TOP FAIRING INNER GARNISH	Dislodged	0.00 F	*- F
28	1		*CENTER FAIRING	Broken	0.00 F	*- F
29	1		*REAR FAIRING	Cut	0.00 F	*- F
30	1		*FAIRING LOWER	Broken	0.00 F	*- F
31	1		*RADIATOR COWLING	Broken	0.00 F	*- F
32	1		*EXHAUST MUFFLER HEAT SHIELD	Broken	0.00 F	*- F
33	1		*REAR NUMBER PLATE	Bent	0.00 F	*- F
34	1		*HELMET	Cut	0.00 F	*- F

F=Franchise part.

**Total Parts (\$\$)**
**0.00**
**0.00**

Report was unsubmitted during this print-out.

## Recommended Miscellaneous Items

There are no new miscellaneous items selected.

## Recommended Labour

There are no labour items selected.

Report was unsubmitted during this print-out.
---

**< END OF ESTIMATES >**