

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CC4/AIG20004829/UGA3Q2

Date: 05/04/2021

REFERENCE

Handling Insurer: AIG Asia Pacific Insurance Pte. Ltd.	Policy No:	1800033306
Claimant		
Vehicle No : SJN7738S	Insured Vehicle No :	SLX5752L
Date of Loss: 30/03/2020	Nature of Claim: TP	Claim No: 2300784633SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SJN7738S		
Make & Model:	TOYOTA WISH, 1.8 CVT (A)	Engine No:	2ZRA649256
Reg. Date:	25/01/2011 (Man. Year: 2010)	Chassis No:	JTDGG20W205001485
Colour:	Blue	Odometer:	210354 km
Engine Capacity:	1798 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	195/65R15	Rear Tyre Size:	195/65R15
Front Left Side:	CST 6 mm	Rear Left Side:	CST 6 mm
Front Right Side:	CST 6 mm	Rear Right Side:	CST 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	3,645.50	2,255.27	1,390.23	38.14
Miscellaneous Items	0.00	0.00	0.00	
Labour	2,020.00	900.00	1,120.00	55.45
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	5,665.50	3,155.27	2,510.23	44.31
Approved Total (Overridden) (S\$)		2,500.00		
(S\$)	5,665.50	2,500.00	3,165.50	55.87
+ GST 7.00/7.00% (S\$)	396.59	175.00	221.59	55.87
Nett Amount (S\$)	6,062.09	2,675.00	3,387.09	55.87
+ Car Rental (4.0 x S\$150.00/day) (S\$)		600.00		
+ Doc/Search Fee (S\$)		31.00		
Nett Liability (S\$)		3,306.00		
Global Sum Settlement (S\$)		3,300.00		

INSPECTION

Date of Assignment:	02/04/2020	
Date Inspected:	02/04/2020 Inspected At:	Focus Auto Pte Ltd (HQ) 1 Kaki Bukit Ave 6, #02-48/50 Autobay Singapore 417883
Estimated Period of Repair:	3.0 days	

Adjuster: MARCUS CHUA

Manager: Chong Pui Lin

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount	
1	1		*FRONT HEADLAMP -LH	Cracked	950.00 FL	*950.00 FL	
2	1		*FRONT FENDER -LH	Dented / Bent	689.20 FL	*689.20 FL	
3	1		*FRONT FENDER DUST COVER -LH	Torn	146.40 FL	*146.40 FL	
4	6		*FRONT FENDER DUST COVER CLIPS-LH	Necessary	33.00 FL	*33.00 FL	
5	1		*FRONT BUMPER	Cut	810.00 FL	*655.10 FL	
6	1		*FRONT BUMPER SIDE RETAINER-LH	Not Necessary	68.20 FL	*- FL	
7	1		*FRONT SHOCK ABSORBER -LH	Not Necessary	346.40 FL	*- FL	
8	1		*FRONT KNUCKLE ARM -LH	Not Necessary	378.20 FL	*- FL	
9	1		*FRONT LOWR ARM -LH	Not Necessary	326.40 FL	*- FL	
10	1		*FRONT HUB BEARING -LH	Not Necessary	246.20 FL	*- FL	
11	1		*SPORT RIM-LH	Cut	650.00 FS	*400.00 FS	
					Sub Total (\$\$)	4,644.00	2,873.70
					- List Item Discount on L Items 25.00/25.00% (\$\$)	998.50	618.43
					Total Parts (\$\$)	3,645.50	2,255.27

F=Franchise part. S=SpcNett. L=ListItemDisc.

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	PANEL BEATING	New	850.00	400.00
2	CHECK WIRING	New	60.00	20.00
3	RUST PROOFING	New	60.00	30.00
4	ALIGNMENT	New	50.00	50.00
5	TO REMOVE & REPLACE FRONT UNDER CARRIAGE	New	280.00	0.00
6	TO SPRAY PAINTING	New	720.00	400.00
			Gross Labour Cost (\$)	900.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >