

LKK Auto Consultants Pte Ltd

(Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Lonpac Insurance Bhd
300 Beach Road, #17-04/07 The Concourse
Singapore 199555

Our File No: CS/LPC20004833/R1TF3E2

Date: 21/05/2020

REFERENCE

Insured/Claimant: FONG SHENG LOGISTIC PTE LTD Policy No: Z/19/VC00/105187

Date of Loss: 27/03/2020

Nature of Claim: OD

Claim No: 19/20/20/VC00/023269

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	XD7979A		
Make & Model:	MITSUBISHI FUSO, 12.0 D FV51SJD2DEA (M)	Engine No:	OM457LA457972C0284755
Reg. Date:	23/10/2014 (Man. Year: 2014)	Chassis No:	FV51SJA10033
Colour:	Green	Odometer:	0 km
Engine Capacity:	11967 cc		
Market Value/New Car Price:	S\$60,000.00		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	295/80 R22.5	Rear Tyre Size:	295/80 R22.5 (D)
Front Left Side:	TAITONG 8 mm	Rear Left Side:	TAITONG 8/8 mm
Front Right Side:	TAITONG 8 mm	Rear Right Side:	TAITONG 8/8 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	56,331.10	47,704.60	8,626.50	15.31
Miscellaneous Items	0.00	0.00	0.00	
Labour	5,600.00	3,750.00	1,850.00	33.04
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	61,931.10	51,454.60	10,476.50	16.92
Approved Total (Overridden) (S\$)		41,150.00		
- Excess (S\$)	0.00	2,000.00	-2,000.00	
(S\$)	61,931.10	39,150.00	22,781.10	36.78
+ GST 7.00/7.00% (S\$)	4,335.18	2,740.50	1,594.68	36.78
Nett Amount (S\$)	66,266.28	41,890.50	24,375.78	36.78

INSPECTION

Date of Assignment: 02/04/2020

Date Inspected: 02/04/2020 Inspected At:

15 FAN YOONG RD

Repairer : Mova Automotive Pte Ltd

Estimated Period of Repair: 8.0 days

Adjuster: MOHD RASUL**Manager:** DENISE TAY KWEE CHENG

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference		
Part Source:	(Last Synchronised: 20 May 2020)	
Parts:	N/A	MITSUBISHI FUSO 12.0 D FV51SJD2DEA (M) (Model not available in database)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for XD7979A)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FRONT WINDSCREEN GLASS (WCP)	Broken	1,500.00 F	*1,500.00 F
2	1		*FRONT WINDSCREEN MOULDING (WCP)	Necessary	350.00 F	*350.00 F
3	1		*WIPER ARM (3PCS)(WCP)	Bent (2Pcs Only)	750.00 F	*500.00 F
4	1		*WIPER LINKAGE ASSY (WCP)	Serviceable	850.00 F	*- F
5	1		*WIPER PANEL (WCP)	Repair	480.00 F	*- F
6	1		*FRONT PANEL (WCP)	Bent	2,800.00 F	*2,800.00 F
7	2		*FRONT PANEL HINGE (WCP)	Serviceable	140.00 F	*- F
8	1		*FRONT PANEL (FUSO) EMBLEM (WCP)	Necessary	180.00 F	*180.00 F
9	2		*FRONT PANEL GRILLE (WCP)	Serviceable	1,200.00 F	*- F
10	1		*FRONT BUMPER TOP (WCP)	Broken	250.00 F	*250.00 F
11	1		*FRONT BUMPER LOWER (WCP)	Bent	1,300.00 F	*1,300.00 F
12	1		*FRONT BUMPER LH & RH (WCP)	N/S Broken / O/S Serviceable	300.00 F	*150.00 F
13	1		*FRONT BUMPER COVER LH (WCP)	N/S Broken / O/S Serviceable	300.00 F	*150.00 F
14	1		*FRONT BUMPER CENTER BRACKET (WCP)	Serviceable	1,050.00 F	*- F
15	1		*FRONT BUMPER LH & RH BRACKET (WCP)	N/S Bent / O/S Serviceable	600.00 F	*300.00 F
16	1		*HEADLAMP LH (WCP)	Broken	800.00 F	*800.00 F
17	1		*SMALL LAMP LH (WCP)	Broken	300.00 F	*300.00 F
18	1		*SIGNAL LAMP LH (WCP)	Broken	160.00 F	*160.00 F
19	1		*FRONT CORNER PANEL LH (WCP)	Cracked	550.00 F	*550.00 F
20	1		*FRONT CORNER PANEL BRACKET LH (WCP)	Serviceable	140.00 F	*- F
21	1		*FRONT SIDE MIRROR BRACKET LH (WCP)	Bent	1,100.00 F	*1,100.00 F
22	1		*FRONT SIDE MIRROR BRACKET SUPPORT (2PCS)(WCP)	Bent (1Pc Only)	600.00 F	*300.00 F
23	2			Cracked	360.00 F	*360.00 F

Report was unsubmitted during this print-out.

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
			*FRONT SIDE MIRROR (WCP)			
24	1		*FRONT SIDE ROUND MIRROR LH (WCP)	Cracked	110.00 F	*110.00 F
25	1		*FRONT WHEEL ARCH LH (WCP)	Deformed	210.00 F	*210.00 F
26	1		*FRONT WHEEL ARCH BLADE GARNISH LH (WCP)	Broken	950.00 F	*950.00 F
27	1		*FRONT STEP PANEL LH (WCP)	Broken	750.00 F	*750.00 F
28	1		*FRONT STEP PANEL BOTTOM LH (WCP)	Broken	600.00 F	*600.00 F
29	3		*FRONT STEP PLATE (WCP)	Broken	714.00 F	*714.00 F
30	1		*FRONT STEP SUPPORT BAR LH (WCP)	Bent	780.00 F	*780.00 F
31	1		*CONDENSER (WCP)	Bent	1,340.00 F	*1,340.00 F
32	1		*CONDENSER BRACKET (WCP)	Bent	580.00 F	*580.00 F
33	2		*CONDENSER AIR CON PIPE (WCP)	Bent	400.00 F	*400.00 F
34	1		*CONDENSER FAN MOTOR (WCP)	Shorted	900.00 F	*900.00 F
35	1		*CONDENSER FAN BLADE (WCP)	Broken	220.00 F	*220.00 F
36	1		*CONDENSER FAN COWLING (WCP)	Broken	190.00 F	*190.00 F
37	1		*LH FRONT DOOR PILLAR (WCP)	Repair	2,800.00 F	*- F
38	1		*FRONT BUMPER CENTER STEP GARNISH (WCP)	Broken	160.00 F	*160.00 F
39	1		*DASHBOARD TOP (WCP)	Cut	2,500.00 F	*2,500.00 F
40	1		*TOWING TO FAN YOONG		350.00 FS	*300.00 FS
41	1		*LH FRONT TYRE (70%)	Punctured	600.00 FS	*420.00 FS
42	1		*FRONT NUMBER PLATE	Bent	50.00 FS	*35.00 FS
43	1		*FRONT IU BRACKET	Necessary	25.00 FS	*25.00 FS
Supplementary #1						
44	2		*FRONT UNDERCARRIAGE LIFT SPRING SUSPENSION ASSY (SET) (WCP)	Bent	3,600.00 FS	*3,600.00 F
45	4		*LIFT SPRING U BOLT 11 (WCP)	Necessary	400.00 FS	*400.00 F
46	1		*FRONT TIE ROD ASSY (WCP)	Bent	800.00 F	*800.00 F
47	1		*DPF MUFFLER ASSY (WCP)	Bent	11,500.00 F	*11,500.00 F
48	1		*FRONT TIE ROD END LH (WCP)	Bent	450.00 F	*450.00 F
Supplementary #2						
49	2		*GEARBOX U SUPPORT BRACKET (WCP)	Cracked	2,600.00 F	*2,600.00 F
F=Franchise part. S=SpcNett.						
					Sub Total (\$\$)	49,639.00 41,584.00
					+ Margin on L,N Items 15.00/15.00% (\$\$)	6,692.10 6,120.60
					Total Parts (\$\$)	56,331.10 47,704.60

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<u>Labour Items</u>				
1	TO INSPECT FRONT LIGHTING WATER & LEAKAGE TEST	New	40.00	40.00
2	TO REMOVE & INSTALL FRONT WINDSCREEN	New	160.00	160.00
3	TO REMOVE & INSTALL DASHBOARD	New	300.00	200.00
4	TO REMOVE & INSTALL CARPET, GARNISH, SEAT & ETC IN ORDER TO CUT OFF LH FRONT DOOR PILLAR & STRAIGHTEN AFFECTED AREAS	New	400.00	200.00
5	TO CUT OFF WIPER PANEL, LH FRONT DOOR PILLAR, STRAIGHTEN AFFECTED AREAS AND RENEW DAMAGED PARTS	New	2,400.00	1,500.00
6	TO SPRAY PAINT ON REPLACED, REPAIRED AREAS	New	1,500.00	1,100.00
<u>Supplementary #1</u>				
<u>Labour Items</u>				
7	TO REMOVE & RENEW FRONT BOTH UNDERCARRIAGE DAMAGED PARTS	New	600.00	400.00
8	TO CHECK ALL WHEELS ALIGNMENT	New	200.00	150.00
Gross Labour Cost (S\$)			5,600.00	3,750.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >