

REPAIR DETAILS

Reference

Part Source: (Last Synchronised: 02 Apr 2020)

Parts: N/A MITSUBISHI FUSO 12.0 D FV51SJD2DEA (M) (Model not available in database)

Labour: Repairer's (Price-denominated Standard List)

Print Code: (Unsubmitted, no print-code for XD7979A)

Validity: These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page

Further Info: Items/values not in reference catalogue are prefixed with an asterisk *.

Estimates on Parts

No.	Qty	Part No.	Particulars	%Disc	%Depr	Amount
1	1		*FRONT WINDSCREEN GLASS <i>bro</i>	0.00	0.00	*1,500.00 F
2	1		*FRONT WINDSCREEN MOULDING <i>rec</i>	0.00	0.00	*350.00 F
3	<i>2 pcs</i>		*WIPER ARM <i>bt</i>	0.00	0.00	*750.00 F <i>500</i>
4	1		*WIPER LINKAGE ASSY <i>X</i>	0.00	0.00	*850.00 F <i>X</i>
5	1		*WIPER PANEL <i>bt repair</i>	0.00	0.00	*480.00 F <i>X</i>
6	1		*FRONT PANEL <i>bt</i>	0.00	0.00	*2,800.00 F <i>✓</i>
7	2		*FRONT PANEL HINGE <i>X</i>	0.00	0.00	*140.00 F <i>X</i>
8	1		*FRONT PANEL (FUSO) EMBLEM <i>rec</i>	0.00	0.00	*180.00 F <i>✓</i>
9	2		*FRONT PANEL GRILLE <i>sc</i>	0.00	0.00	*1,200.00 F <i>✓</i>
10	1		*FRONT BUMPER TOP <i>bro</i>	0.00	0.00	*250.00 F <i>✓</i>
11	1		*FRONT BUMPER LOWER <i>bt</i>	0.00	0.00	*1,300.00 F
12	<i>2 pcs</i>		*FRONT BUMPER LH & RH <i>LH-bro/RH-X</i>	0.00	0.00	*300.00 F <i>150</i>
13	<i>2 pcs</i>		*FRONT BUMPER COVER LH & RH <i>LH-bro/RH-X</i>	0.00	0.00	*300.00 F <i>150</i>
14	1		*FRONT BUMPER CENTER BRACKET <i>?</i>	0.00	0.00	*1,050.00 F
15	<i>2 pcs</i>		*FRONT BUMPER LH & RH BRACKET <i>LH-bt/RH-X</i>	0.00	0.00	*600.00 F <i>300</i>
16	1		*HEADLAMP LH <i>bro</i>	0.00	0.00	*800.00 F
17	1		*SMALL LAMP LH <i>bro</i>	0.00	0.00	*300.00 F
18	1		*SIGNAL LAMP LH <i>bro</i>	0.00	0.00	*160.00 F
19	1		*FRONT CORNER PANEL LH <i>cm</i>	0.00	0.00	*550.00 F
20	1		*FRONT CORNER PANEL BRACKET LH <i>?</i>	0.00	0.00	*140.00 F
21	1		*FRONT SIDE MIRROR BRACKET LH <i>bt</i>	0.00	0.00	*1,100.00 F
22	<i>2 pcs</i>		*FRONT SIDE MIRROR BRACKET SUPPORT <i>bt</i>	0.00	0.00	*600.00 F
23	2		*FRONT SIDE MIRROR <i>cm</i>	0.00	0.00	*360.00 F
24	1		*FRONT SIDE ROUND MIRROR LH <i>cm</i>	0.00	0.00	*110.00 F
25	1		*FRONT WHEEL ARCH LH <i>de</i>	0.00	0.00	*210.00 F
26	1		*FRONT WHEEL ARCH BLADE GARNISH LH <i>bro</i>	0.00	0.00	*950.00 F
27	1		*FRONT STEP PANEL LH <i>bro</i>	0.00	0.00	*750.00 F
28	1		*FRONT STEP PANEL BOTTOM LH <i>bro</i>	0.00	0.00	*600.00 F
29	3		*FRONT STEP PLATE <i>bro</i>	0.00	0.00	*714.00 F
30	1		*FRONT STEP SUPPORT BAR LH <i>bt</i>	0.00	0.00	*780.00 F
31	1		*CONDENSER <i>bt</i>	0.00	0.00	*1,340.00 F
32	1		*CONDENSER BRACKET <i>bt</i>	0.00	0.00	*580.00 F
33	2		*CONDENSER AIR CON PIPE <i>bt</i>	0.00	0.00	*400.00 F
34	1		*CONDENSER FAN MOTOR <i>?</i>	0.00	0.00	*900.00 F
35	1		*CONDENSER FAN BLADE <i>?</i>	0.00	0.00	*220.00 F
36	1		*CONDENSER FAN COWLING <i>?</i>	0.00	0.00	*190.00 F
37	1		*LH FRONT DOOR PILLAR <i>repair</i>	0.00	0.00	*2,800.00 F
38	1		*FRONT BUMPER CENTER STEP GARNISH <i>bro</i>	0.00	0.00	*160.00 F
39	1		*DASHBOARD TOP <i>?</i>	0.00	0.00	*2,500.00 F
40	1		*TOWING TO FAN YOONG	0	0.00	*350.00 FS <i>receipt?</i>
41	1		*LH FRONT TYRE <i>punctured</i>	0	0.00 <i>70%</i>	*600.00 FS <i>? 420</i>
42	1		*FRONT NUMBER PLATE <i>bt</i>	0	0.00 <i>35</i>	*50.00 FS
43	1		*FRONT IU BRACKET <i>rec</i>	0	0.00	*25.00 FS
Sub Total (\$\$)						30,289.00
+ Margin on L,N Items 15.00% (\$\$)						4,389.60
Total Parts (\$\$)						34,678.60

F=Franchise part. S=SpcNett.

Report was unsubmitted during this print-out.
Generated using Merimen e-Claims IEAS

Estimates on Miscellaneous Items

There are no new miscellaneous items selected.

Estimates on Labour

No	Particulars	Lab.Type	Amount
Labour Items			
1	TO INSPECT FRONT LIGHTING WATER & LEAKAGE TEST	New	40.00
2	TO REMOVE & INSTALL FRONT WINDSCREEN	New	160.00
3	TO REMOVE & INSTALL DASHBOARD	New	300.00 200
4	TO REMOVE & INSTALL CARPET, GARNISH, SEAT & ETC IN ORDER TO CUT OFF LH FRONT DOOR PILLAR & STRAIGHTEN AFFECTED AREAS	New	400.00 200
5	TO CUT OFF WIPER PANEL, LH FRONT DOOR PILLAR, STRAIGHTEN AFFECTED AREAS AND RENEW DAMAGED PARTS	New	2,400.00 1200
6	TO SPRAY PAINT ON REPLACED, REPAIRED AREAS	New	1,500.00 900
Gross Labour Cost (\$\$)			4,800.00

Report was unsubmitted during this print-out.
Generated using Merimen e-Claims IEAS

< END OF ESTIMATES >

KKK Auto Consultants hence notify
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Rasul
Hp 90010068

8 days

4/5

EXCESS: 2000

REVERT

02/04/2020 @1635

Resurvey after repair