

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933 TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

#### **TAX INVOICE**

MS FIRST CAPITAL INSURANCE LTD 36 ROBINSON ROAD #16-01 CITY HOUSE

SINGAPORE 068877

INV No. AC2007950

INV Date 26/11/2020

Reference CC4/FCI20004848/Kka3q2

Code FCI2

#### **PROFESSIONAL SERVICE FEE**

Vehicle No. SKP 7326A

Insured Veh. SHA 7817P

Claim No. D20001750MFSH/1

Policy No. D-20094922MFSH

Accident Date 31/03/2020

Inspection Date 02/04/2020

Description	Total
Third Party Express Settlement	350.00
Subtotal	350.00
GST (7%)	24.50
Grand Total	374.50

We shall be glad if you could forward the payment at your early convenience.

Cheque should be crossed and made payable to 'LKK Auto Consultants Pte Ltd'

**LKK Auto Consultants Pte Ltd** 





51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

	Affiliated to Federation Internationale Des Experts En Automobile					
MS F	MS FIRST CAPITAL INSURANCE LTD Ref: CC4/FCI20004848/Kka3q2					
36 ROBINSON ROAD #16-01 CITY HOUSESINGAPORE 068877		INGAPORE 068877	Date: 26-11-2020 Code: FCI2			
1.		Policy Particulars	- THIRD PARTY CLAIM			
	Insured Veh.	SHA 7817P	Veh. Inspected	SKP 7326A		
	Policy No.	D-20094922MFSH	Coverage (\$)	0.00		
	Claim No.	D20001750MFSH/1	Excess (\$)	0.00		
	Assign From	CHRIS	Assign Date	02/04/2020		
2.		Vehicle Partic	culars & Condition			
	Make & Model	HONDA INSIGHT (A)	c.c	1339		
	Engine No.	HIDDEN	Year of Reg.	2014		
	Chassis No.	JHMZE2850ES200150	Colour	METALLIC DARK GREY		
	Odometer	245610	Steering	IN ORDER		
	Brakes	IN ORDER	Modification	STANDARD ALLOY RIM		
	General	GOOD				
3.		Condition	ons of Tyres	_		
		Size	Make	Balance		
	R/H Front Tyre	185/55 R16	YOKOHAMA	8 mm		
	L/H Front Tyre	185/55 R16	YOKOHAMA	8 mm		
	R/H Rear Tyre	185/55 R16	YOKOHAMA	7 mm		
	L/H Rear Tyre	185/55 R16	YOKOHAMA	7 mm		
4.		•	on of Damages			
	THE VEHICLE SU	STAINED DAMAGES AT THE REA	AR PORTION.			
	DAMAGES SEE D	ETAILS.				
5.		General	Information			
	Accident Date	31/03/2020	Inspection Date	02/04/2020		
	Survey held at	HWA SENG SPRAY PAINTING	COMPANY			
		160 SIN MING DRIVE #05-11 SIN MING AUTOCITY SINGAPORE 575722				
5a.		Re	emarks			
	A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.					
5b.	5b. Estimate Days of Repair					
	ESTIMATED NORI	MAL PERIOD FOR REPAIR:	5 Working Days			



51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 2

#### ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SKP 7326A

Qty	Description of Parts	Condition	Estimate By Workshop (\$))	Our Adjusted (\$)
	REPLACEMENT OF PARTS			
1	TAILGATE	BENT	928.20	928.20
2	TAILGATE HINGES @\$42.20	TO REPAIR SEE LABOUR	84.40	-
2	TAILGATE ABSORBER @\$124.80	SERVICEABLE	249.60	-
1	TAILGATE GARNISH	SERVICEABLE	305.60	-
1	EMBLEM 'INSIGHT'	NOT NECESSARY	48.50	-
1	LOGO EMBLEM	NOT NECESSARY	38.60	-
1	EMBLEM 'HYBRID'	NOT NECESSARY	52.50	-
1	TAILGATE UPPER LOCK	DENTED	262.20	262.20
1	TAILGATE LOWER LOCK	TO REPAIR SEE LABOUR	42.00	-
1	TAILGATE HANDLE	SERVICEABLE	74.80	-
2	TAILLAMP @\$576.00	SERVICEABLE	1,152.00	-
1	TAILGATE REFLECTOR	SERVICEABLE	211.00	-
1	REAR BUMPER	BUCKLED	701.60	701.60
1	REAR BUMPER REINFORCEMENT	NOT NECESSARY	385.00	-
1	REAR BUMPER BEAM	NOT NECESSARY	197.00	-
2	REAR BUMPER RETAINER @\$47.40	SERVICEABLE	94.80	-
1	REAR BUMPER LOWER GARNISH	DENTED/ DISTORTED	189.00	189.00
2	REAR BUMPER LOWER GARNISH REFLECTOR @\$44.20	NOT NECESSARY	88.40	-
1	END PANEL	BENT	438.70	438.70
1	SPARE TYRE PANEL	TO REPAIR SEE LABOUR	611.30	-
1	SPARE TYRE BOARD	SERVICEABLE	197.00	-
1	END PANEL GARNISH	NOT NECESSARY	141.20	-
	LESS 20% DISCOUNT		-1,298.68	-503.94
			5,194.72	2,015.76
	SPECIAL NETT ITEMS			
1	SEALANT & CLIP (SN)	NECESSARY	80.00	60.00
1	INNER SEAL (SN)	NECESSARY	60.00	30.00
1	SET REVERSE SENSOR (SN)	SHORTED	230.00	200.00

Report Ref No. CC4/FCI20004848/Kka3q2



51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:2 of 2

3,200.00

Qty	Description of Parts	Condition	Estimate By Workshop (\$))	Our Adjusted (\$)
1	SET NUMBER PLATE WITH HOLDER (SN)	SERVICEABLE	75.00	-
			445.00	290.00
	LABOUR			
	PANEL KNOCKING.INCLUSIVE OF THE REPAIR OF TAILGATE HINGES,TAILGATE LOWER LOCK AND SPARE TYRE PANEL.		1,000.00	600.00
	SPRAY PAINTING.		1,200.00	600.00
	WIRE CHECKING.		50.00	15.00
	LABOUR TO REMOVE AND INSTALL REAR WINDSCREEN.		160.00	120.00
	LABOUR TO REMOVE AND INSTALL UPHOLSTERY.		150.00	60.00
	REMOVE ,INSTALL & RESET HYBRID BATTERY . (ADDITIONAL)		450.00	250.00
			3,010.00	1,645.00
	GRAND TOTAL		8,649.72	3,950.76

Report Ref No. CC4/FCI20004848/Kka3q2

RECOMMENDED COST OF LUMP SUM REPAIRS

(TO ITS PRE-ACCIDENT CONDITION)

KONG SENG CHEONG

Licensed Appraiser



51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933 TEL: 6256 3581 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

### PHOTOGRAPHS FOR VEHICLE NO. SKP 7326A

INSPECTION

















51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933 TEL: 6256 3581 FAX: 6256 4315















51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933 TEL: 6256 3581 FAX: 6256 4315















51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933 TEL: 6256 3581 FAX: 6256 4315





51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933 TEL: 6256 3581 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

### PHOTOGRAPHS FOR VEHICLE NO. SKP 7326A

#### RE-INSPECTION















51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933 TEL: 6256 3561 FAX: 6256 4315





