Page 1 of 3 Adjuster Report

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS3/AIG20004871/GSD3E2

Date: 14/04/2020

REFERENCE

No:

Handling Insurer: AIG Asia Pacific Insurance Pte. Ltd. Policy No: 1800122668 Claimant Vehicle SJR3425A **Insured Vehicle No:** SMG848E

ΤP Date of Loss: 01/04/2020 Nature of Claim: Claim No: 9365982808SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: SJR3425A

Make & Model: KIA CERATO FORTE, 1.6 SX (A) Engine No: G4FC9H261727 Reg. Date: 19/06/2009 (Man. Year: 2009) Chassis No: KNAFH221395084028

Colour: Odometer: 206966 km

Engine Capacity: 1591 cc Market Value/New Car Price: N/A

Sum Insured (S\$): Market Value/New Car Price

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Footbrake (Serviceable): Yes

Handbrake (Serviceable): Engine Modification: No Pre-accident Condition: Yes

CONDITION OF TYRES

Front Tyre Size: 215/45 R17 Rear Tyre Size: 215/45 R17 Front Left Side: Rear Left Side: Lead 5 mm Lead 5 mm Rear Right Side: Front Right Side: Lead 5 mm Lead 5 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	0.00	0.00	0.00	
Miscellaneous Items	0.00	0.00	0.00	
Labour	0.00	0.00	0.00	
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Nett Amount (S\$)	0.00	0.00	0.00	

INSPECTION

02/04/2020 Date of Assignment:

Date Inspected: 06/04/2020 Inspected At: Excel Motor (HQ)

BLK 5032 Ang Mo Kio Industrial Park 2,

#01-297

Singapore 569535

Estimated Period of Repair: 7.0 days

XING GUO QIANG Adjuster: Manager: Hiew May Fung

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

Adjuster Report Page 2 of 3

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FRT LH DOOR	Buckled	0.00 F	*- F
2	1		*ROCKER PANEL LH	Repair	0.00 F	*- F
3	1		*FRT LH FENDER	Repair	0.00 F	*- F
4	1		*FRT LH WHEEL RIM	Cut	0.00 F	*- F
5	1		*FRT RH WHEEL RIM	Cut	0.00 F	*- F
6	1		*REAR LH DOOR	Buckled	0.00 F	*- F
7	1		*REAR LH FENDER	Repair	0.00 F	*- F
8	1		*REAR LH WHEEL RIM	Cut	0.00 F	*- F
9	1		*FRT LH KNUCKLE ARM BEARING	* Check	0.00 F	*- F
10	1		*REAR WHEEL HUB BEARING	* Check	0.00 F	*- F
11	1		*FRT RH KNUCKLE ARM BEARING	* Check	0.00 F	*- F
F=Fra	anchise	part.		_		
				Total Parts (S\$)	0.00	0.00

Report was unsubmitted during this print-out.

Adjuster Report Page 3 of 3

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

There are no labour items selected.

Report was unsubmitted during this print-out.

< END OF ESTIMATES >