

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SHA 4047P

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
<u>REPLACEMENT OF PARTS</u>				
1	FRONT BUMPER COVER	TO REPAIR SEE LABOUR	418.30	-
1	FRONT BUMPER BRACKET - RH	NOT NECESSARY	28.00	-
1	FRONT BUMPER TOP BRACKET - RH	NOT NECESSARY	12.00	-
10	FRONT BUMPER CLIPS @\$2.20	NOT NECESSARY	22.00	-
1	FRONT BUMPER GRILLE - RH	SCRATCHED	186.90	186.90
1	FRONT FENDER - RH	BUCKLED	490.70	490.70
1	FRONT FENDER EMBLEM - BLUEDRIVE	NECESSARY	26.60	26.60
1	HEADLAMP - RH	TO REPAIR SEE LABOUR	1,993.65	-
1	HEADLAMP SUPPORT PANEL	NOT NECESSARY	949.30	-
	LESS 20% DISCOUNT		-825.49	-140.84
			3,301.96	563.36
<u>LABOUR</u>				
	PANEL BEATING. INCLUSIVE OF THE REPAIR OF FRONT BUMPER COVER AND HEADLAMP - RH.		700.00	640.00
	SPRAY PAINTING CHARGE.		500.00	450.00
	WIRING CHARGE.		80.00	50.00
	TUFF KOTE.		80.00	50.00
			1,360.00	1,190.00
GRAND TOTAL			4,661.96	1,753.36
RECOMMENDED COST OF REPAIRS (CONFIRMED)				1,753.36

Report Ref No. NS/INC20004874/Ftf3e2



PARASURAM S/O SHANMUGAM

Asst. Automotive Assessor



K.K.LAU CPT(RET)

**BEng(Hons),B.Bus,MBA,PEng,PE,
MInstAEA,MASME,MIRTE**

REGD Auto Consultant-SAE, Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contact or tort, is accepted to any third party who may reply on the Report wholly or in part. Any third party acting or replying on this Report, in whole or in part, does so at his or her own risk.