

(08/11/13) wef

ASS. REC. BY: *Marcus*

REF:

A169/

## ASSIGNMENT

From: Date:

Estimated Cost:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No:

at Workshop m/s

of

Insured:

Policy No.

Claims No.

Sum Insured: Excess:

(Client's Record)

Make of Veh:

(Policy Condition)

Remark: The veh had commenced its  
repair at the time of inspection.

Bal. or Market Value:

IDAC Accident Rpt: Consistent? : Yes or No

GIA / PR Seen: Consistent? : Yes or No

Est. Repairs: 4 days Res.: Yes or No

Lum Sum: 2W % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Date:

Person Contacted:

Vehicle: IN / OUT

Veh No:

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make:

Colour:

Sp. Reading

Eng/No:

C/No:

Gen. Cond: Good / Fair / Poor / Burnt

Steering: Inorder / Jammed / Leaked / Burnt or

Brake: Inorder / Jammed / Leaked / Burnt or

Modi: Nil / S/Rim / STD A/Rim or

Tyre Size:

F:

R:

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Front

R/Bal.

L/Bal.

D.O.A.

Survey held at

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time

Action / Instruction

Date/Time, File Pass to?

1)

Date/Time, File Return to?

2)

☐

Preli. Report

☒

Final Report

Days Of Repair:

Resurvey No. of Trip:

Add Fee:

☐

Site Insp (\$

☐

Interview (\$

☐

Tech. Invs (\$

☐

Weekend (\$

Survey Fee:

Transportation:

) S + RS, SI

) Photos

) Others

TOTAL

Report Format :

Lump Sum / I.B.I: (\$ 2,300/- 45 )

|     |     |
|-----|-----|
|     |     |
| N/S | O/S |
|     |     |

6/4/20

LTA 1435 (see 13-7-2020 note 256)

4/5 @ 2300 confid with AH Lin

( \$ 1,959.93 Red - 46% )

3ale plus

O/S Lf.

Van max

Rear

R/Bal.

L/Bal.

D.O.I.

5

mm

5

mm

5

mm

24/3/20

3/4/20

# 祥輝汽車修理 SIANG HUI MOTOR WORKS

Blk 3006, Ubi Road 1 #01-338, Singapore 408700.  
Tel: 67444605 Fax: 67440726  
REG. No. 322208/00M

not Adjust  
her  
nearby  
2/5 2300  
3/4/20 4475

Date, 3/4/20

vehicle no: GY 7141R Nissan

|          |     |                            |        |            |         |
|----------|-----|----------------------------|--------|------------|---------|
| 1        | IPC | Front door o/s             | 3.1500 | \$ 1116.80 | ✓       |
| 2        | IPC | Front corner Panel o/s     | 2.4    | \$ 231.70  | ✓       |
| 3        | IPC | Front side Lamp o/s        | cm     | \$ 126.80  | ✓       |
| 4        | IPC | Front bumper               | Dis    | \$ 622.80  | ✓       |
| 5        | IPC | Front bumper Side Retainer | cm     | \$ 63.20   | 48.00 ✓ |
| 6        | IPC | Headlamp o/s               | 395 cm | \$ 927.60  | ✓       |
| 7        | IPC | Fog Lamp Cover o/s         | 1.1    | \$ 113.70  | X       |
| 8        | IPC | Fog Lamp o/s               | cm     | \$ 197.30  | ✓       |
|          |     |                            |        | \$ 3399.90 |         |
| Less 30% |     |                            |        | \$ 1019.97 |         |
|          |     |                            |        | \$ 2379.93 | 2738.40 |

Labour charges:-

1) To remove, replace front door, side panel, bumper & headlamp \$ 980.00 450

2) To spray painting \$ 900.00 600

Total: \$ 4259.93

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

2966.88  
2373