No.25 Kaki Bukit Road 4 #06-46 Synergy @KB Singapore 41780 Hotline: 6385 1171

Our reference

19-9-8556

Date

15/10/2019

Page

2

Section A: Damaged Parts Assessment

Section A. Da	mageu	raits Assessme	TIL		
Part's Description	Qty	Condition As inspected	Repairer's Estimate	Our Adjustment	
List Items:					
Boot lid	1	bent/warped	1956.50	1956.50	1550
Boot lid weather strip	1	necessary	155.00	155.00	X SVC
Boot lid top lock	1	bent-in	257.80	257.80	X SVC
Boot lid logo	1	necessary	69.80	69.80	55
Boot lid emblem 'C200'	1	necessary	65.00	65.00	
Boot lid emblem 'CGI"	1	necessary	45.00	45.00	
Boot lid outer handle	1	grazed/holder damaged	291.20	291.20	X SVC
Rear bumper	1	deformed	1557.80	1557.80	1460
Rear bumper inner garnish	1	damaged	266.00	266.00	180
Rear bumper reinforcement	1	bent	657.00	657.00	
Rear bumper center moulding	1	necessary	211.00	211.00	120
Rear bumper side moulding @\$142.00	2	necessary	284.00	284.00	220
Tail lamp @\$601.00	1	Ih damaged rh reuse	1202.00	601.00	540
Tail lamp lower bracket Ih	1	damaged	82.00	82.00	54
Rear end panel	1	repair	640.00	0.00	
Rear end panel top garnish	1	serviceable	185.00	0.00	
Rear exhaust pipe	1	bent/dented	1554.80	1554.80	x repair
Front cushion seat headrest @\$1645.00	2	deployed	3290.00	3290.00	x repair
Air bag (signal check)	1	see labour	0.00	0.00	
	Sub- Tota	al cost	12769.90	11343.90	4946
Percentage	10%	1276.99	1134.39		
Sub-Total costs for parts			11492.91	10209.51	4451.4

Subsidiaries of Impact Analysis Consultant:

www.iaconsultingsg.com

Impact Analysis Consulting Pte Ltd
 Impact Analysis Academy Pte Ltd
 IA Racking Solutions Pte Ltd
 IA Accounting & Consultancy Pte Ltd
 Infoknights International Services (Philippines)
 IABN Pte Ltd

No.25 Kaki Bukit Road 4 #06-46 Synergy @KB Singapore 41780 Hotline: 6385 1171

Our reference

19-9-8556

Date

15/10/2019

Special	Nett	Items:
Special	14000	15011131

			The street of th		
	Sub-Total cost	Sub-Total costs for parts		358.50	243.5
Rear reverse sensor	1	malfunction	350.00	300.00	200
Tail lamp side garnish clips lh @\$4.50	3	necessary	13.50	13.50	
Rear bumper clips @\$4.50	10	necessary	45.00	45.00	30

Parts Repair

Sub- Total costs Total costs for parts
 0.00
 0.00

 0.00
 0.00

 11901.41
 10568.01

IA Accounting & Consultancy Pte Ltd • Infoknights International Services (Philippines) • IABN Pte Ltd www.iaconsultingsg.com

No.25 Kaki Bukit Road 4 #06-46 Synergy @KB Singapore 41780 Hotline: 6385 1171

Our reference

19-9-8556

Date

15/10/2019

Page

3

Section B: Labour Cost Calculation

To dismonth, replace out world brook out dente to straighten assident		rate	Manhr, Req.	Total		
To dismantle, replace, cut, weld, knock out dents to straighten accident parts as-mentioned on the 'Parts Repair' column inclusive of replacement parts.	\$ 50	0.00	20	\$	1,000.00	60
Putty & Spray painting to adjacent panels. Job allowance. Paint / material.	erial. Sub-contract work. \$ 800		800.00	60		
Apply rust proofing on the adjacent panels.	Sub-contract work.		\$	50.00	x	
Remove and replace rear exhaust system	\$ 50	0.00	1.7	\$	85.00	60
Remove and replace rear bumper reverse sensor & conduct distance safety setting.	\$ 50	0.00	1.7	\$	85.00	40
Specialist charges -Air bag diagnostic	-		į.	\$	600.00	12
Specialist charges -Front Head rest (2) reset	-		-	\$	550.00	2
Wiring / bulb checking	\$ 50	0.00	0.5	\$	25.00	V
Total labour cost			bour cost	\$	3,195.00	16

Manhour rate and the number of manhours required for each repairing task are formulated based on individual workshop's operating cost and in-house@ IA Research Guidelines respectively.

Subsidiaries of Impact Analysis Consultant:

[•] Impact Analysis Consulting Pte Ltd • Impact Analysis Academy Pte Ltd • IA Racking Solutions Pte Ltd

IA Accounting & Consultancy Pte Ltd • Infoknights International Services (Philippines) • IABN Pte Ltd www.iaconsultingsg.com



No.25 Kaki Bukit Road 4 #06-46 Synergy @KB Singapore 41780 Hotline: 6385 1171

Our reference

19-9-8556

Date

15/10/2019

Section C: Summary Table of Total Repair Cost

Desc	cription	Cost	
Asses	ged Parts ssment ection A)	\$10,568.01	
Further discount	20%	\$2,113.60	
Recommended cost of parts		\$8,454.41	(1)
	t Calculation	\$3,195.00	(2)
	epair Cost to hundred)	\$11,600.00	(1) + (2)

We would recommend a sum of	\$11,600.00	and	7	working days for repair.
No further items will be approved	without our expressed	d written agreen	nent. Any signif	icant additional
items will be subject to a supplem	entary report.			

Mechanical Engineer, Accident Expert Witness, Licensed Appraiser (Automobile)

B.Eng. (Hons, NUS)

Diploma.Mechanical Engineering

NTC-2 Automovite Technology

Sr.MIES, Institution of Engineers, Singapore (#20100091)

MATAI, Maryland Association of Traffic Accident Investigators

IAARS, International Association of Accident Reconstruction Specialists

PMC of Singapore Business Advisors & Consultants Council

ACTA certified Trainer, Singapore

SPRING- Recognised Certification for Management Consultants

20%:5050

6239.9

6 days

Subsidiaries of Impact Analysis Consultant:

 [♦] Impact Analysis Consulting Pte Ltd
 ♦ Impact Analysis Academy Pte Ltd
 ♦ IA Racking Solutions Pte Ltd

IA Accounting & Consultancy Pte Ltd • Infoknights International Services (Philippines) • IABN Pte Ltd www.iaconsultingsg.com