

## **LKK Auto Consultants Pte Ltd**

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 2

## ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SKX 4278H

Qty	Description of Parts	Condition	Estimate By Workshop (\$))	Our Adjusted (\$)
	REPLACEMENT OF PARTS			
1	REAR DOOR N/S (CONSISTENT)	BENT / WARPED	1,855.20	1,516.20
1	REAR DOOR OUTER LOWER CHROME MOULDING N/S (CONSISTENT)	NOT NECESSARY	425.50	-
1	REAR DOOR INNER LOCK N/S (CONSISTENT)	NOT NECESSARY	466.20	-
1	REAR DOOR INNER RUBBER N/S (CONSISTENT)	NECESSARY	292.30	188.20
1	REAR DOOR FRAME BLACK GARNISH N/S (CONSISTENT)	NECESSARY	165.00	68.00
1	REAR FENDER N/S (CONSISTENT)	TO REPAIR SEE LABOUR	1,819.20	-
1	ROCKER PANEL GARNISH N/S (CONSISTENT)	NOT NECESSARY	688.50	-
1	REAR MUDFLAP N/S (CONSISTENT)	NOT NECESSARY	148.50	-
1	REAR SHOCK ABSORBER N/S (CONSISTENT)	NOT NECESSARY	399.50	-
1	REAR WHEEL HUB BEARING N/S (CONSISTENT)	NOT NECESSARY	625.00	-
1	REAR KNUCKLE ARM N/S (CONSISTENT)	NOT NECESSARY	699.20	-
1	REAR BUMPER (CONSISTENT)	TO REPAIR SEE LABOUR	1,299.30	-
1	SET REAR BUMPER CLIPS (CONSISTENT)	NOT NECESSARY	50.00	-
1	REAR BUMPER SIDE RETAINER N/S (CONSISTENT)	NOT NECESSARY	66.50	-
	LESS 25% DISCOUNT		-	-443.10
			8,999.90	1,329.30
	SPECIAL NETT ITEMS			
1	REAR SPORT RIM N/S (CONSISTENT) (SN)	сит	1,200.00	850.00
			1,200.00	850.00
	LABOUR			
	TO CHECK WIRING .		50.00	20.00
	TO DISMANTLE & REFIX REVERSE SENSOR .		80.00	50.00
	TO CONDUCT WHEEL ALIGNMENT.		120.00	60.00
	TO DISMANTLE & REFIX REAR UNDERCARRIAGE .	NOT NECESSARY	150.00	_
	TO TRANSFER REAR DOOR MECHANISM .		100.00	60.00
	TO SPRAY RUST PROOFING .		80.00	30.00

Report Ref No. CC4/ASM20004896/Uga3q2



## **LKK Auto Consultants Pte Ltd**

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:2 of 2

Qty	Description of Parts	Condition	Estimate By Workshop (\$))	Our Adjusted (\$)
	LABOUR FOR PANEL BEATING & REPLACING PARTS.INCLUSIVE OF THE REPAIR OF REAR FENDER N/S AND REAR BUMPER.		900.00	520.00
	TO PUTTY & SPRAY PAINTING.		1,280.00	600.00
			2,760.00	1,340.00
	GRAND TOTAL		12,959.90	3,519.30

RECOMMENDED COST OF LUMP SUM REPAIRS		2,800.00
(TO ITS PRE-ACCIDENT CONDITION)		

Report Ref No. CC4/ASM20004896/Uga3q2

CHUA KANG SENG

Licensed Appraiser