



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

TAX INVOICE

LONPAC INSURANCE BHD
300 BEACH ROAD
#17-04/07 THE CONCOURSE
SINGAPORE 199555

INV No. AC2003409
INV Date 23/04/2020
Reference CS/LPC20004904/Uvd3n2
Code LPC2



PROFESSIONAL SERVICE FEE

Vehicle No. YP 7668Y
Insured Veh. GBF 5826X
Claim No. 19/20/20/VC05/023252
Policy No.
Accident Date 25/03/2020
Inspection Date 09/04/2020

Description	Total
Survey Inspection	350.00
Resurvey Inspection	
Digital Photographs	
Transportation	
Subtotal	350.00
GST (7%)	24.50
Grand Total	374.50

We shall be glad if you could forward the payment at your early convenience.

Cheque should be crossed and made payable to **'LKK Auto Consultants Pte Ltd'**

LKK Auto Consultants Pte Ltd

HYN



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
LONPAC INSURANCE BHD		Ref : CS/LPC20004904/Uvd3n2		
300 BEACH ROAD #17-04/07 THE CONCOURSESINGAPORE 199555		Date : 23-04-2020		
		Code : LPC2		
1. Policy Particulars :- THIRD PARTY CLAIM				
Insured Veh.	GBF 5826X	Veh. Inspected	YP 7668Y	
Policy No.		Coverage (\$)	0.00	
Claim No.	19/20/20/VC05/023252	Excess (\$)	0.00	
Assign From	ONG LI LI	Assign Date	03/04/2020	
2. Vehicle Particulars & Condition				
Make & Model	MITSUBISHI FUSO FK62 (M)	c.c	7545	
Engine No.	HIDDEN	Year of Reg.	2017	
Chassis No.	FK62FMA30353	Colour	WHITE	
Odometer	212485	Steering	IN ORDER	
Brakes	IN ORDER	Modification	NIL	
General	GOOD			
3. Conditions of Tyres				
	Size	Make	Balance	
R/H Front Tyre	245/70 R19.5	FALKEN	7 mm	
L/H Front Tyre	245/70 R19.5	FALKEN	7 mm	
R/H Rear Tyre	245/70 R19.5 (D)	FALKEN	7/7 mm	
L/H Rear Tyre	245/70 R19.5 (D)	FALKEN	7/7 mm	
4. Description of Damages				
THE VEHICLE SUSTAINED DAMAGES AT THE REAR AND FRONT PORTION. DAMAGES SEE DETAILS.				
5. General Information				
Accident Date	25/03/2020	Inspection Date	09/04/2020	
Survey held at	MAH LIAN MOTOR VEHICLE REPAIRER 38 DEFU LANE 9 SINGAPORE 539278			
5a. Remarks				
A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.				
5b. Estimate Days of Repair				
ESTIMATED NORMAL PERIOD FOR REPAIR:		5 Working Days		



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 2

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. YP 7668Y

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	<u>REPLACEMENT OF PARTS</u>			
1	FRONT PANEL	BADLY DENTED	2,658.34	2,658.34
1	FRONT PANEL RUBBER SEAL	NOT NECESSARY	233.00	-
2	FRONT PANEL HINGE-LH/RH @\$72.45	CRACKED	144.90	144.90
1	FRONT PANEL HANDLE-RH	BENT	189.53	189.53
1	FRONT GRILLE	CRACKED	1,355.06	1,355.06
1	"MITSUBISHI" LOGO	SCRATCHED	279.91	279.91
1	WIPER PANEL	TO REPAIR SEE LABOUR	2,821.98	-
1	WIPER PANEL RUBBER SEAL	NOT NECESSARY	127.00	-
1	WIPER WASHER TANK	DEFORMED	769.87	366.20
1	WIPER MOTOR BRACKET	NOT NECESSARY	235.34	-
1	WIPER LINK ASSY	NOT NECESSARY	835.28	-
2	FRONT CORNER PANEL-LH/RH @\$1127.41	CRACKED	2,254.82	2,254.82
1	INNER PANEL	TO REPAIR SEE LABOUR	5,122.87	-
1	INNER PANEL REINFORCEMENT	TO REPAIR SEE LABOUR	1,321.28	-
1	FRONT BUMPER	BENT	2,389.52	2,389.52
2	FRONT BUMPER BRACKET-LH/RH @\$299.27	BENT	598.54	598.54
2	HEADLAMP RIM-LH/RH @\$544.39	CRACKED	1,088.78	1,088.78
2	HEADLAMP ASSY-LH/RH @\$1322.78	CRACKED	2,645.56	2,645.56
2	HEADLAMP BRACKET-LH/RH @\$299.27	BENT	598.54	598.54
2	FOG LAMP-LH/RH @\$544.96	CRACKED	1,089.92	1,089.92
2	SIGNAL LAMP-LH/RH @\$405.08	NOT NECESSARY	810.16	-
2	STEP PANEL-LH/RH @\$788.96	NOT NECESSARY	1,577.92	-
1	AIRCON BLOWER ASSY	NOT NECESSARY	1,321.28	-
1	AIRCON COOLING COIL ASSY	NOT NECESSARY	1,074.30	-
1	AIRCON EVAPORATOR ASSY	NOT NECESSARY	2,165.47	-
	LESS 25% DISCOUNT		-8,427.29	-3,914.91
			25,281.88	11,744.71

Report Ref No. CS/LPC20004904/Uvd3n2



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:2 of 2

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
1	<u>SPECIAL NETT ITEMS</u>			
	REAR TIPPER WOOD STEP (SN)	CRACKED	638.00	480.00
			638.00	480.00
	<u>LABOUR</u>			
	LABOUR TO REMOVE & REFIT AIRCON SYSTEM, TOP UP & VACUUM AIRCON GAS.	NOT NECESSARY	200.00	-
	LABOUR TO REMOVE & REFIT WIPER MOTOR, ARM, BLADE.	NOT NECESSARY	180.00	-
	LABOUR TO CHARGE & REMOVE & REFIT & DISMANTLE & WELD & CUT & RENEW ALL ABOVE PARTS. INCLUSIVE OF THE REPAIR OF WIPER PANEL, INNER PANEL AND INNER PANEL REINFORCEMENT.		3,500.00	1,200.00
	TO SPRAY & PAINTING AT ACCIDENT DENTED AREA.		1,600.00	1,400.00
	TO RUST PROOFING AT ACCIDENT DENTED AREA.		100.00	50.00
	LABOUR TO DISMANTLE & RENEW REAR TIPPER WOOD.		550.00	200.00
GRAND TOTAL			32,049.88	15,074.71

RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION)			12,000.00
---	--	--	------------------

Report Ref No. CS/LPC20004904/Uvd3n2

CHUA KANG SENG

Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.