

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)
 51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park
 Singapore 408933
 Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS/AIG20004905/KCF3Q2
Date: 05/03/2021

REFERENCE

Handling Insurer: AIG Asia Pacific Insurance Pte. Ltd.	Policy No: 1800040981	
Claimant Vehicle No : SMG7745Y	Insured Vehicle No : SKS5549X	
Date of Loss: 31/03/2020	Nature of Claim: TP	Claim No: 7293255132SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: SMG7745Y		
Make & Model: TOYOTA SIENTA, 1.5 (A)	Engine No: 2NRX397779	
Reg. Date: 31/12/2018 (Man. Year: 2018)	Chassis No: MHFZ28H3100059934	
Colour: Metallic Black	Odometer: 66987 km	
Engine Capacity: 1496 cc		
Market Value/New Car Price: N/A		
Sum Insured (S\$): Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable): Yes	Footbrake (Serviceable): Yes
Handbrake (Serviceable): Yes	Engine Modification: No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 195/65R15	Rear Tyre Size: 195/65R15	
Front Left Side: Yokohama 7 mm	Rear Left Side: Yokohama 7 mm	
Front Right Side: Yokohama 7 mm	Rear Right Side: Yokohama 7 mm	

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	7,981.00	3,290.22	4,690.78	58.77
Miscellaneous Items	0.00	0.00	0.00	
Labour	3,930.00	1,890.00	2,040.00	51.91
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	11,911.00	5,180.22	6,730.78	56.51
Approved Total (Overridden) (S\$)		4,100.00		
Nett Amount (S\$)	11,911.00	4,100.00	7,811.00	65.58

INSPECTION

Date of Assignment: 03/04/2020		
Date Inspected: 04/04/2020	Inspected At: Blk 160 Sin Ming Drive #08-13 Sin Ming Auto City	
Estimated Period of Repair: 6.0 days	Repairer: Heng Yap Seng Auto Services	

Adjuster: KENNETH KONG

Manager: CELINE FONG

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*REAR BUMPER (LH+CENTRE+RH)	Buckled	807.10 F	*807.10 FL
2	2		*REAR BUMPER RETAINERS	Serviceable	85.30 F	*- FL
3	2		*REAR BUMPER BRACKETS	Repair	110.20 F	*- FL
4	2		*REAR BUMPER REFLECTORS	Serviceable	106.90 F	*- FL
5	1		*SET REAR BUMPER CLIPS	Necessary	40.00 F	*40.00 FL
6	1		*REAR TAILGATE	Bent	1,040.40 F	*1,040.40 FL
7	1		*REAR TAILGATE CENTRE LOGO	Necessary	45.90 F	*45.90 FL
8	1		*REAR TAILGATE OUTER CHROME HANDLE	Warped	108.30 F	*108.30 FL
9	1		*REAR TAILGATE LOCK	Dented	359.50 F	*359.50 FL
10	2		*REAR TAILGATE HINGES	Repair	133.60 F	*- FL
11	2		*REAR TAILGATE DAMPERS	Serviceable	209.10 F	*- FL
12	1		*REAR TAILGATE WEATHERSTRIP	Dented/Cut	168.50 F	*168.50 FL
13	1		*REAR TAILGATE G EMBLEM	Necessary	43.20 F	*43.20 FL
14	1		*REAR TAILGATE SIENTA EMBLEM	Necessary	78.10 F	*78.10 FL
15	1		*REAR TAILGATE WIPER ARM	Serviceable	201.90 F	*- FL
16	1		*TAIL LAMP (OUTER)	Mtg Cracked	350.90 F	*350.90 FL
17	1		*TAIL LAMP (INNER)	Mtg Cracked	241.10 F	*241.10 FL
18	1		*REAR END PANEL	Bent	617.40 F	*617.40 FL
19	1		*REAR END PANEL TOP GARNISH	Mtg Distorted	219.90 F	*219.90 FL
20	1		*REAR FLOOR PANEL	Repair	706.30 F	*- FL
21	1		*REAR SPARE TYRE TOP BOARD	Serviceable	599.40 F	*- FL
22	1		*REAR EXHAUST SILENCER	Repair	1,012.10 F	*- FL
23	1		*REAR EXHAUST SILENCER MOUNTING	Serviceable	85.90 F	*- FL
24	1		*REAR NUMBER PLATE	Serviceable	60.00 FS	*- FS
25	1		*SET REVERSE SENSOR	Dented/Shorted	300.00 FS	*200.00 FS
26	1		*REVERSE CAMERA	Serviceable	250.00 FS	*- FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (\$\$)	7,981.00	4,320.30
- List Item Discount on L Items 0.00/25.00% (\$\$)	0.00	1,030.08
Total Parts (\$\$)	7,981.00	3,290.22

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	LABOUR CHARGE TO REMOVE,CUT OUT DAMAGE PORTION,JACK OUT,STRAIGHTEN,PANEL BEATING,WELDING,ALIGN AND RENEW REPLACED PARTS	New	1,500.00	800.00
2	TO PUTTY AND RESPRAY PAINTING ON AFFECTED AREAS	New	1,200.00	800.00
3	TO REMOVE,REPLACE REAR TAILGATE FITTINGS TO FACILITATE REPAIR	New	350.00	60.00
4	TO REMOVE,REPLACE REAR WINDSCREEN GLASS	New	200.00	120.00
5	TO REMOVE,REPLACE REVERSE CAMERA	New	200.00	40.00
6	TO REMOVE,REPLACE REVERSE SENSOR	New	150.00	50.00
7	TO REMOVE,REPLACE REAR EXHAUST SILENCER	New	250.00	0.00
8	TO CHECK WIRING AND LIGHTINGS	New	80.00	20.00
Gross Labour Cost (S\$)			3,930.00	1,890.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >