

LKK Auto Consultants Pte Ltd

(Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CC4/AIG20004924/KEA3Q2

Date: 07/09/2020

REFERENCE

Handling Insurer: AIG Asia Pacific Insurance Pte. Ltd. Policy No: 1800078309

Claimant
Vehicle No : SMA9134D **Insured Vehicle No :** SMC5043Z

Date of Loss: 03/04/2020 Nature of Claim: TP Claim No: 7224864526SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SMA9134D		
Make & Model:	HONDA SHUTTLE HYBRID, 1.5 (A)	Engine No:	LEB6556249
Reg. Date:	22/06/2018 (Man. Year: 2018)	Chassis No:	GP71213372
Colour:	Metallic Pearl White	Odometer:	33354 km
Engine Capacity:	1496 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	185/60 R15	Rear Tyre Size:	185/60 R15
Front Left Side:	Bridgestone 7 mm	Rear Left Side:	Bridgestone 5 mm
Front Right Side:	Bridgestone 7 mm	Rear Right Side:	Bridgestone 5 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	7,238.40	3,104.96	4,133.44	57.10
Miscellaneous Items	0.00	0.00	0.00	
Labour	2,300.00	1,360.00	940.00	40.87
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	9,538.40	4,464.96	5,073.44	53.19
Approved Total (Overridden) (S\$)		3,550.00		
(S\$)	9,538.40	3,550.00	5,988.40	62.78
+ GST 7.00/7.00% (S\$)	667.69	248.50	419.19	62.78
Nett Amount (S\$)	10,206.09	3,798.50	6,407.59	62.78
+ Car Rental (6.0 x S\$100.00/day + 7.00% GST) (S\$)		642.00		
+ Doc/Search Fee (S\$)		31.00		
Nett Liability (S\$)		4,471.50		

INSPECTION

Date of Assignment: 06/04/2020

Date Inspected: 07/04/2020 Inspected At:

MBM Wheelpower Pte Ltd (HQ)
160 Sin Ming Drive #06-02, Sin Ming
AutoCity
Singapore 575722

Estimated Period of Repair: 4.0 days

Adjuster: KENNETH KONG**Manager:** Asher Sng Rong Yi

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*REAR WINDSCREEN MOULDING	Necessary	166.00 FL	*120.00 FL
2	1		*TAIL GATE	Bent	1,432.00 FL	*1,193.00 FL
3	1		*TAIL GATE WEATHERSTRIP	Distorted	220.00 FL	*220.00 FL
4	1		*TAIL GATE LOCK	Repair	308.00 FL	*- FL
5	1		*TAIL GATE SHUTTLE EMBLEM	Necessary	76.00 FL	*76.00 FL
6	1		*TAIL GATE HYBRID EMBLEM	Necessary	92.00 FL	*92.00 FL
7	1		*TAIL GATE HONDA LOGO	Necessary	70.00 FL	*70.00 FL
8	1		*TAIL GATE CHROME TRIM	Serviceable	420.00 FL	*- FL
9	1		*TAIL GATE INNER MOULDING	Serviceable	350.00 FL	*- FL
10	1		*TAIL GATE LAMP LH	Serviceable	480.00 FL	*- FL
11	1		*TAIL GATE LAMP RH	Serviceable	480.00 FL	*- FL
12	1		*TAIL LAMP LH	Serviceable	550.00 FL	*- FL
13	1		*TAIL LAMP RH	Cut	550.00 FL	*460.00 FL
14	1		*REAR BUMPER	Buckled	1,390.00 FL	*1,150.20 FL
15	10		*REAR BUMPER CLIPS	Necessary	50.00 FL	*50.00 FL
16	1		*REAR BUMPER RH REFLECTOR PLATE	Serviceable	75.00 FL	*- FL
17	1		*REAR BUMPER LH REFLECTOR PLATE	Serviceable	75.00 FL	*- FL
18	1		*REAR BUMPER RH REFLECTOR	Serviceable	187.00 FL	*- FL
19	1		*REAR BUMPER LH REFLECTOR	Serviceable	187.00 FL	*- FL
20	1		*REAR BUMPER RH TOW COVER	Serviceable	40.00 FL	*- FL
21	1		*END PANEL CENTRE	Serviceable	160.00 FL	*- FL
22	1		*END PANEL LH	Repair	650.00 FL	*- FL
23	1		*END PANEL RH	Repair	160.00 FL	*- FL
24	1		*END PANEL TOP GARNISH	Serviceable	180.00 FL	*- FL
25	1		*BODY SEALANT	Not Necessary	80.00 FS	*- FS
26	1		*SET REVERSE SENSORS	Dented	400.00 FS	*320.00 FS
27	1		*WINDSCREEN SEALANT	Necessary	80.00 FS	*40.00 FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (S\$)	8,908.00	3,791.20
- List Item Discount on L Items 20.00/20.00% (S\$)	1,669.60	686.24
Total Parts (S\$)	7,238.40	3,104.96

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<u>Labour Items</u>				
1	TO REMOVE,REFIT & REPAIR AFFECTED DAMAGED PARTS .INCLUDING TO KNOCK -OUT ,WELD & STRAIGHTEN ON THE AFFECTED PARTS	New	1,200.00	500.00
2	TO REMOVE AND REFIT REAR WINDSCREEN	New	150.00	120.00
3	TO DISMANTLE & TRANSFER TAIL GATE FITTINGS & MECHANISM TO NEW TAILGATE /FACILITATE REPAIR	New	80.00	60.00
4	TO REMOVE,REFIT & UPHOLSTERY TO FACILITATE REPAIRS	New	150.00	60.00
5	TO REMOVE & REPLACE BUMPER SENSORS	New	40.00	40.00
6	TO CHECK & RECONNECT ALL NECESSARY WIRING	New	80.00	20.00
7	TO SPRAY PAINT ON THE AFFECTED AREAS	New	600.00	560.00
Gross Labour Cost (\$\$)			2,300.00	1,360.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >