



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

TAX INVOICE

EQ INSURANCE COMPANY LTD
5 MAXWELL ROAD
#17-00 TOWER BLOCK
MND COMPLEX
SINGAPORE 069110

INV No. AC2005514
INV Date 12/08/2020
Reference CC4/EQI20004925/Uea3q2
Code EQI



PROFESSIONAL SERVICE FEE

Vehicle No. SLF 5940E
Insured Veh. YN 9905K
Claim No. DM20HO00684-JG
Policy No. DMCPHQ19-004922
Accident Date 03/04/2020
Inspection Date 06/04/2020

Description	Total
Third Party Express Settlement	400.00
Subtotal	400.00
GST (7%)	28.00
Grand Total	428.00

We shall be glad if you could forward the payment at your early convenience.

Cheque should be crossed and made payable to 'LKK Auto Consultants Pte Ltd'

LKK Auto Consultants Pte Ltd



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile

EQ INSURANCE COMPANY LTD

Ref : CC4/EQI20004925/Uea3q2

5 MAXWELL ROAD
#17-00 TOWER BLOCK
MND COMPLEXSINGAPORE 069110

Date : 12-08-2020



Code : EQI

1. Policy Particulars :- THIRD PARTY CLAIM

Insured Veh.	YN 9905K	Veh. Inspected	SLF 5940E
Policy No.	DMCPHQ19-004922	Coverage (\$)	0.00
Claim No.	DM20HO00684-JG	Excess (\$)	0.00
Assign From	JOEL	Assign Date	03/04/2020

2. Vehicle Particulars & Condition

Make & Model	TOYOTA VIOS (A)	c.c	1497
Engine No.	HIDDEN	Year of Reg.	2005
Chassis No.	MR053HY4204153720	Colour	SILVER
Odometer	273397	Steering	IN ORDER
Brakes	IN ORDER	Modification	SPORTS RIM
General	GOOD		

3. Conditions of Tyres

	Size	Make	Balance
R/H Front Tyre	185/60 R14	MICHELIN	6 mm
L/H Front Tyre	185/60 R14	MICHELIN	6 mm
R/H Rear Tyre	185/60 R14	MICHELIN	6 mm
L/H Rear Tyre	185/60 R14	MICHELIN	6 mm

4. Description of Damages

THE VEHICLE SUSTAINED DAMAGES AT THE REAR PORTION. DAMAGES SEE DETAILS.
--

5. General Information

Accident Date	03/04/2020	Inspection Date	06/04/2020
Survey held at	ZOOM AUTOWERKS PTE LTD 832 SIMS AVENUE #12-884 EUNOSVILLE SINGAPORE 400832		

5a. Remarks

A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.
--

5b. Estimate Days of Repair

ESTIMATED NORMAL PERIOD FOR REPAIR:	4 Working Days
-------------------------------------	----------------



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 2

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SLF 5940E

Qty	Description of Parts	Condition	Estimate By Workshop (\$))	Our Adjusted (\$)
<u>REPLACEMENT OF PARTS</u>				
1	REAR BUMPER	DEFORMED / TORN	758.40	322.01
2	REAR BUMPER SIDE RETAINER @\$65.00	NOT NECESSARY	130.00	-
2	REAR BUMPER BRACKET @\$78.00	NOT NECESSARY	156.00	-
2	REAR BUMPER LOWER SIDE GARNISH @\$168.00	NOT NECESSARY	336.00	-
1	REAR BUMPER CLIPS	NECESSARY	60.00	50.00
1	REAR BOOTLID PANEL	DENTED / BENT	799.40	655.10
1	REAR BOOTLID CENTRE GARNISH	CRACKED	198.70	198.70
1	REAR BOOTLID INNER LOCK	NOT NECESSARY	195.80	-
1	REAR BOOTLID CATCH	NOT NECESSARY	58.70	-
1	REAR BOOTLID LOGO	NECESSARY	75.90	48.50
2	REAR TAILLAMPS @\$699.60	NOT NECESSARY	1,399.20	-
1	REAR LEFT TAILLAMP PANEL	NOT NECESSARY	385.70	-
1	REAR END PANEL	TO REPAIR SEE LABOUR	756.70	-
1	REAR END PANEL TOP GARNISH	NOT NECESSARY	165.80	-
1	REAR END PANEL TOP GARNISH CLIPS	NOT NECESSARY	60.00	-
1	REAR LEFT FENDER (NPA)	NOT NECESSARY	-	-
2	REAR FENDER INNER TRIM GARNISH @\$385.70	NOT NECESSARY	771.40	-
1	REAR FENDER INNER TRIM GARNISH CLIPS	NOT NECESSARY	80.00	-
2	REAR FENDER INNER SHIELD @\$176.00	NOT NECESSARY	352.00	-
1	REAR LEFT FENDER INNER SHIELD CLIPS	NOT NECESSARY	80.00	-
1	REAR SPARE TYRE TOP GARNISH	NOT NECESSARY	265.40	-
2	REAR SPARE TYRE TOP FOAM @\$325.60	NOT NECESSARY	651.20	-
1	REAR SPARE TYRE PANEL	NOT NECESSARY	980.00	-
	LESS 25% DISCOUNT		-2,179.08	-318.58
			6,537.22	955.73
<u>SPECIAL NETT ITEMS</u>				
1	REAR BOOTLID PANEL TOP SPOILER SEALANT (SN)	NOT NECESSARY	80.00	-
1	REAR TAILLAMP PANEL SEALANT (SN)	NOT NECESSARY	60.00	-
1	REAR END PANEL SEALANT (SN)	NOT NECESSARY	80.00	-
1	REAR SPARE TYRE PANEL SEALANT (SN)	NOT NECESSARY	80.00	-

Report Ref No. CC4/EQI20004925/Uea3q2



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:2 of 2

Qty	Description of Parts	Condition	Estimate By Workshop (\$))	Our Adjusted (\$)
1	REAR NUMBER PLATE W/BASE GARNISH (SN)	NOT NECESSARY	80.00	-
1	SET REVERSE SENSOR (SN)	SHORTED	280.00	200.00
			660.00	200.00
	LABOUR			
	TO REMOVE,REPAIR & RENEW REAR AFFECTED ACCIDENT AREAS.INCLUSIVE OF THE REPAIR OF REAR END PANEL.		1,400.00	400.00
	TO PUTTY,SPRAY PAINT ON AFFECTED ACCIDENT AREAS.		1,400.00	600.00
	TO CHECK & RE-CONNECT ALL ELECTRICAL WIRING.		50.00	20.00
	TO REMOVE & INSTALL REAR BOOTLID COMPONENTS TRIM & GARNISH.		150.00	50.00
	TO REMOVE & INSTALL REAR FENDERS TRIM,GARNISH.		150.00	60.00
	TO CONDUCT WATER LEAKAGE TEST.	NOT NECESSARY	150.00	-
	TO RUST PROOF AFFECTED AREAS.		200.00	30.00
			3,500.00	1,160.00
GRAND TOTAL			10,697.22	2,315.73
RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION)				1,850.00

Report Ref No. CC4/EQI20004925/Uea3q2

CHUA KANG SENG

Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or replying on this Report, in whole or in part, does so at his or her own risk.



LKK Auto Consultants Pte Ltd

S1 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3581 FAX: 6256 4315

Reg No: 199607198R GST Reg. No. 19-9607198-R

PHOTOGRAPHS FOR VEHICLE NO. SLF 5940E

INSPECTION





LKK Auto Consultants Pte Ltd

S1 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3551 FAX: 6256 4315

Reg No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

S1 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3551 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

S1 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3551 FAX: 6256 4315

Reg No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

S1 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3581 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

S1 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3551 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

S1 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3551 FAX: 6256 4315

Reg No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

S1 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3551 FAX: 6256 4315

Reg No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

S1 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3581 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

S1 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3551 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

S1 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3551 FAX: 6256 4315

Reg No: 199607198R GST Reg. No. 19-9607198-R

PHOTOGRAPHS FOR VEHICLE NO. SLF 5940E

RE-INSPECTION

