

# LKK Auto Consultants Pte Ltd

(Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

## VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS3/MSG20003606/ETF3E2-1

Date: 15/04/2020

### REFERENCE

Handling Insurer: MSIG Insurance (Singapore) Pte. Ltd.

Policy No: 1001293489

Claimant Vehicle No : YQ1030X

Insured Vehicle No : YP1125L

Date of Loss: 02/03/2020

Nature of Claim: TP

Claim No: 239838

### DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: YQ1030X

Make &amp; Model: ISUZU NPR85UH5A, 3.0 D (M)

Engine No: 4JJ13V8518

Reg. Date: 24/06/2019 (Man. Year: 2018)

Chassis No: JAANPR85HJ7100659

Colour: White

Odometer: 35199 km

Engine Capacity: 2999 cc

Market Value/New Car Price: N/A

Sum Insured (S\$): Market Value/New Car Price

### CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable):

Yes

Footbrake (Serviceable):

Yes

Handbrake (Serviceable): Yes Engine Modification:

No

Pre-accident Condition:

### CONDITION OF TYRES

Front Tyre Size: 205/85 R16

Rear Tyre Size: 205/85 R16

Front Left Side: Hankook 5 mm

Rear Left Side: Hankook 5 mm

Front Right Side: Hankook 5 mm

Rear Right Side: Hankook 5 mm

*The above values represent the remaining tyre treads depth*

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	3,232.40	3,065.65	166.75	5.16
Miscellaneous Items	0.00	0.00	0.00	
Labour	2,460.00	1,260.00	1,200.00	48.78
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
<b>Gross Total (S\$)</b>	<b>5,692.40</b>	<b>4,325.65</b>	<b>1,366.75</b>	<b>24.01</b>
<b>+ GST 7.00/7.00% (S\$)</b>	<b>398.47</b>	<b>302.80</b>	<b>95.67</b>	<b>24.01</b>
<b>Nett Amount (S\$)</b>	<b>6,090.87</b>	<b>4,628.45</b>	<b>1,462.42</b>	<b>24.01</b>

### INSPECTION

Date of Assignment: 04/03/2020

Date Inspected: 05/03/2020 Inspected At:

Carport Auto Service (HQ)

Block 3, Pioneer Road North, #01-24

Singapore 628457

Estimated Period of Repair: 5.0 days

Adjuster: CHEN TSUE YEE

Manager: DENISE TAY KWEE CHENG

*NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.*

## REPAIR DETAILS

### Reference

<b>Part Source:</b>	(Last Synchronised: 15 Apr 2020)	
<b>Parts:</b>	N/A	ISUZU NPR85UH5A 3.0 D (M) (Model not available in database)
<b>Labour:</b>	Repairer's	(Price-denominated Standard List)
<b>Print Code:</b>	(Unsubmitted, no print-code for YQ1030X)	
<b>Validity:</b>	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
<b>Further Info:</b>	Items/values not in reference catalogue are prefixed with an asterisk *.	

### Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FRONT PANEL	Dented	821.60 FL	*821.60 FL
2	1		*FRONT PANEL EMBLEM ISUZU	Necessary	118.00 FL	*118.00 FL
3	1		*FRONT BUMPER	Cut	680.50 FL	*680.50 FL
4	1		*FRONT BUMPER BRACKET LH	Repair	155.00 FL	*- FL
5	1		*FRONT GRILLE	Broken	411.20 FL	*411.20 FL
6	1		*FRONT SIDE LAMP LH	Broken	296.50 FL	*296.50 FL
7	1		*FRONT HEADLAMP LH	Broken	311.25 FL	*311.25 FL
8	1		*FRONT CORNER PANEL LH	Broken	301.50 FL	*301.50 FL
9	1		*FRONT MIRROR BRACKET LH	Bent	315.60 FL	*315.60 FL
10	1		*FRONT MIRROR BRACKET COVER LH	Broken	61.20 FL	*61.20 FL
11	1		*FRONT VIEW MIRROR LH	Cut	155.40 FL	*155.40 FL
12	1		*FRONT ROUND MIRROR LH	Missing	98.60 FL	*98.60 FL
13	1		*SET CLIP & RIVET	Necessary	65.00 FS	*30.00 FS
					<b>Sub Total (\$\$)</b>	<b>3,791.35</b>
					<b>- List Item Discount on L Items 15.00/15.00% (\$\$)</b>	<b>558.95</b>
					<b>Total Parts (\$\$)</b>	<b>3,232.40</b>
						<b>3,065.65</b>

F=Franchise part. S=SpcNett. L=ListItemDisc.

Report was unsubmitted during this print-out.

## Recommended Miscellaneous Items

There are no new miscellaneous items selected.

## Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<b><u>Labour Items</u></b>				
1	TO CHECK FRONT ELECTRICAL WIRING & REFOCUS HEADLAMP	New	60.00	30.00
2	TO RESPRAY PAINTING & ETC	New	1,100.00	500.00
3	PANEL BEATING, REMOVE & REPLACING ABOVE PARTS	New	1,200.00	700.00
4	TO SPRAY ANTI RUST ON AFFECTED AREA	New	100.00	30.00
<b>Gross Labour Cost (S\$)</b>			<b>2,460.00</b>	<b>1,260.00</b>

Report was unsubmitted during this print-out.

< END OF ESTIMATES >