

Constant Appraiser Services

Qualified Automobile Accident Damage Appraisers/Loss Adjusters

Blk 2 Rivervale Link, #09-02 Singapore 545040

Tel/Fax: 6886 1106 Mobile: 9007 5234

Email: constant_as@yahoo.com.sg

RCB No. 53138015K

Automobile Inspection Report

To: Tiong Lian Food Pte Ltd c/o Blk 3, Pioneer Road North #01-24 Singapore 628457	Date : 13/03/2020 Reference No : CAS/20-03/009																				
<u>General Information</u> Registration No. : YQ 1030X Accident Date : 02/03/2020																					
<u>Particulars of Damaged Vehicle</u> <table><tr><td>Colour</td><td>: White</td><td>Make & Model</td><td>: Isuzu NPR85UH5A</td></tr><tr><td>Engine Capacity</td><td>: 2999 cc</td><td>Pre-Accident Condition</td><td>: Good</td></tr><tr><td>Mileage (KM)</td><td>: 35199</td><td>Engine No.</td><td>: 4JJ13V8518</td></tr><tr><td>Chassis No.</td><td>: JAANPR85HJ7100659</td><td>Steering</td><td>: In Order</td></tr><tr><td>Registration Date</td><td>: 24/06/2019</td><td>Brake</td><td>: In Order</td></tr></table>		Colour	: White	Make & Model	: Isuzu NPR85UH5A	Engine Capacity	: 2999 cc	Pre-Accident Condition	: Good	Mileage (KM)	: 35199	Engine No.	: 4JJ13V8518	Chassis No.	: JAANPR85HJ7100659	Steering	: In Order	Registration Date	: 24/06/2019	Brake	: In Order
Colour	: White	Make & Model	: Isuzu NPR85UH5A																		
Engine Capacity	: 2999 cc	Pre-Accident Condition	: Good																		
Mileage (KM)	: 35199	Engine No.	: 4JJ13V8518																		
Chassis No.	: JAANPR85HJ7100659	Steering	: In Order																		
Registration Date	: 24/06/2019	Brake	: In Order																		
<u>Tyre Condition</u> <table><thead><tr><th></th><th>Size</th><th>Make</th><th>Balance</th></tr></thead><tbody><tr><td>R/H Front Tyre</td><td>205/85R16</td><td>HANKOOK</td><td>90%</td></tr><tr><td>L/H Front Tyre</td><td>205/85R16</td><td>HANKOOK</td><td>90%</td></tr><tr><td>R/H Rear Tyre</td><td>195/85R16 (D)</td><td>YOKOHAMA</td><td>60% / 60%</td></tr><tr><td>L/H Rear Tyre</td><td>195/85R16 (D)</td><td>YOKOHAMA</td><td>60% / 60%</td></tr></tbody></table>			Size	Make	Balance	R/H Front Tyre	205/85R16	HANKOOK	90%	L/H Front Tyre	205/85R16	HANKOOK	90%	R/H Rear Tyre	195/85R16 (D)	YOKOHAMA	60% / 60%	L/H Rear Tyre	195/85R16 (D)	YOKOHAMA	60% / 60%
	Size	Make	Balance																		
R/H Front Tyre	205/85R16	HANKOOK	90%																		
L/H Front Tyre	205/85R16	HANKOOK	90%																		
R/H Rear Tyre	195/85R16 (D)	YOKOHAMA	60% / 60%																		
L/H Rear Tyre	195/85R16 (D)	YOKOHAMA	60% / 60%																		
<u>Inspection</u> Repairer : Carport Auto Service Blk 3, Pioneer Road North, #01-24, Singapore 628457																					
<u>Adjustment And Recommendation Cost Of Repair</u> Repairer's Estimate : \$5,692.40 Revised Amount : \$4,970.65 Less Excess : - Nett Total : \$4,970.65																					
<u>Remarks</u> (A) Survey was done on 03/03/2020 (B) Re-survey before paint was done on 06/03/2020 (C) Re-survey after repair was done on 10/03/2020 (D) The survey was conducted entirely on WITHOUT PREJUDICE basis. (E) We have NOT given any instruction to authorize the repair of the vehicle.																					

NOTE: The revised estimate was made from a visual inspection. Should there be any discrepancy or unseen damage/item in this survey, kindly notified the company within 7 (seven) days from the date hereof. Otherwise, the revised amount shall be deem to be valid.

Adjustment On Repair Costs And Replacement Of Parts:

S/No	Qty	Descriptions	Assessed Condition	Estimate by Workshop (\$)	Revised Amount (\$)
		<u>PARTS REPLACEMENT – LIST ITEMS</u>			
1	1pc	Front panel ✓ DD	Dented/Warped	821.60	821.60
2	1pc	Front panel emblem 'Isuzu' ✓ NEC	Necessary	118.00	118.00
3	1pc	Front bumper ✓ CUT	Dented/Deformed	680.50	680.50
4	1pc	Front bumper bracket LH ✗ NN	Repair	155.00	-
5	1pc	Front grille ✓ BR	Broken	411.20	411.20
6	1pc	Front side lamp LH ✓ BR	Broken	296.50	296.50
7	1pc	Front headlamp LH ✓ BR	Broken	311.25	311.25
8	1pc	Front corner panel LH ✓ BR	Broken	301.50	301.50
9	1pc	Front mirror bracket LH ✓ BT	Dented/Bent	315.60	315.60
10	1pc	Front mirror bracket cover LH ✓ BR	Broken	61.20	61.20
11	1pc	Front view mirror LH ✓ CUT	Grazed/Cut	155.40	155.40
12	1pc	Front round mirror LH ✓ MIS	Missing	98.60	98.60
				3,726.35	3,571.35
		Less 15%		(558.95)	(535.70)
		Sub total		3,167.40	3,035.65
		<u>PARTS REPLACEMENT – SPECIAL NETT ITEMS</u>			
1	1set	Clip & rivet set ✓ NEC	Necessary	65.00	65.00 30 ✓
		Sub total		3,232.40	3,100.65
		<u>LABOUR & MISC. CHARGES</u>			
1		To check front electrical wiring & refocus headlamp		60.00	30.00 ✓
2		To respray painting & etc		1,100.00	800.00 500 ✓
3		Panel beating, remove & replacing above parts		1,200.00	1,000.00 700 ✓
4		To spray anti rust on affected area		100.00	40.00 30 ✓
		Grand total		5,692.40	4,970.65

5 repair days


Adjustment/Recommendations

We have thoroughly inspected each and every item on the estimate against the physical damage found on the vehicle and we have listed the breakdown of our finding and our recommendation.

The repairer has agreed to undertake the job at our adjusted amount of **\$4,970.65** corresponding to labour charge, spray painting and replacement of parts. Under normal circumstances, the repair period would be about **7 (Seven)** working days.

Yours faithfully,

Constant Appraiser Services



Lim Yong Tian (Sebastian)
Licensed Appraiser
Adv. Dip. In Mechanical Engineering (AUS)
MSAAA

Constant Appraiser Services

Qualified Automobile Accident Damage Appraisers/Loss Adjusters

Blk 2 Rivervale Link, #09-02 Singapore 545040

Tel/Fax: 6886 1106 Mobile: 9007 5234

Email: constant_as@yahoo.com.sg

RCB No. 53138015K

INVOICE

To: Tiong Lian Food Pte Ltd
c/o Blk 3, Pioneer Road North
#01-24
Singapore 628457


Date : 13/03/2020

Invoice No : IV20-03009/CAS

Particulars	Amount
Fee For Services Rendered In Respect Of: Surveying, Adjusting, and Re-inspection Of Accident Damaged Vehicle YQ 1030X (Inclusive Of Photographs And Transport Charges) Our reference : CAS/20-03/009	\$598.00
Total	\$598.00

E. & O.E

Constant Appraiser Services



Cheque Should Be Crossed And Made Payment To 'Constant Appraiser Services'