



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 2

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. FBA 991K

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
REPLACEMENT OF PARTS				
1	FRONT FENDER	TO REPAIR SEE LABOUR	155.00	-
2	FRONT FORK @\$340.00	TO REPAIR SEE LABOUR	680.00	-
1	FRONT FORK CLAMP	TO REPAIR SEE LABOUR	180.00	-
1	METER CASING (BLACK)	SCRATCHED	180.00	120.00
1	HEADLAMP	SCRATCHED	310.00	270.00
2	HEADLAMP HOLDER @\$68.00	SCRATCHED	136.00	136.00
1	HANDLEBAR	CRUMPLED	130.00	130.00
1	REAR MUDGUARD	CRUMPLED	78.00	78.00
1	TAIL LIGHT	SERVICEABLE	310.00	-
1	TAIL BOARD	SERVICEABLE	235.00	-
1	REAR ABSORBER R/H	SCRATCHED	814.00	400.00
1	FOOTREST LONG BRACKET (LEFT)	CRACKED	130.00	75.00
1	FOOTREST LONG BRACKET (RIGHT)	SERVICEABLE	130.00	-
1	PILLION FOOTPEG BRACKET (LEFT AND RIGHT)	SERVICEABLE	25.00	-
1	RIDER FOOTREST	SERVICEABLE	35.00	-
1	GEAR SHIFTER	CRUMPLED	95.00	95.00
1	GEAR PEDAL	CRACKED	77.00	77.00
1	SWING ARM	BENT	740.00	740.00
1	CLUTCH LEVER	BENT	95.00	95.00
1	RADIATOR ASSY	BENT	380.00	380.00
1	REAR DISC	SERVICEABLE	160.00	-
1	EXHAUST PIPE YOSHIMURA	BENT	780.00	700.00
1	HANDLE GRIP R/H	SCRATCHED	35.00	35.00
	LESS 10% DISCOUNT		-589.00	-333.10
			5,301.00	2,997.90
SPECIAL NETT ITEMS				
1	SET ENGINE GUARD R/H (SN)	BENT	190.00	150.00
1	FRONT SIGNAL LAMP R/H (SN)	CRACKED	75.00	75.00

Report Ref No. CS3/AIG20001167/Htf3e2-1



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:2 of 2

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
1	REAR SIGNAL LAMP (SN)	SERVICEABLE	75.00	-
1	FORK OIL (SN)	NECESSARY	20.00	20.00
1	FORK SEAL (SN)	NECESSARY	40.00	20.00
1	4L ENGINE OIL (SN)	SERVICEABLE	60.00	-
1	OIL FILTER (SN)	SERVICEABLE	15.00	-
			475.00	265.00
	LABOUR			
	TO CARRY OUT BODY FRAME ALIGNMENT.		350.00	80.00
	TO REMOVE / REPLACE & DAMAGED PARTS & COMPONENTS. INCLUSIVE OF THE REPAIR OF FRONT FENDER, FRONT FORK AND FRONT FORK CLAMP.		500.00	320.00
	TO RESPRAY REPLACED & AFFECTED PARTS.		500.00	200.00
			1,350.00	600.00
	GRAND TOTAL		7,126.00	3,862.90
	RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION)			3,100.00

Report Ref No. CS3/AIG20001167/Htf3e2-1

LEE HOCK ANN

Asst. Automotive Assessor

ADRIAN LING WAI PING

B.Eng,AMSOE,AMIRTE,AMSAE-A,M.MATAI

Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.