

LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 3

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SKH 5885H

Qty	Description of Parts	Condition	Estimate By Workshop (\$))	Our Adjusted (\$)
	REPLACEMENT OF PARTS			
1	BOOTLID (CONSISTENT)	BADLY DENTED	2,481.10	1,766.32
1	BOOTLID REAR LOGO (CONSISTENT)	NECESSARY	60.00	60.00
1	BOOTLID 'G-TRONIC' EMBLEM (CONSISTENT)	NECESSARY	82.00	82.00
1	BOOTLID 'C180' EMBLEM (CONSISTENT)	NECESSARY	85.00	85.00
1	BOOTLID 'C&C' EMBLEM (CONSISTENT)	NECESSARY	45.00	45.00
1	BOOTLID CHROME MOULDING (CONSISTENT)	BENT / CRACKED	361.10	215.00
1	BOOTLID WEATHERSTRIP (CONSISTENT)	TWISTED	366.20	299.00
1	BOOTLID INNER LOCK (CONSISTENT)	TWISTED	491.10	289.20
1	BOOTLID INNER TRIM (CONSISTENT)	DEFORMED / TORN	650.20	431.10
1	SET BOOTLID INNER TRIM CLIPS (CONSISTENT)	NECESSARY	60.00	60.00
2	BOOTLID HINGES @\$185.00 (CONSISTENT)	BENT	370.00	370.00
2	TAILLAMPS @\$850.00 (CONSISTENT)	BROKEN	1,700.00	1,190.00
2	TAILLAMP SIDE GARNISH @\$30.00 (CONSISTENT)	TORN	60.00	60.00
1	REAR BUMPER (CONSISTENT) }	DISTORTED	1,906.10	1,415.20
1	REAR BUMPER TOW COVER (CONSISTENT)		60.00	-
1	SET REAR BUMPER CENTRE CHROME MOULDING (CONSISTENT)	BENT	488.20	425.00
2	REAR BUMPER SIDE HOLDERS @\$250.00 (CONSISTENT)	NOT NECESSARY	500.00	-
1	SET REAR BUMPER CLIPS (CONSISTENT)	NECESSARY	60.00	60.00
1	REAR BUMPER LOWER GARNISH (CONSISTENT)	NOT FITTED	620.00	-
1	REAR BUMPER REINFORCEMENT (CONSISTENT)	BENT	815.00	605.00
1	REAR BUMPER TOP RETAINER (CONSISTENT)	CRACKED / TWISTED	216.90	184.00
2	REAR BUMPER LOWER BRACKETS @\$105.00 (CONSISTENT)	NOT NECESSARY	210.00	-
6	REAR BUMPER PDC SENSORS @\$250.00(CONSISTENT)	CRACKED (2 PCS ONLY)	1,500.00	390.00
1	REAR BUMPER PDC SENSOR WIRE (CONSISTENT)	SERVICEABLE	388.00	-
1	REAR BUMPER INNER CENTRE GUIDE (CONSISTENT)	NOT NECESSARY	266.20	-
1	REAR END PANEL (CONSISTENT)	BADLY DENTED	1,506.00	981.10
1	REAR END PANEL TOP GARNISH (CONSISTENT)	TWISTED	485.12	311.20
1	REAR FLOOR PANEL (CONSISTENT)	TO REPAIR SEE LABOUR	1,140.60	-

Report Ref No. CC4/ASM20004942/Uka3q2



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:2 of 3

Qty	Description of Parts	Condition	Estimate By Workshop (\$))	Our Adjusted (\$)
1	REAR FLOOR PANEL TOP BOARD (CONSISTENT)	WARPED / DENTED	820.60	611.20
1	REAR FLOOR PANEL FIBRE WELL (CONSISTENT)	NOT NECESSARY	1,020.00	-
1	REAR EXHAUST (CONSISTENT)	NOT NECESSARY	2,115.00	-
1	REAR EXHAUST HEAT SHIELD N/S (CONSISTENT)	NOT NECESSARY	388.00	-
2	REAR FENDERS @\$1800.00 (CONSISTENT)	BADLY DENTED / BUCKLED	3,600.00	3,600.00
2	REAR FENDER INNER TRIMS @\$620.00 (CONSISTENT)	DEFORMED / TORN	1,240.00	1,240.00
	LESS 50% DISCOUNT		-	-7,387.66
			26,157.42	7,387.66
	SPECIAL NETT ITEMS			
1	REAR LICENCE PLATE W/HOLDER (SN) (CONSISTENT)	NOT NECESSARY	50.00	-
1	REAR END PANEL SEALANT (SN) (CONSISTENT)	NECESSARY	80.00	50.00
1	REAR WINDSCREEN SEALANT (SN) (CONSISTENT)	NECESSARY	80.00	40.00
			210.00	90.00
	LABOUR			
	TOWING CHARGE.	NOT NECESSARY	120.00	-
	TO CHECK WIRING .		80.00	30.00
	TO DISMANTLE & REPLACING PDC SENSOR .		100.00	50.00
	TO DISMANTLE & REFIX REAR EXHAUST .	NOT NECESSARY	150.00	-
	TO DISMANTLE & REFIX PETROL TANK .		100.00	60.00
	TO DISMANTLE & REFIX SEAT ,CUSHION UPHOLSTERY.		120.00	100.00
	TO DISMANTLE & REFIX BOOTLID MECHANISM .		100.00	60.00
	TO DISMANTLE & REFIX REAR WINDSCREEN .		150.00	120.00
	TO SPRAY RUST PROOFING .		120.00	100.00
	LABOUR FOR PANEL BEATING ,CUT ,WELD ,STRAIGHTENED & REPLACING PARTS.INCLUSIVE OF THE REPAIR OF REAR FLOOR PANEL.		1,800.00	1,750.00
	TO PUTTY & SPRAY PAINTING.		1,800.00	1,200.00
			4,640.00	3,470.00
	GRAND TOTAL		31,007.42	10,947.66

RECOMMENDED COST OF LUMP SUM REPAIRS		9,500.00
(TO ITS PRE-ACCIDENT CONDITION)		

Report Ref No. CC4/ASM20004942/Uka3q2





Report Ref No. CC4/ASM20004942/Uka3q2

CHUA KANG SENG
Licensed Appraiser