

LKK Auto Consultants Pte Ltd

(Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CC6/AIG20004947/UGA3Q2

Date: 30/06/2020

REFERENCE

Handling Insurer: AIG Asia Pacific Insurance Pte. Ltd. Policy No: 2100414289

Claimant
Vehicle No : SJM7858J **Insured Vehicle No :** SGG5449L

Date of Loss: 04/04/2020 Nature of Claim: TP Claim No: 0955556741SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SJM7858J		
Make & Model:	TOYOTA VIOS, 1.5 E (A)	Engine No:	1NZX856508
Reg. Date:	16/01/2009 (Man. Year: 2008)	Chassis No:	MR053HY9305097921
Colour:	Black	Odometer:	223530 km
Engine Capacity:	1497 cc		
Market Value/New Car Price:	N/A		
Sum Insured (\$\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	195/65 R15	Rear Tyre Size:	195/65 R15
Front Left Side:	Yokohama 6 mm	Rear Left Side:	Yokohama 6 mm
Front Right Side:	Yokohama 6 mm	Rear Right Side:	Yokohama 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	19,766.98	6,533.81	13,233.17	66.95
Miscellaneous Items	0.00	0.00	0.00	
Labour	6,730.00	3,860.00	2,870.00	42.64
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (\$\$)	26,496.98	10,393.81	16,103.17	60.77
Approved Total (Overridden) (\$\$)		8,300.00		
(\$\$)	26,496.98	8,300.00	18,196.98	68.68
+ GST 7.00/7.00% (\$\$)	1,854.79	581.00	1,273.79	68.68
Nett Amount (\$\$)	28,351.77	8,881.00	19,470.77	68.68
+ Car Rental (7.0 x \$100.00/day) (\$\$)		700.00		
+ Doc/Search Fee (\$\$)		2.00		
Nett Liability (\$\$)		9,583.00		
Global Sum Settlement (\$\$)		9,500.00		

INSPECTION

Date of Assignment: 06/04/2020

Date Inspected: 06/04/2020 Inspected At:

Fastech Auto Pte Ltd (HQ)
1 Kaki Bukit Ave 6, #01-46/48/50
Autobay
Singapore 417883

Estimated Period of Repair: 10.0 days

Adjuster: MARCUS CHUA**Manager:** Chong Pui Lin

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*REAR WINDSCREEN MOULDING	Not Necessary	68.10 F	*- FL
2	1		*BOOTLID	Buckled	665.90 F	*665.90 FL
3	1		*BOOTLID REAR LOGO	Necessary	50.20 F	*50.20 FL
4	1		*BOOTLID VIOS EMBLEM	Necessary	46.60 F	*46.60 FL
5	1		*BOOTLID E EMBLEM	Necessary	36.30 F	*36.30 FL
6	1		*BOOTLID SPORT EMBLEM	Not fitted	45.00 F	*- FL
7	1		*BOOTLID OUTER HANDLE	Bent / Cracked	136.00 F	*136.00 FL
8	1		*BOOTLID INNER LOCK	Twisted	100.80 F	*100.80 FL
9	1		*BOOTLID WEATHERSTRIP	Twisted	184.70 F	*184.70 FL
10	2		*BOOTLID HINGES	Bent	137.00 F	*137.00 FL
11	1		*REAR BUMPER	Distorted	427.90 F	*427.90 FL
12	2		*REAR BUMPER SIDE RETAINERS	Not Necessary	93.00 F	*- FL
13	2		*REAR BUMPER BRACKETS	Not Necessary	97.00 F	*- FL
14	2		*REAR BUMPER REFLECTORS	Cracked	212.50 F	*212.50 FL
15	1		*SET REAR BUMPER CLIPS	Necessary	50.00 F	*50.00 FL
16	2		*REAR BUMPER SIDE HOLDERS	Not Necessary	164.50 F	*- FL
17	1		*REAR EXHAUST BOX	Repair	569.05 F	*- FL
18	2		*REAR EXHAUST BOX MOUNTING	Not Necessary	85.00 F	*- FL
19	1		*REAR END PANEL	Badly Dented	539.13 F	*539.13 FL
20	1		*REAR END PANEL TOP GARNISH	Twisted	89.65 F	*89.65 FL
21	1		*REAR FLOOR PANEL	Repair	781.65 F	*- FL
22	1		*REAR FLOOR PANEL TOP BOARD	Torn	156.50 F	*156.50 FL
23	2		*REAR FLOOR PANEL SIDE TOOLS SPONGES	Deformed / Torn	449.60 F	*449.60 FL
24	2		*TAILLAMPS	Cracked	963.30 F	*963.30 FL
25	2		*TAILLAMP HOUSING PANELS	Dented / Bent	210.00 F	*210.00 FL
26	2		*REAR FENDER INNER TRIMS	Not Necessary	573.00 F	*- FL
27	2		*REAR FENDERS	Repair	1,690.20 F	*- FL
28	2		*REAR FENDER LOWER SHIELDS	Not Necessary	117.00 F	*- FL
29	1		*REAR AIR VENT	Not Necessary	32.50 F	*- FL
30	1		*BONNET	Repair	485.30 F	*- FL
31	1		*BONNET INNER LOCK	Twisted	66.50 F	*66.50 FL
32	1		*FRONT BUMPER	Distorted	465.30 F	*465.30 FL
33	1		*FRONT BUMPER CENTRE GRILLE	Cut	86.30 F	*86.30 FL
34	1		*FRONT BUMPER INNER TOP GARNISH	Twisted	130.20 F	*130.20 FL
35	1		*FRONT BUMPER REINFORCEMENT	Dented	385.10 F	*385.10 FL
36	2		*FRONT BUMPER FOG LAMPS	Not Necessary	840.20 F	*- FL
37	1		*SET FRONT BUMPER CLIPS	Necessary	45.00 F	*45.00 FL
38	1		*FRONT GRILLE	Cracked	192.30 F	*192.30 FL
39	1		*FRONT GRILLE LOGO	Necessary	48.50 F	*48.50 FL
40	2		*HEADLAMPS	Cracked	850.20 F	*850.20 FL
41	1		*FRONT SUPPORT PANEL CENTRE	Bent	266.50 F	*266.50 FL
42	2		*FRONT SUPPORT SIDE PANELS	Repair	236.20 F	*- FL
43	1		*AIR CON CONDENSER	Bent / Punctured	1,213.10 F	*1,213.10 FL
44	1		*RADIATOR	Not Necessary	1,499.10 F	*- FL
45	1		*RADIATOR FAN ASSY	Not Necessary	495.10 F	*- FL
46	1		*SET REAR BUMPER REVERSE SENSOR	Shorted	280.00 FS	*200.00 FS
47	1		*REAR BUMPER LOWER SKIRTING	Not fitted	1,080.00 FS	*- FS
48	1		*BOOTLID TOP SPOILER	Not fitted	1,000.00 FS	*- FS
49	1		*REAR LICENCE PLATE W/HOLDER	Cracked	50.00 FS	*40.00 FS
50	1		*REAR EXHAUST CHROME	Not Necessary	50.00 FS	*- FS
51	1		*REAR END PANEL SEALANT	Necessary	50.00 FS	*50.00 FS
52	1		*FRONT LICENCE PLATE W/HOLDER	Cracked	50.00 FS	*40.00 FS
53	1		*FRONT BUMPER LOWER SKIRTING	Not fitted	1,080.00 FS	*- FS

Report was unsubmitted during this print-out.

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
54	1		*BOL RADIATOR COOLANT	Necessary	50.00 FS	*50.00 FS
F=Franchise part. S=SpcNett. L=ListItemDisc.						
					Sub Total (\$)	19,766.98
					8,585.08	
					- List Item Discount on L Items 0.00/25.00% (\$)	0.00
						2,051.27
					Total Parts (\$)	19,766.98
						6,533.81

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<u>Labour Items</u>				
1	TO CHECK WIRING	New	80.00	30.00
2	TO DISMANTLE & REPLACING REVERSE SENSOR	New	80.00	50.00
3	TO TRANSFER BOOTLID COMPARTMENTS	New	100.00	60.00
4	TO DISMANTLE & REPLACING REAR EXHAUST	New	100.00	60.00
5	TO DISMANTLE & REFIX SEAT ,CUSHION UPHOLSTERY	New	120.00	80.00
6	TO DISMANTLE & REFIX PETROL TANK	New	100.00	0.00
7	TO REFILL AIR CON GAS	New	150.00	100.00
8	LABOUR FOR PANEL BEATING ,CUT ,WELD ,STRAIGHTEN & REPLACING PARTS	New	3,000.00	1,680.00
9	TO PUTTY & SPRAY PAINTING	New	3,000.00	1,800.00
Gross Labour Cost (\$\$)			6,730.00	3,860.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >