

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:** CC4/AIG20004951/BPA3Q2**Date:** 16/12/2021REFERENCE

Handling Insurer:	AIG Asia Pacific Insurance Pte. Ltd.	Policy No:	1800141207
Claimant Vehicle No :	GBG9165M	Insured Vehicle No :	SMF9412A
Date of Loss:	05/04/2020	Nature of Claim:	TP
		Claim No:	8803860196SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	GBG9165M		
Make & Model:	TOYOTA HIACE, 3.0 D DX (A)	Engine No:	1KD2749930
Reg. Date:	30/11/2017 (Man. Year: 2017)	Chassis No:	KDH2010233110
Colour:	Silver	Odometer:	114760 km
Engine Capacity:	2982 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	195 R15	Rear Tyre Size:	195 R15
Front Left Side:	Dunlop 7 mm	Rear Left Side:	Bridgestone 7 mm
Front Right Side:	Dunlop 7 mm	Rear Right Side:	Bridgestone 7 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	9,989.70	5,411.07	4,578.63	45.83
Miscellaneous Items	0.00	0.00	0.00	
Labour	5,250.00	2,210.00	3,040.00	57.90
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	15,239.70	7,621.07	7,618.63	49.99
Approved Total (Overridden) (S\$)		6,100.00		
(S\$)	15,239.70	6,100.00	9,139.70	59.97
+ GST 7.00/7.00% (S\$)	1,066.78	427.00	639.78	59.97
Nett Amount (S\$)	16,306.48	6,527.00	9,779.48	59.97
+ Car Rental (8.0 x S\$80.00/day + 7.00% GST) (S\$)		684.80		
(S\$)		7,211.80		
Liabe Amount (60.00%) (S\$)		4,327.08		
+ Doc/Search Fee (S\$)		36.45		
Nett Liability (S\$)		4,363.53		
Global Sum Settlement (S\$)		4,200.00		

INSPECTION

Date of Assignment:	06/04/2020	
Date Inspected:	08/04/2020	Inspected At: 160 SIN MING DRIVE #01-14
Estimated Period of Repair:	7.0 days	Repairer: Team Autopro Pte Ltd - Sin Ming (HQ)

12/16/21, 1:37 PM

Adjuster Report

Adjuster: Lim Teow Guan

Manager: CHEW HSIAO TONG

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FRONT DOOR LH	Dented	1,270.00 FL	*1,270.00 FL
2	1		*FRONT DOOR INNER LOCK	Not Damaged	325.80 FL	*- FL
3	1		*FRONT DOOR INNER TRIM BOARD	Not Damaged	472.30 FL	*- FL
4	1		*FRONT DOOR OUTER HANDLE	Not Damaged	125.00 FL	*- FL
5	1		*FRONT DOOR WEATHERSTRIP	Not Damaged	195.80 FL	*- FL
6	1		*FRONT DOOR LOWER HINGE	Bent	120.00 FL	*120.00 FL
7	1		*FRONT DOOR CHECKER	Not Damaged	115.60 FL	*- FL
8	1		*FRONT DOOR PILLAR	Dented	958.60 FL	*877.00 FL
9	1		*FRONT BUMPER	Broken	785.60 FL	*651.10 FL
10	1		*FRONT BUMPER SIDE RETAINER	Broken	151.00 FL	*151.00 FL
11	1		*FRONT BUMPER FOG LAMP GARNISH	Broken	110.40 FL	*110.40 FL
12	1		*HEADLAMP LH	Cut	954.80 FL	*850.00 FL
13	1		*FRONT DOOR SIDE PILLAR	No such part	420.00 FL	*- FL
14	1		*FRONT STEP PANEL	Dented	189.00 FL	*189.00 FL
15	1		*FRONT STEP PANEL GARNISH	Broken	133.40 FL	*133.40 FL
16	1		*FUEL COVER	Not Damaged	89.20 FL	*- FL
17	1		*SLIDING DOOR	Cut	1,885.00 FL	*1,268.10 FL
18	1		*SLIDING DOOR WEATHERS STRIP	Not Damaged	156.80 FL	*- FL
19	1		*SLIDING DOOR INNER LOCK	Not Damaged	125.80 FL	*- FL
20	1		*SLIDING DOOR LOWER ROLLER	Not Damaged	175.60 FL	*- FL
21	1		*SLIDING DOOR INNER TRIM BOARD	Not Damaged	362.00 FL	*- FL
22	1		*FRONT KNUCKLE ARM	Dented	451.20 FL	*451.20 FL
23	1		*FRONT KNUCKLE ARM BEARING	Jammed	264.70 FL	*264.70 FL
24	1		*FRONT LOWER ARM	Bent	372.20 FL	*372.20 FL
25	1		*FRONT UPPER ARM	Not Damaged	296.80 FL	*- FL
26	1		*FRONT SHOCK ABSORBER	Not Damaged	213.00 FL	*- FL
27	1		*SUNDRIES	Not Necessary	80.00 FS	*- FS
28	1		*FRONT BUMPER CLIPS	Necessary	50.00 FS	*30.00 FS
29	1		*FRONT DOOR SEALANT	Necessary	100.00 FS	*30.00 FS
30	1		*FRONT DOOR INNER TRIM BOARD CLIPS	Necessary	50.00 FS	*30.00 FS
31	1		*FRONT DOOR PILLAR SEALANT	Not Necessary	80.00 FS	*- FS
32	1		*FRONT DOOR SIDE PILLAR SEALANT	Not Necessary	80.00 FS	*- FS
33	1		*ALLOY RIM (LOCAL REPAIR)	Scratched	750.00 FS	*200.00 FS
34	1		*TYRE	Not Damaged	380.00 FS	*- FS
35	1		*FRONT STEP PANEL SEALANT	Not Necessary	80.00 FS	*- FS
36	1		*FRONT STEP PANEL GARNISH CLIPS	Necessary	50.00 FS	*30.00 FS
37	1		*COMPANY STICKER	Necessary	80.00 FS	*30.00 FS
38	1		*SLIDING DOOR SEALANT	Not Necessary	120.00 FS	*- FS
39	1		*SLIDING DOOR INNER TRIM BOARD CLIPS	Necessary	50.00 FS	*30.00 FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (\$\$)	12,669.60	7,088.10
- List Item Discount on L Items 25.00/25.00% (\$\$)	2,679.90	1,677.03
Total Parts (\$\$)	9,989.70	5,411.07

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	PANEL BEAT	New	1,800.00	1,000.00
2	R&R SLIDING DOOR COMPONENT	New	300.00	80.00
3	TO R&R UNDERCARRIAGE PARTS	New	250.00	150.00
4	R&R FUEL TANK TO FACILITATE REPAIR WORKS	New	400.00	0.00
5	R&R SIDE PANEL INNER BOARD	New	200.00	0.00
6	R&R TYRE AND RIM (FRONT) TO PERFORM TYRE BALANCING	New	180.00	60.00
7	WHEEL ALIGNMENT	New	120.00	60.00
8	SPRAY PAINTING	New	1,800.00	800.00
9	RUST PROOFING	New	200.00	60.00
Gross Labour Cost (\$)			5,250.00	2,210.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >