

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

China Taiping Insurance (Singapore) Pte. Ltd.
3 Anson Road, #16-00 Springleaf Tower
Singapore 079909

Our File No: CS/CTI20004952/R1CF3E2

Date: 14/05/2021

REFERENCE

Insured/Claimant: DOUBLE-TRANS PTE LTD Policy No: DMCVSNA00005742000

Date of Loss: 21/03/2020

Nature of Claim: OD

Claim No: SNM20D201452/C02/TANKL

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: **XE5495L**

Make & Model: HINO FS1EKND, 12.9 D 28 TON 6X4 MT (M)

Engine No: E13CAT10536

Reg. Date: 23/01/2020 (Man. Year: 2019)

Chassis No: JHDFS1EKNXXX10048

Colour: White

Odometer: 0 km

Engine Capacity: 12913 cc

Market Value/New Car Price: S\$145,000.00

Sum Insured (S\$): **Market Value/New Car Price**

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes

Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 295/80 R22.5

Rear Tyre Size: 295/80 R22.5 (D)

Front Left Side: Bridgestone 8 mm

Rear Left Side: Bridgestone 8/8 mm

Front Right Side: Bridgestone 8 mm

Rear Right Side: Bridgestone 8/8 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	80,510.10	48,346.00	32,164.10	39.95
Miscellaneous Items	0.00	0.00	0.00	
Labour	27,455.20	24,275.20	3,180.00	11.58
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	107,965.30	72,621.20	35,344.10	32.74
- Excess (S\$)	1,500.00	1,500.00	0.00	0.00
(S\$)	106,465.30	71,121.20	35,344.10	33.20
+ GST 7.00/7.00% (S\$)	7,452.57	4,978.48	2,474.09	33.20
Nett Amount (S\$)	113,917.87	76,099.68	37,818.19	33.20

INSPECTION

Date of Assignment: 04/04/2020

Date Inspected: 06/04/2020 Inspected At:

Borneo Motors (S) Pte Ltd (Pandan)

2 Pandan Crescent

Singapore 128462

Estimated Period of Repair: 14.0 days

Adjuster: MOHD RASUL

Manager: CELINE FONG

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference

Part Source:	(Last Synchronised: 14 May 2021)	
Parts:	N/A	HINO FS1EKND 12.9 D 28 TON 6X4 MT (M) (Model not available in database)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for XE5495L)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*SUNDRIES	Necessary	100.00 FS	*50.00 FS
2	1		*VALVE ASSY, AIR BRAKE	Serviceable	1,186.10 FS	*- FS
3	1		*CONNECTOR SUB-ASSY	Serviceable	37.30 FS	*- FS
4	1		*CONNECTOR SUB-ASSY	Serviceable	40.50 FS	*- FS
5	1		*HEADLAMP ASSY	Cracked	750.30 FS	*750.30 FS
6	1		*HEADLAMP ASSY, LH	Serviceable	750.30 FS	*- FS
7	1		*HOUSING, INSTR CLUSTE	Cracked	1,193.60 FS	*1,193.60 FS
8	1		*PANEL, INSTR CLUSTER	Serviceable	515.00 FS	*- FS
9	1		*PANEL, INSTRUMENT CL	Serviceable	355.40 FS	*- FS
10	1		*PANEL, INSTR CLUSTER	Serviceable	320.00 FS	*- FS
11	1		*PANEL, INSTR CLUSTER	Serviceable	207.80 FS	*- FS
12	1		*METER ASSY, COMBINATION	Serviceable	2,224.60 FS	*- FS
13	1		*LINK SUB-ASSY, FR WI	Bent	157.90 FS	*157.90 FS
14	1		*LINK SUB-ASSY, FR WI	Serviceable	205.80 FS	*- FS
15	1		*ARM & BLADE ASSY, FR	Broken	399.20 FS	*399.20 FS
16	1		*MOTOR & BRACKET ASSY	Serviceable	664.90 FS	*- FS
17	1		*GEAR ASSY, POWER STE	Serviceable	8,347.90 FS	*- FS
18	1		*TANK ASSY, RESERVE	Bent	429.10 FS	*429.10 FS
19	1		*POLE SUB-ASSY, ANTEN	Serviceable	44.50 FS	*- FS
20	1		*LAMP ASSY, DOME	Serviceable	49.80 FS	*- FS
21	1		*ANTENNA	Serviceable	79.70 FS	*- FS
22	1		*FEEDER SUB ASSY, ANTE	Serviceable	45.00 FS	*- FS
23	1		*LAMP ASSY, STEP	Serviceable	29.30 FS	*- FS
24	1		*LAMP ASSY, FR TURN S	Broken	156.40 FS	*156.40 FS
25	1		*INLET SUB-ASSY, WASH	Serviceable	101.90 FS	*- FS
26	1		*COVER, OUTER MIRROR,	Serviceable	18.50 FS	*- FS
27	1		*COVER, OUTER MIRROR,	Serviceable	18.50 FS	*- FS
28	1		*MOTER ASSY, POWER ST	Serviceable	755.30 FS	*- FS
29	1		*LAMP ASSY, SIDE TURN	Serviceable	93.20 FS	*- FS
30	1		*SWITCH, COURTESY	Serviceable	23.80 FS	*- FS
31	1		*BRACKET, HAND RAIL	Serviceable	17.80 FS	*- FS
32	1		*COVER, HAND RAIL BAR	Serviceable	10.80 FS	*- FS
33	1		*GRIP SUB ASSY, INSIDE	Distorted	258.80 FS	*258.80 FS
34	1		*GRIP ASSY, ASSIST, RR RH	Serviceable	60.00 FS	*- FS
35	1		*COVER, HAND GRIP, NO	Serviceable	5.50 FS	*- FS
36	1		*COVER, HAND GRIP, NO	Serviceable	23.30 FS	*- FS
37	1		*GRIP SUB-ASSY, ASSIS	Serviceable	156.40 FS	*- FS
38	1		*GRIP SUB-ASSY, INSTR	Serviceable	139.20 FS	*- FS
39	1		*WEATHERSTRIP, FR DOO	Necessary	292.30 FS	*292.30 FS
40	1		*WEATHERSTRIP, FR DOO	Not Necessary	292.30 FS	*- FS
41	1		*GARNISH ASSY, FR PILLAR, RH	Serviceable	98.20 FS	*- FS
42	1		*BOARD, QUARTER TRIM,	Serviceable	236.80 FS	*- FS
43	1		*RETAINER	Necessary	32.00 FS	*32.00 FS
44	1		*COVER, SHOULDER BELT	Not Necessary	17.80 FS	*- FS
45	1		*COVER, SHOULDER BELT	Not Necessary	17.80 FS	*- FS
46	1		*MOULDING	Necessary	457.10 FS	*457.10 FS

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
47	1		*WINDSHIELD	Broken	2,356.40 FS	*2,356.40 FS
48	2		*SIKA 182010 SIKA TACK GO! (BLA	Necessary	216.00 FS	*216.00 FS
49	2		*SIKA 207. G+P ADHESIVE PRIMER	Necessary	400.00 FS	*400.00 FS
50	1		*BRACKET, OUTER MIRRO	Necessary	43.00 FS	*43.00 FS
51	1		*COVER, OUTER MIRROR,	Cracked	12.80 FS	*12.80 FS
52	1		*BRACKET, OUTER MIRRO	Necessary	30.30 FS	*30.30 FS
53	1		*STAY SUB-ASSY, OUT R	Bent	333.70 FS	*333.70 FS
54	1		*BRACKET, OUTER MIRRO	Necessary	45.50 FS	*45.50 FS
55	1		*STAY SUB-ASSY, OUT R	Bent	96.70 FS	*96.70 FS
56	1		*MIRROR ASSY, OUTER R	Broken	135.70 FS	*135.70 FS
57	1		*ORNAMENT, RADIATOR G	Necessary	276.30 FS	*276.30 FS
58	1		*ORNAMENT, HOOD, LWR	Necessary	185.10 FS	*185.10 FS
59	2		*ORNAMENT, FR DOOR, R	Necessary	479.60 FS	*479.60 FS
60	2		*ORNAMENT, FR FENDER	Necessary	227.40 FS	*227.40 FS
61	1		*EXTENSION, FR FENDER	Serviceable	648.00 FS	*- FS
62	1		*PANEL, FR CORNER, LWR	Serviceable	14.50 FS	*- FS
63	1		*REINFORCE SUB-ASSY	Bent	261.80 FS	*261.80 FS
64	1		*PANEL, COWL TOP, OUT	Bent	677.60 FS	*677.60 FS
65	1		*EXTENSION, FR FENDER	Cracked	630.40 FS	*630.40 FS
66	1		*RETAINER	Necessary	1.40 FS	*1.40 FS
67	1		*REINFORCE SUB-ASSY	Serviceable	261.80 FS	*- FS
68	1		*LEVER SUB-ASSY, HOOD	Serviceable	33.00 FS	*- FS
69	1		*CABLE, CONTROL	Not Working	103.40 FS	*103.40 FS
70	2		*STRIKER ASSY, HOOD P	Serviceable	34.60 FS	*- FS
71	2		*LOCK ASSY, LID	Serviceable	181.40 FS	*- FS
72	2		*HANDLE, LID LOCK	Serviceable	48.00 FS	*- FS
73	1		*LEVER ASSY, AUXILIAR	Serviceable	70.20 FS	*- FS
74	1		*STAY ASSY, DUMPER	Serviceable	151.60 FS	*- FS
75	1		*MEMBER, HOOD	Serviceable	50.50 FS	*- FS
76	1		*WEATHERSTRIP, FR CORN	Not Necessary	82.70 FS	*- FS
77	1		*SEAL, FR PANEL, LWR RH	Cracked	103.40 FS	*103.40 FS
78	1		*CAP	Missing	9.80 FS	*9.80 FS
79	1		*GRIP ASSY, FR PANEL,	Cut	298.00 FS	*298.00 FS
80	1		*EMBLEM	Necessary	211.60 FS	*211.60 FS
81	1		*GRILLE, RADIATOR	Cracked	2,121.70 FS	*2,121.70 FS
82	20		*RETAINER	Necessary	22.00 FS	*22.00 FS
83	1		*REINFORCEMENT SUB AS	Serviceable	107.40 FS	*- FS
84	5		*SCREW, W/WASHER	Necessary	9.00 FS	*9.00 FS
85	1		*WEATHERSTRIP, FR CORN	Serviceable	226.60 FS	*- FS
86	1		*WEATHERSTRIP, FR CRNE	Serviceable	54.20 FS	*- FS
87	1		*SEAL, FR PANEL, LWR	Necessary	99.90 FS	*99.90 FS
88	1		*RETAINER	Necessary	2.80 FS	*2.80 FS
89	1		*HOSE, DEF	Serviceable	45.30 FS	*- FS
90	1		*NOZZLE ASSY, DEFROST	Cut	267.30 FS	*267.30 FS
91	1		*HOSE, DEF	Serviceable	45.30 FS	*- FS
92	1		*GUSSET SUB ASSY, INST	Serviceable	54.20 FS	*- FS
93	1		*BRACKET, INSTR PANEL	Serviceable	14.50 FS	*- FS
94	1		*GUSSET SUB ASSY, INST	Serviceable	41.30 FS	*- FS
95	1		*COVER, SPEAKER HOLE,	Serviceable	54.20 FS	*- FS
96	1		*COVER, SPEAKER	Serviceable	50.50 FS	*- FS
97	1		*DUCT, HEATER TO FOOT	Cracked	48.50 FS	*48.50 FS
98	1		*DUCT, HEATER TO FOOT	Serviceable	54.30 FS	*- FS
99	1		*DUCT, HEATER TO REGI	Cracked	253.30 FS	*253.30 FS
100	1		*DUCT, HEATER TO REGI	Serviceable	99.70 FS	*- FS
101	1		*BRACE SUB-ASSY, PEDAL SUPPORT TO C	Bent	532.30 FS	*532.30 FS
102	1		*PANEL SUB ASSY, INSTR	Bent	1,240.80 FS	*1,240.80 FS
103	4		*CLIP	Necessary	8.80 FS	*8.80 FS
104	1		*CLIP	Necessary	4.80 FS	*4.80 FS
105	4		*RETAINER	Necessary	35.20 FS	*35.20 FS
106	1		*COVER, FR DOOR SERVI	Serviceable	7.80 FS	*- FS

Report was unsubmitted during this print-out.

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
107	1		*REGULATOR ASSY, DOOR	Bent	821.20 FS	*821.20 FS
108	1		*STRIKER ASSY, DOOR	Necessary	29.50 FS	*29.50 FS
109	1		*LOCK ASSY, FR DOOR	Bent	228.10 FS	*228.10 FS
110	1		*LINK, DOOR LOCK	Serviceable	14.80 FS	*- FS
111	1		*HANDLE ASSY, FR DOOR	Serviceable	115.40 FS	*- FS
112	1		*BRACKET, INSIDE HAND	Serviceable	17.30 FS	*- FS
113	1		*HANDLE SUB-ASSY, FR	Serviceable	55.00 FS	*- FS
114	5		*RETAINER	Serviceable	20.00 FS	*- FS
115	1		*LINK ASSY, DOOR CHECK	Bent	93.50 FS	*93.50 FS
116	1		*RETAINER	Necessary	4.00 FS	*4.00 FS
117	1		*GRIP ASSY, DOOR ASSI	Bent	118.90 FS	*118.90 FS
118	1		*ARMREST ASSY, DOOR	Serviceable	47.50 FS	*- FS
119	1		*PANEL SUB-ASSY, FR D	Deformed	643.70 FS	*643.70 FS
120	1		*ESCUTCHEAN, DOOR ASS	Necessary	8.80 FS	*8.80 FS
121	1		*PANEL, FR DOOR ARMRE	Serviceable	125.40 FS	*- FS
122	1		*SWITCH ASSY, POWER W	Serviceable	177.90 FS	*- FS
123	1		*PANEL SUB-ASSY, FR A	Bent	75.20 FS	*75.20 FS
124	1		*DOOR SUB-ASSY, FR AS	Serviceable	111.20 FS	*- FS
125	1		*PANEL SUB-ASSY, FR D	Serviceable	643.70 FS	*- FS
126	1		*WEATHERSTRIP, DOOR G	Necessary	152.90 FS	*152.90 FS
127	1		*GLASS ASSY, DOOR WIND	Broken	495.80 FS	*495.80 FS
128	1		*FRAME SUB-ASSY, FR D	Serviceable	46.80 FS	*- FS
129	1		*WEATHERSTRIP, FR DOOR, NO.4 RH	Necessary	81.00 FS	*81.00 FS
130	1		*OSCILLATOR-PROOF SUB	Serviceable	77.80 FS	*- FS
131	1		*SEAL, RR DOOR DIVISI	Not Necessary	27.30 FS	*- FS
132	1		*WEATHERSTRIP, FR DOO	Necessary	217.60 FS	*217.60 FS
133	1		*GARNISH SUB-ASSY, DO	Serviceable	250.00 FS	*- FS
134	1		*BRACKET, FR DOOR OUT	Serviceable	149.90 FS	*- FS
135	1		*PANEL, FR FENDER SID	Deformed	521.00 FS	*521.00 FS
136	1		*BRACKET SUB ASSY, FR	Bent	142.90 FS	*142.90 FS
137	1		*SUPPORT SUB-ASSY, ST	Bent	339.20 FS	*339.20 FS
138	1		*BRACKET, AIR DUCT CL	Serviceable	116.40 FS	*- FS
139	1		*BRACKET SUB ASSY, FR	Serviceable	57.70 FS	*- FS
140	1		*MUDGUARD, SIDE, RH	Scratched	240.10 FS	*240.10 FS
141	10		*RETAINER	Necessary	17.00 FS	*1.70 FS
142	1		*MUDGUARD, FR FENDER,	Serviceable	81.20 FS	*- FS
143	1		*SPLASHBOARD, SIDE	Serviceable	141.70 FS	*- FS
144	1		*PLATE, FR APRON TO C	Serviceable	139.40 FS	*- FS
145	1		*SPLASHBOARD SUB ASSY	Serviceable	213.60 FS	*- FS
146	1		*PLATE, STEP, LH	Serviceable	257.80 FS	*- FS
147	1		*BRACKET, TILT CAB ST	Serviceable	285.00 FS	*- FS
148	1		*COVER, STEP LWR, RH	Serviceable	135.40 FS	*- FS
149	1		*REINFORCEMENT SUB-AS	Bent	355.40 FS	*355.40 FS
150	1		*SUPPORT SUB-ASSY, FR	Bent	322.00 FS	*322.00 FS
151	1		*STAY, FR CORNER PANEL	Necessary	19.00 FS	*19.00 FS
152	1		*COVER, STEP PLATE, R	Cracked	332.00 FS	*332.00 FS
153	3		*RETAINER	Necessary	6.30 FS	*6.30 FS
154	4		*RETAINER	Necessary	13.20 FS	*13.20 FS
155	1		*COVER, FR STEP, RH	Scratched	410.60 FS	*410.60 FS
156	1		*RETAINER	Necessary	3.30 FS	*3.30 FS
157	1		*PLATE, DOOR SCUFF, R	Cracked	52.50 FS	*52.50 FS
158	1		*EXTENSION, ROCKER, O	Bent	260.50 FS	*260.50 FS
159	1		*REINFORCEMENT, FR BODY PILLAR, UPR	Bent	80.50 FS	*80.50 FS
160	1		*REINFORCEMENT SUB-ASSY, FR PLR, LWR	Bent	239.30 FS	*239.30 FS
161	1		*PILLAR, FR BODY, UPR	Bent	603.40 FS	*603.40 FS
162	1		*PANEL, QUARTER, RH	Bent	1,046.30 FS	*1,006.40 FS
163	1		*PANEL, SIDE GATE	Bent	107.40 FS	*107.40 FS
164	1		*PILLAR SUB-ASSY, FR, RH	Bent	260.50 FS	*260.50 FS
165	1		*PANEL SUB-ASSY, FR DOOR, RH	Buckled	2,875.20 FS	*2,875.20 FS
166	1		*HINGE ASSY, DOOR	Bent	189.90 FS	*189.90 FS

Report was unsubmitted during this print-out.

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
167	1		*HINGE ASSY, DOOR	Bent	189.90 FS	*189.90 FS
168	1		*PANEL SUB-ASSY, COWL	Serviceable	1,130.70 FS	*- FS
169	1		*CUSHION, BODY MOUNTI	Serviceable	8.80 FS	*- FS
170	1		*GUSSET, FR BODY PILL	Serviceable	57.50 FS	*- FS
171	1		*BRACKET, INSTRUMENT	Serviceable	8.80 FS	*- FS
172	1		*BRACKET, ASSIST GRIP	Serviceable	31.50 FS	*- FS
173	1		*PILLAR, FR BODY, LWR INNER RH	Bent	316.20 FS	*316.20 FS
174	1		*PANEL SUB-ASSY, DASH	Serviceable	1,970.30 FS	*- FS
175	1		*COWL	Bent	2,385.90 FS	*2,385.90 FS
176	1		*GUSSET, FR BODY PILL	Serviceable	57.50 FS	*- FS
177	1		*BRACKET, INSTRUMENT	Serviceable	8.80 FS	*- FS
178	1		*PILLAR, FR BODY, LWR	Serviceable	316.20 FS	*- FS
179	1		*APRON, STEP, RH	Serviceable	146.20 FS	*- FS
180	1		*MUDGUARD, STEP	Serviceable	47.50 FS	*- FS
181	1		*HOLDER MUDGUARD	Serviceable	33.00 FS	*- FS
182	1		*SUPPORT SUB-ASSY, ST	Serviceable	721.30 FS	*- FS
183	1		*STAY SUB-ASSY, STEP	Serviceable	155.40 FS	*- FS
184	1		*STAY SUB-ASSY, STEP	Serviceable	155.40 FS	*- FS
185	1		*SUPPORT SUB-ASSY, ST	Serviceable	711.60 FS	*- FS
186	1		*LID SUB-ASSY, STEPOP	Serviceable	71.00 FS	*- FS
187	1		*COVER, STEP, RH	Serviceable	384.70 FS	*- FS
188	1		*BRACKET, TILT CAB ST	Serviceable	285.00 FS	*- FS
189	1		*STAY SUB ASSY, STEP	Serviceable	94.70 FS	*- FS
190	1		*GRILLE SUB-ASSY, RAD	Missing	1,023.10 FS	*1,023.10 FS
191	1		*REINFORCE, FR BUMPER	Serviceable	267.00 FS	*- FS
192	1		*BRACKET, GRILLE	Serviceable	29.50 FS	*- FS
193	1		*MEMBER, ENGINE COVER	Serviceable	895.90 FS	*- FS
194	1		*STAY SUB-ASSY, FR UN	Serviceable	282.30 FS	*- FS
195	1		*MOULDING, FR BUMPER	Missing	17.00 FS	*17.00 FS
196	1		*MOULDING, FR BUMPER	Serviceable	17.00 FS	*- FS
197	1		*GARNISH, BUMPER, RH	Serviceable	172.60 FS	*- FS
198	1		*GARNISH, BUMPER, LH	Serviceable	154.90 FS	*- FS
199	1		*GARNISH, BUMPER, LH	Serviceable	172.10 FS	*- FS
200	1		*BRACKET SUB-ASSY, HE	Serviceable	202.60 FS	*- FS
201	1		*STAY, HEADLAMP, NO.2	Not Necessary	49.30 FS	*- FS
202	1		*STAY, HEADLAMP, NO.2	Not Necessary	49.30 FS	*- FS
203	1		*BRACKET SUB-ASSY, HE	Serviceable	202.60 FS	*- FS
204	1		*BUMPER SUB-ASSY, FR	Bent	2,265.00 FS	*2,265.00 FS
205	1		*EXTENSION SUB-ASSY, FR BUMPER, RH	Bent	237.10 FS	*237.10 FS
206	1		*EXTENSION SUB-ASSY, FR BUMPER, LH	Serviceable	237.10 FS	*- FS
207	1		*REINFORCEMENT ASSY	Bent	849.00 FS	*849.00 FS
208	1		*SWITCH ASSY, PRESS	Not Working	70.50 FS	*70.50 FS
209	1		*COVER, STEERING COLUMN, UPR	Deformed	36.50 FS	*36.50 FS
210	1		*COVER, STEERING COLUMN, LWR	Deformed	57.70 FS	*57.70 FS
211	1		*BOOTS, STRG COLUMN LW	Necessary	20.00 FS	*20.00 FS
212	1		*TUBE, STEERING COLUM	Necessary	80.00 FS	*80.00 FS
213	1		*CLEANER ASSY, AIR	Deformed	1,436.60 FS	*1,436.60 FS
214	1		*UNITASSY, AIR CONDIT	Cracked	2,126.20 FS	*2,126.20 FS
215	1		*BLOWER ASSY	Cracked	838.50 FS	*838.50 FS
216	1		*PAD, PEDAL	Cut	14.30 FS	*14.30 FS
217	1		*SENSOR	Not Working	249.30 FS	*249.30 FS
218	2		*BOLT, CAB MOUNTING	Necessary	131.40 FS	*131.40 FS
219	2		*NUT	Necessary	19.00 FS	*19.00 FS
220	1		*DUCT, HEATER TO FOOT	Cracked	154.30 FS	*154.30 FS
221	1		*BRACKET, FR SEAT MOU	Bent	1,529.10 FS	*1,529.10 FS
222	1		*PAD, HEEL	Cut	88.30 FS	*88.30 FS
223	1		*BRACKET, PIPE. JOINT	Bent	77.50 FS	*77.50 FS
224	1		*BRACKET SUB-ASSY, TU	Bent	169.20 FS	*169.20 FS
225	1		*BRACKET SUB-ASSY, TI	Bent	525.50 FS	*525.50 FS
226	1		*LEVER SUB-ASSY, TILT	Bent	3,423.40 FS	*3,423.40 FS

Report was unsubmitted during this print-out.

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
227	1		*COVER SUB-ASSY, SIDE	Deformed	1,101.90 FS	*1,101.90 FS
228	1		*BRACKET SUB-ASSY, ST	Bent	944.40 FS	*944.40 FS
229	1		*ABSORBER ASSY, CAB R	Bent	262.80 FS	*262.80 FS
230	1		*SPRING ASSY, CAB FR	Necessary	394.90 FS	*394.90 FS
F=Franchise part. S=SpcNett.						
					Total Parts (\$\$)	80,510.10 48,346.00

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	SUPPLY JOINT PANEL SEALANT	New	400.00	300.00
2	REPLACE AND REFOCUS HEADLAMP	New	149.60	149.60
3	REMOVE INTERIOR UPHOLSTERY TO FAC REPAIR	New	880.00	880.00
4	R/I DASHBOARD ASSY TO FAC REPAIR	New	1,760.00	1,760.00
5	REPLACE FRONT WINDSCREEN GLASS	New	880.00	880.00
6	CHECK WIRING AND CONDUCT WATER TEST	New	149.60	149.60
7	R/I AC CON BLOWER ASSY TO FAC REPAIR & REGAS	New	880.00	880.00
8	R/I WIRE HANESS ASSY TO FAC REPAIR	New	880.00	880.00
9	R/I BRAKE BOOSTER SYSTEM TO FAC REPAIR	New	880.00	880.00
10	REMOVE AND TRANSFER DOOR COMPONENT ONTO NEW DOOR	New	880.00	880.00
11	REPLACE STEERING GEAR ASSY	New	1,760.00	1,760.00
12	R/I ROOF LINING TO FAC REPAIR	New	1,760.00	1,760.00
13	REPLACE ACC DAMAGED PARTS AND STRAIGHTEN / REALIGN. ACC AFFECTED AREAS	New	6,160.00	4,400.00
14	RESPRAY ACC AFFECTED AREAS	New	4,620.00	3,300.00
15	TO RESET ECU AND REPROGRAMME	New	180.00	180.00
16	SUPPLY IU BRACKET	New	26.00	26.00
17	TOWING CHARGES	New	150.00	150.00
18	REMOVE INTERIOR SHATTEDED GLASS	New	220.00	220.00
19	TO REPLACE FLOOR PANEL, RH REAR QUARTER PANEL	New	3,520.00	3,520.00
20	TO RESPRAY FLOOR PANEL AND RH REAR QUARTER PANEL	New	1,320.00	1,320.00
Gross Labour Cost (\$\$)			27,455.20	24,275.20

Report was unsubmitted during this print-out.

< END OF ESTIMATES >