

## LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park  
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

### VEHICLE DAMAGE INSPECTION REPORT

**Our File No:** CS/AIG20004954/ESF3E2

**Date:** 21/04/2020

#### REFERENCE

Handling Insurer: AIG Asia Pacific Insurance Pte. Ltd.	Policy No:	2100506055
Claimant Vehicle No : SJE9933D	Insured Vehicle No :	SLM5348D
Date of Loss: 28/03/2020	Nature of Claim:	TP Claim No: 5954594663SG

#### DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SJE9933D	Engine No:	27186030454302
Make & Model:	MERCEDES-BENZ E250, 1.8 (A)	Chassis No:	WDD2120472A604544
Reg. Date:	24/08/2012 (Man. Year: 2012)	Odometer:	96717 km
Colour:	Grey		
Engine Capacity:	1796 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	<b>Market Value/New Car Price</b>		

#### CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

#### CONDITION OF TYRES

Front Tyre Size:	265/35Z R18	Rear Tyre Size:	265/35Z R18
Front Left Side:	Michelin 6 mm	Rear Left Side:	Michelin 6 mm
Front Right Side:	Michelin 6 mm	Rear Right Side:	Michelin 6 mm

*The above values represent the remaining tyre treads depth*

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	12,880.80	6,762.24	6,118.56	47.50
Miscellaneous Items	0.00	0.00	0.00	
Labour	2,200.00	1,390.00	810.00	36.82
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
<b>Calculated Gross Total (S\$)</b>	<b>15,080.80</b>	<b>8,152.24</b>	<b>6,928.56</b>	<b>45.94</b>
<b>Approved Total (Overridden) (S\$)</b>		<b>5,500.00</b>		
<b>Nett Amount (S\$)</b>	<b>15,080.80</b>	<b>5,500.00</b>	<b>9,580.80</b>	<b>63.53</b>

#### INSPECTION

Date of Assignment:	03/04/2020	
Date Inspected:	07/04/2020 Inspected At:	Car Pro Auto (HQ) Blk 6 Yew Tee Industrial Estate 399-J, Woodlands Road Singapore 678008
Estimated Period of Repair:	5.0 days	

**Adjuster:** CHEN TSUE YEE

**Manager:** Hiew May Fung

*NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.*

MARKET VALUE: \$59,000.00(EST)-LTA REIMBURSEMENT VALUE: \$53,766.00=NETT VALUE: \$5,234.00

## REPAIR DETAILS

### Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FRONT BUMPER	Crushed	1,510.00 FL	*1,510.00 FL
2	1		*FRONT BUMPER LOWER GRILLE	Broken	110.00 FL	*110.00 FL
3	1		*FRONT BUMPER FOG LAMP	Cut	540.00 FL	*540.00 FL
4	1		*FRONT BUMPER FOG LAMP COVER	Broken	85.00 FL	*85.00 FL
5	1		*FRONT BUMPER FOG LAMP CHROME	Cut	140.00 FL	*140.00 FL
6	1		*FRONT BUMPER RH LOWER CHROME	Necessary	105.00 FL	*105.00 FL
7	2		*FR BUMPER RETAINER	Broken	173.60 FL	*173.60 FL
8	1		*FR BUMPER SUPPORT BRACKET RH	Not Necessary	155.00 FL	*- FL
9	1		*FR BUMPER REINFORCEMENT	Not Necessary	590.00 FL	*- FL
10	1		*FRONT BONNET	Repair	2,510.00 FL	*- FL
11	1		*BONNET INNER LOCK	Not Necessary	135.00 FL	*- FL
12	1		*FRONT GRILLE	Cut	1,220.00 FL	*1,220.00 FL
13	1		*FRONT GRILLE CHROME	Repeated	1,200.00 FL	*- FL
14	2		*FRONT HEADLAMP LH & RH	Cut / Broken	2,260.00 FL	*2,260.00 FL
15	1		*FR BUMPER SPONGE	Not Necessary	163.20 FL	*- FL
16	1		*FRONT SUPPORT PANEL	Not Necessary	1,660.00 FL	*- FL
17	1		*SET FRONT SUPPORT PANEL TOP GARNISH	Broken	150.00 FL	*150.00 FL
18	1		*FRONT RH FENDER	Dented	1,100.00 FL	*1,100.00 FL
19	1		*FRONT GRILLE INNER CENTER GARNISH	Broken	120.00 FL	*120.00 FL
20	1		*SET FRONT FENDER RH INNER SHIELD	Not Necessary	185.00 FL	*- FL
21	1		*HEADLAMP PANEL TOP GARNISH LH	Not Necessary	115.20 FL	*- FL
22	1		*HEADLAMP LOWER SUPPORT BRACKET	Not Necessary	85.00 FL	*- FL

F=Franchise part. L=ListItemDisc.

<b>Sub Total (\$)</b>	<b>14,312.00</b>	<b>7,513.60</b>
<b>- List Item Discount on L Items 10.00/10.00% (\$)</b>	1,431.20	751.36
<b>Total Parts (\$)</b>	<b>12,880.80</b>	<b>6,762.24</b>

Report was unsubmitted during this print-out.

## Recommended Miscellaneous Items

There are no new miscellaneous items selected.

## Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<b>Labour Items</b>				
1	TO PANEL BEAT AND RENEWAL OF ALL NECESSARY DAMAGED BODY PARTS	New	1,000.00	500.00
2	TO CHECK WIRING AND REWIRE	New	80.00	30.00
3	TO ANTI-RUST	New	120.00	30.00
4	TO PUTTY AND SPRAY-PAINT OF AFFECTED AREAS	New	800.00	700.00
5	TO CLEAR / RESET FAULT CODE	New	150.00	100.00
6	TO REALIGN HEADLAMP FOCUS	New	50.00	30.00
			<b>Gross Labour Cost (S\$)</b>	<b>2,200.00</b>
				<b>1,390.00</b>

Report was unsubmitted during this print-out.

< END OF ESTIMATES >