Adjuster Report Page 1 of 4

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CC4/AIG20004961/KGA3Q2

Date: 26/08/2020

REFERENCE

Date of Loss: 01/04/2020 Nature of Claim: TP Claim No: 6975259801SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: SDJ9388Y

Make & Model:

NISSAN QASHQAI, 1.2 DIG-T CVT ABS 2WD
Engine No: HRA2441768A

5DR (A)

Reg. Date: 23/06/2017 (Man. Year: 2017) Chassis No: SJNFEAJ11UZ011206

Colour: Metallic Pearl White Odometer: 54930 km

Engine Capacity: 1197 cc
Market Value/New Car

Price: N/A

Sum Insured (S\$): Market Value/New Car Price

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes

Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 215/60 R17 Rear Tyre Size: 215/60 R17
Front Left Side: Yokohama 9 mm Rear Left Side: Yokohama 9 mm
Front Right Side: Yokohama 9 mm
Rear Right Side: Yokohama 9 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	1,177.00	1,177.00	0.00	0.00
Miscellaneous Items	0.00	0.00	0.00	
Labour	160.00	80.00	80.00	50.00
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	1,337.00	1,257.00	80.00	5.98
Approved Total (Overridden) (S\$)		900.00		
Nett Amount (S\$)	1,337.00	900.00	437.00	32.69
+ Loss of Use (1.0 x S\$	50.00/day) (S\$)	50.00		
+ Doc/S	7.45			
Ne	tt Liability (S\$)	957.45		
Global Sum S	950.00			

INSPECTION

Date of Assignment: 03/04/2020

Date Inspected: 03/04/2020 Inspected At: CARPLUS AUTO PTE LTD (HQ)

160 SIN MING DRIVE #04-06, SIN

MING AUTOCITY Singapore 575722

Estimated Period of Repair: 1.0 days

Adjuster Report Page 2 of 4

Adjuster: KENNETH KONG Manager: Chong Pui Lin

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

Adjuster Report Page 3 of 4

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount		
1	1		*REAR RIGHT SPORT RIM	Dented	1,177.00 FS	*1,177.00 FS		
F=Fra	nchise	part. S=SpcNet	t.	Total Parts (S\$)	1,177.00	1,177.00		
Report was unsubmitted during this print-out.								

Adjuster Report Page 4 of 4

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Lab	our Items			
1	COMPUTER ALIGNMENT	New	80.00	60.00
2	BEING LABOUR TO DISMANTLE & RENEW SPORT RIM	New	80.00	20.00
	Gross Labour Cost (S\$)		160.00	80.00
	Renort was unsubmitted duri	ng this print-out		

< END OF ESTIMATES >