Adjuster Report Page 1 of 4

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

AIG Asia Pacific Insurance Pte. Ltd.

Our File No: CC3/AIG20004965/T1TF3E2

AIG Building, 78 Shenton Way #08-16
Singapore 079120

Date: 14/04/2020

REFERENCE

Insured/Claimant: BHAGWANI GOPAL SANJEEV Policy No: 1900103746

Date of Loss: 31/03/2020 Nature of Claim: OD Claim No: 1688143839SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: SML6937R

Make & Model: AUDI A4, 2.0 MU TFSI (8E) (A) Engine No: CVK077902

Reg. Date: 30/05/2019 (Man. Year: 2019) Chassis No: WAUZZZF47KA047225

Colour: White Odometer: 10736 km

Engine Capacity: 1984 cc Market Value/New Car Price: \$\$125,000.00

Sum Insured (S\$): Market Value/New Car Price

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes

Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 205/60 R18 Rear Tyre Size: 205/60 R18
Front Left Side: Continental 6 mm Rear Left Side: Continental 6 mm
Front Right Side: Continental 6 mm Rear Right Side: Continental 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	0.00	0.00	0.00	
Miscellaneous Items	0.00	0.00	0.00	
Labour	5,802.00	1,242.00	4,560.00	78.59
Paintwork Labour	0.00	0.00	0.00	
Towing Gross Total (S\$)	0.00	0.00	0.00	
	5,802.00	1,242.00	4,560.00	78.59
+ GST 7.00/7.00% (S\$)	406.14	86.94	319.20	78.59
Nett Amount (S\$)	6,208.14	1,328.94	4,879.20	78.59

INSPECTION

Date of Assignment: 06/04/2020

Date Inspected: 03/04/2020 Inspected At: 281 ALEXANDRA ROAD

Repairer : Premium Automobiles Pte Ltd

Estimated Period of Repair: 4.0 days

Adjuster: MOHD TAUFIKH BIN HAMID Manager: DENISE TAY KWEE CHENG

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

Adjuster Report Page 2 of 4

(REPAIR COST NOT CONCLUDE)

Adjuster Report Page 3 of 4

REPAIR DETAILS

Recommended Parts

There are no new parts selected.

Report was unsubmitted during this print-out.

Adjuster Report Page 4 of 4

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Lab	our Items			
1	TO REMOVE AND REINSTALL REAR PARKING AID AND REAR LID KICK SENSOR. CHECK FUNCTION AND RENEW ACCORDING TO DAMAGE	New	360.00	0.00
2	TO DISMANTLE REAR BUMPER. TO REPAIR REAR BUMPER, LHS REAR FENDER AND LHS REAR DOOR. RE-ORGANISE REAR CRASH MANAGEMENT COMPONENTS. REINSTALL ALL PARTS REMOVED	New	2,450.00	500.00
3	TO RESPRAY REAR BUMPER, LHS REAR DOOR AND LHS REAR FENDER	New	2,800.00	550.00
4	TO CARRY OUT DIAGNOSTIC CHECK	New	192.00	192.00
	Gross Labou	ır Cost (S\$)	5,802.00	1,242.00
	Report was unsubmitted during	this print-out.		

< END OF ESTIMATES >