



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 1

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. XE 5490A

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
REPLACEMENT OF PARTS				
1	CORNER PANEL - LH	TO REPAIR SEE LABOUR	580.30	-
1	DOOR ASSY - LH	TO REPAIR SEE LABOUR	4,868.78	-
1	FRONT BUMPER SIDE PROTECTOR - LH	MISSING	385.68	385.68
	LESS 10% DISCOUNT		-583.48	-38.57
			5,251.28	347.11
LABOUR				
	LABOUR TO KNOCK & WELD ON CORNER PANEL, DOOR & RENEW BUMPER SIDE PROTECTOR. INCLUSIVE OF THE REPAIR OF CORNER PANEL - LH AND DOOR ASSY - LH.		850.00	400.00
	TO SPRAY & PAINTING ON ACCIDENT AFFECTED AREA & CORPORATE STICKER.		680.00	680.00
	TO RUST PROOFING ON ACCIDENT AFFECTED AREA.	NOT NECESSARY	380.00	-
			1,910.00	1,080.00
GRAND TOTAL			7,161.28	1,427.11
RECOMMENDED COST OF REPAIRS				1,427.11

Report Ref No. CS/UOI20004972/Utf3e2

CHUA KANG SENG

Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may reply on the Report wholly or in part. Any third party acting or replying on this Report, in whole or in part, does so at his or her own risk.