



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

TAX INVOICE

EQ INSURANCE COMPANY LTD
5 MAXWELL ROAD
#17-00 TOWER BLOCK
MND COMPLEX
SINGAPORE 069110

INV No. AC2006658
INV Date 25/09/2020
Reference CC6/EQI20004978/Aka3q2
Code EQI



PROFESSIONAL SERVICE FEE

Vehicle No. SLN 4026J
Insured Veh. GBB 8123S
Claim No. DM20HO00708/SG
Policy No. DMCPHQ19-002857
Accident Date 30/03/2020
Inspection Date 06/04/2020

Description	Total
Third Party Express Settlement	400.00
Subtotal	400.00
GST (7%)	28.00
Grand Total	428.00

We shall be glad if you could forward the payment at your early convenience.

Cheque should be crossed and made payable to 'LKK Auto Consultants Pte Ltd'

LKK Auto Consultants Pte Ltd




LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
EQ INSURANCE COMPANY LTD		Ref : CC6/EQI20004978/Aka3q2		
5 MAXWELL ROAD #17-00 TOWER BLOCK MND COMPLEXSINGAPORE 069110		Date : 25-09-2020		
		Code : EQI		
1. Policy Particulars :- THIRD PARTY CLAIM				
	Insured Veh.	GBB 8123S	Veh. Inspected	SLN 4026J
	Policy No.	DMCPHQ19-002857	Coverage (\$)	0.00
	Claim No.	DM20HO00708/SG	Excess (\$)	0.00
	Assign From		Assign Date	06/04/2020
2. Vehicle Particulars & Condition				
	Make & Model	TOYOTA WISH	c.c	1798
	Engine No.	HIDDEN	Year of Reg.	2017
	Chassis No.	JTDGG20W50J006722	Colour	GREY
	Odometer	56826	Steering	IN ORDER
	Brakes	IN ORDER	Modification	SPORTS RIM
	General	GOOD		
3. Conditions of Tyres				
		Size	Make	Balance
	R/H Front Tyre	195/65 R15	YOKOHAMA	6 mm
	L/H Front Tyre	195/65 R15	YOKOHAMA	6 mm
	R/H Rear Tyre	195/65 R15	YOKOHAMA	6 mm
	L/H Rear Tyre	195/65 R15	YOKOHAMA	6 mm
4. Description of Damages				
	THE VEHICLE SUSTAINED DAMAGES AT THE FRONT PORTION. DAMAGES SEE DETAILS.			
5. General Information				
	Accident Date	30/03/2020	Inspection Date	06/04/2020
	Survey held at	HUA MENG SPRAY PAINTING WORKSHOP 1 KAKI BUKIT AVE 6 #01-61 AUTOBAY SINGAPORE 417883		
5a. Remarks				
	A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.			
5b. Estimate Days of Repair				
	ESTIMATED NORMAL PERIOD FOR REPAIR:		4 Working Days	



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 2

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SLN 4026J

Qty	Description of Parts	Condition	Estimate By Workshop (\$))	Our Adjusted (\$)
<u>REPLACEMENT OF PARTS</u>				
1	FRONT BUMPER	DEFORMED	530.10	530.10
2	FRONT BUMPER SIDE HOLDER @\$188.60	NOT NECESSARY	377.20	124.00
1	FRONT BUMPER REINFORCEMENT	NOT NECESSARY	318.90	-
1	FRONT BUMPER SPONGE	CRACKED	189.70	189.70
2	FRONT BUMPER BRACKET @\$189.30	NOT NECESSARY	378.60	-
2	FRONT BUMPER LOWER LIP @\$748.00	NOT NECESSARY	1,496.00	-
2	FRONT BUMPER FOD LAMP @\$408.90	NOT NECESSARY	817.80	-
2	FRONT BUMPER FOD LAMP GARNISH @\$304.80	NOT NECESSARY	609.60	-
1	FRONT GRILLE	CUT	408.90	286.00
2	FRONT HEADLAMP @\$1883.60	CUT	3,767.20	2,442.00
2	FRONT HEADLAMP LOWER BRACKET @\$189.70	NOT NECESSARY	379.40	-
1	FRONT BONNET	DENTED	640.10	640.10
2	FRONT BONNET HINGES @\$133.50	NOT NECESSARY	267.00	-
1	FRONT BONNET LOCK	NOT NECESSARY	200.40	-
1	FRONT BONNET LOCK BRACKET	BENT	191.90	191.90
1	FRONT BONNET INNER RUBBER	NOT NECESSARY	208.00	-
1	FRONT BONNET INNER INSULATION	NOT NECESSARY	409.00	-
1	FRONT BONNET CENTRE LOGO	NECESSARY	133.20	58.00
1	FRONT SUPPORT PANEL	NOT NECESSARY	1,069.50	-
1	FRONT SUPPORT TOP COVER	NOT NECESSARY	318.90	-
6	FRONT SUPPORT PANEL COVER CLIPS @\$14.20	NOT NECESSARY	85.20	-
1	AIRCOND CONDENSER	DENTED	1,418.00	1,418.00
	LESS 25% DISCOUNT		-3,553.65	-1,469.95
			10,660.95	4,409.85
<u>SPECIAL NETT ITEMS</u>				
1	FRONT NUMBER PLATE (SN)	BENT	50.00	25.00
1	FRONT NUMBER PLATE HOLDER (SN)	DEFORMED	50.00	30.00
			100.00	55.00
<u>LABOUR</u>				
	REMOVE & REINSTALL AIR CON FILL IN GAS.		150.00	80.00

Report Ref No. CC6/EQI20004978/Aka3q2



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:2 of 2

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	REMOVE,REPLACE & REPAIR CONSISTENT TO THE ACCIDENT .		1,100.00	500.00
	RESPRAY PAINTING.		1,000.00	600.00
	TUFF KOTE.	NOT NECESSARY	100.00	-
			2,350.00	1,180.00
GRAND TOTAL			13,110.95	5,644.85
RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION)				4,500.00

Report Ref No. CC6/EQI20004978/Aka3q2

ADRIAN LING WAI PING

B.Eng,AMSOE,AMIRTE,AMSAE-A,M.MATAI

Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or replying on this Report, in whole or in part, does so at his or her own risk.



LKK Auto Consultants Pte Ltd

S1 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3581 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

PHOTOGRAPHS FOR VEHICLE NO. SLN 4026J

INSPECTION





LKK Auto Consultants Pte Ltd

S1 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3581 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

S1 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3551 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

S1 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3551 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

S1 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3551 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

S1 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3581 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

PHOTOGRAPHS FOR VEHICLE NO. SLN 4026J

RE-INSPECTION





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3581 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd


S1 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3551 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

PHOTOGRAPHS FOR VEHICLE NO. SLN 4026J

RE-INSPECTION





LKK Auto Consultants Pte Ltd

S1 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3551 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

S1 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3551 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

