Adjuster Report Page 1 of 4

#### LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

#### VEHICLE DAMAGE INSPECTION REPORT

Our File No: CC4/AIG20004995/T1PS3Q2

Date: 09/07/2020

**REFERENCE** 

Handling Insurer: AIG Asia Pacific Insurance Pte. Ltd. 2100435702 Policy No: Claimant GBE2560L Insured Vehicle No: SKV2211Z Vehicle No:

Date of Loss: ΤP 05/04/2020 Nature of Claim: Claim No: 9930589499SG

**DESCRIPTION & IDENTIFICATION OF VEHICLE** 

**GBE2560L** Reg No:

NISSAN NV200, 1.5 L ABS AIRBAG 2WD 6DR Make & Model: Engine No:

K9KC400D054730 EURO 5 (M)

Reg. Date: 14/10/2015 (Man. Year: 2015) Chassis No: VSKYBAM20Z0108471 Colour: White Odometer: 139073 km

**Engine Capacity:** 1461 cc Market Value/New Car N/A

Price:

Market Value/New Car Price Sum Insured (S\$):

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes

Handbrake (Serviceable): Yes Engine Modification: Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 175/70 R14 Rear Tyre Size: 175/70 R14 Front Left Side: Dunlop 6 mm Rear Left Side: Dunlop 6 mm Front Right Side: Rear Right Side: Dunlop 6 mm Dunlop 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	7,651.71	6,155.83	1,495.88	19.55
Miscellaneous Items	0.00	0.00	0.00	
Labour	2,890.00	2,000.00	890.00	30.80
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	10,541.71	8,155.83	2,385.88	22.63
Approved Total (Overridden) (S\$)		6,500.00		
(S\$)	10,541.71	6,500.00	4,041.71	38.34
+ GST 7.00/7.00% (S\$)	737.92	455.00	282.92	38.34
Nett Amount (S\$)	11,279.63	6,955.00	4,324.63	38.34
+ Loss of Use (7.0 x S\$8	30.00/day) (S\$)	560.00		
+ Doc/Se	36.45			
Net	t Liability (S\$)	7,551.45		
Global Sum S	7,400.00			

**INSPECTION** 

06/04/2020 Date of Assignment:

07/04/2020 Inspected At: Date Inspected: Em-1 Auto Pte Ltd (sin Ming) (HQ)

160 SIN MING DRIVE, #05-21 SIN

MING AUTOCITY Singapore 575722 Adjuster Report Page 2 of 4

Estimated Period of Repair: 7.0 days

Adjuster: MOHD TAUFIKH BIN HAMID Manager: CHEW HSIAO TONG

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

Adjuster Report Page 3 of 4

# **REPAIR DETAILS**

## **Recommended Parts**

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*TAILGATE LH	Bent	1,404.90 FN	*1,281.60 FN
2	1		*TAILGATE WINDSCREEN INNER SEAL LH	. Necessary	60.00 FN	*60.00 FN
3	1		*TAILGATE BADGE	Necessary	78.20 FN	*78.20 FN
4	1		*TAILGATE EMBLEM NV200	Necessary	125.10 FN	*125.10 FN
5	1		*TAILGATE UPPER LOCK LH	Not Necessary	153.50 FN	*-FN
6	1		*TAILGATE UPPER LOCK CATCH LH	Not Necessary	46.20 FN	*- FN
7	1		*TAILGATE INNER BOTTOM LOCK LH	Bent	153.50 FN	*130.20 FN
8	1		*TAILGATE INNER BOTTOM LOCK CATCH LH	Bent	46.20 FN	*46.20 FN
9	1		*TAILGATE WEATHERSTRIP	Torn	195.20 FN	*195.20 FN
10	1		*TAILGATE OUTER GARNISH LH	Deformed	351.50 FN	*336.10 FN
11	1		*TAILGATE OPENER HANDLE	Deformed	143.60 FN	*143.60 FN
12	2		*TAILGATE HINGE LH	Bent (1 PCS ONLY)	172.00 FN	*86.00 FN
13	1		*TAILGATE CHECKER LH	Bent	72.00 FN	*72.00 FN
14	1		*TAILGATE INNER BOARD	Deformed	283.20 FN	*283.20 FN
15	1		*SET TAILGATE INNER BOARD CLIPS	Necessary	40.00 FN	*20.00 FN
16	1		*TAILGATE RH	Bent	1,159.30 FN	*960.90 FN
17	1		*TAILGATE WINDSCREEN INNER SEAL RH	Necessary	60.00 FN	*60.00 FN
18	1		*TAILGATE EMBLEM DCI	Necessary	69.60 FN	*69.60 FN
19	1		*TAILGATE INNER BOTTOM LOCK RH	Not Necessary	136.20 FN	*-FN
20	1		*TAILGATE INNER BOTTOM LOCK CATCH RH	Not Necessary	58.00 FN	*- FN
21	1		*TAILGATE INNER RUBBER RH	Necessary	139.20 FN	*139.20 FN
22	1		*REAR BUMPER	Deformed	790.00 FN	*652.00 FN
23	1		*REAR BUMPER SIDE RETAINERS	N/S Deformed / O/SNotNecessary	78.00 FN	*39.00 FN
24	1		*SET REAR BUMPER CLIPS	Necessary	50.00 FN	*30.00 FN
25	1		*REAR BUMPER SPONGE	Cracked	119.60 FN	*119.60 FN
26	1		*REAR BUMPER REFLECTOR LH	Not Necessary	67.90 FN	*- FN
27	1		*TAILLAMP LH	Cracked	289.50 FN	*289.50 FN
28	1		*TAILLAMP INNER SEALER	Not Necessary	38.00 FN	*-FN
29	1		*END PANEL	Bent	465.00 FN	*465.00 FN
30	1		*END PANEL TOP TRIM	Deformed	126.50 FN	*126.50 FN
31	1		*SET END PANEL TOP TRIM CLIPS	Necessary	30.00 FN	*20.00 FN
32	2		*TAILGATE GLASS SEALANT	Necessary	120.00 FS	*80.00 FS
33	1		*TAILGATE STICKER 70KM/H	Necessary	15.00 FS	*15.00 FS
34	1		*TAILGATE STICKER 6PAX	Necessary	15.00 FS	*15.00 FS
35	1		*SET REVERSE SENSOR	Not Working	250.00 FS	*200.00 FS
36	1		*SET BOTH TAILGATE COMPANY LOGO	Necessary	500.00 FS	*300.00 FS
37 F=Fra	1 inchise	part. S=S	*SET REVERSE CAMERA SpcNett. N=NettItemDisc.	Distorted	450.00 FS	*300.00 FS
			- Nett Item Discount	Sub Total (S\$) on N Items 10.00/10.00% (S\$)	<b>8,351.90</b> 700.19	<b>6,738.70</b> 582.87
				Total Parts (S\$)	7,651.71	6,155.83
			Report was unsubmitted	d during this print-out.		

Adjuster Report Page 4 of 4

# Recommended Miscellaneous Items

There are no new miscellaneous items selected.

## **Recommended Labour**

No	Particulars	Lab.Type	Repairer's	Amount
Lab	our Items			
1	PANEL BEATING	New	1,000.00	700.00
2	SPRAY PAINTING	New	1,000.00	800.00
3	CHECK WIRING	New	50.00	30.00
4	ANTI RUST	New	120.00	50.00
5	REMOVE AND INSTALL BOTH TAILGATE GLASS	New	240.00	160.00
6	REMOVE AND INSTALL BOTH TAILGATE PARTS	New	180.00	140.00
7	REMOVE AND INSTALL CARPET AND INTERIOR	New	120.00	60.00
8	REMOVE AND INSTALL REVERSE SENSOR	New	90.00	30.00
9	REMOVE AND INSTALL REVERSE CAMERA	New	90.00	30.00
	Gross Labour Cost		2,890.00	2,000.00

< END OF ESTIMATES >

Report was unsubmitted during this print-out.